

OWNER: RJ AIRCRAFT LEASING
ADDRESS: 4802 AMBER VALLEY PKWY S
FARGO ND 58104-8919
PHONE:
FAX:

OPERATOR: RJ AIRCRAFT LEASING
ADDRESS: 4802 AMBER VALLEY PKWY S
FARGO ND 58104-8919
PHONE:
FAX:

ANALYST: MICHAEL MUNDELL
EMAIL: MMUNDELL@CAMPSYSTEMS.COM

+1-316-462-2407 (DIRECT)
1-866-581-2267 (OFFICE)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 60 255/N160RJ **MODEL:** LEARJET 60 **MANUFACTURER:** BOMBARDIER INCORPORATED

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	10-MAY-2002	6787.9 A/C HRS	as of 03-JUN-2019	A/C HRS	as of ___/___/___
		4531 AFL	as of 03-JUN-2019	AFL	as of ___/___/___
		2624.1 APH	as of 03-JUN-2019	APH	as of ___/___/___
		888.2 ACH	as of 07-MAR-2018	ACH	as of ___/___/___

APU SERIAL/PART: SP-E990310/4503135 **MODEL:** T-20G-10C3A (CIMMS) **MANUFACTURER:** HAMILTON SUNDSTRAND CORPORATION

INSTALLED ON 25-NOV-2011		LAST ACTUALS		CURRENT ACTUAL	
1439	APU HRS	2624.1	APU HRS as of 03-JUN-2019	APU HRS	as of ___/___/___
3463	APUS	5055	APUS as of 03-JUN-2019	APUS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-305018/31B4067-02 **MODEL:** PW305A **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 22-MAR-2016		LAST ACTUALS		CURRENT ACTUAL	
9032.8	ENG. HRS	6382.8	A/C HRS as of 03-JUN-2019	ENG. HRS	as of ___/___/___
6211	ENC	6467	ENC as of 03-JUN-2019	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: PCE-305110/31B4067-02 **MODEL:** PW305A **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 22-MAR-2016		LAST ACTUALS		CURRENT ACTUAL	
9654.5	ENG. HRS	6382.8	A/C HRS as of 03-JUN-2019	ENG. HRS	as of ___/___/___
6554	ENC	6810	ENC as of 03-JUN-2019	ENC	as of ___/___/___

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS								
05-10-01-A1	C/W 300HR PHASE A1 INSPECTION IAW LEAR 60 M/M 5-10-01								
	PKG 1	MOS	12				05-OCT-2018	05-OCT-2019	19-OCT-2019
		HRS/MSC	300				6634.6	6934.6	6959.6
	REF: AMM 05-10-01	AFL					4467		
05-10-02-A2	C/W 300HR PHASE A2 INSPECTION IAW LEAR 60 M/M 5-10-02								
	PKG 2	MOS	12				05-OCT-2018	05-OCT-2019	19-OCT-2019
		HRS/MSC	300				6634.6	6934.6	6959.6
	REF: AMM 05-10-02	AFL					4467		
05-10-03-A3	C/W 300HR PHASE A3 INSPECTION IAW LEAR 60 M/M 5-10-03								
	PKG 3	MOS	12				05-OCT-2018	05-OCT-2019	19-OCT-2019
		HRS/MSC	300				6634.6	6934.6	6959.6
	REF: AMM 05-10-03	AFL					4467		
05-10-04-A4	C/W 300HR PHASE A4 INSPECTION IAW LEAR 60 M/M 5-10-04								
	PKG 4	MOS	12				05-OCT-2018	05-OCT-2019	19-OCT-2019
		HRS/MSC	300				6634.6	6934.6	6959.6
	REF: AMM 05-10-04	AFL					4467		
05-10-05-A5	C/W 300HR PHASE A5 INSPECTION IAW LEAR 60 M/M 5-10-05								
	PKG 5	MOS	12				05-OCT-2018	05-OCT-2019	19-OCT-2019
		HRS/MSC	300				6634.6	6934.6	6959.6
	REF: AMM 05-10-05	AFL					4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-06-A6	C/W 300HR PHASE A6 INSPECTION IAW LEAR 60 M/M 5-10-06								
	PKG 6	MOS	12				05-OCT-2018	05-OCT-2019	19-OCT-2019
		HRS/MSC	300	+14d/-14d			6634.6	6934.6	6959.6
	REF: AMM 05-10-06	AFL		+25/-25			4467		
05-10-07-B1	C/W 600HR PHASE B1 INSPECTION IAW LEAR 60 M/M 5-10-07								
	PKG 7	MOS	24				05-OCT-2018	05-OCT-2020	19-OCT-2020
		HRS/MSC	600	+14d/-14d			6634.6	7234.6	7259.6
	REF: AMM 05-10-07	AFL		+25/-25			4467		
05-10-08-B2	C/W 600HR PHASE B2 INSPECTION IAW LEAR 60 M/M 5-10-08								
	PKG 8	MOS	24				05-OCT-2018	05-OCT-2020	19-OCT-2020
		HRS/MSC	600	+14d/-14d			6634.6	7234.6	7259.6
	REF: AMM 05-10-08	AFL		+25/-25			4467		
05-10-09-B3	C/W 600HR PHASE B3 INSPECTION IAW LEAR 60 M/M 5-10-09								
	PKG 9	MOS	24				05-OCT-2018	05-OCT-2020	19-OCT-2020
		HRS/MSC	600	+14d/-14d			6634.6	7234.6	7259.6
	REF: AMM 05-10-09	AFL		+25/-25			4467		
05-10-10-B4	C/W 600HR PHASE B4 INSPECTION IAW LEAR 60 M/M 5-10-10								
	PKG 10	MOS	24				05-OCT-2018	05-OCT-2020	19-OCT-2020
		HRS/MSC	600	+14d/-14d			6634.6	7234.6	7259.6
	REF: AMM 05-10-10	AFL		+25/-25			4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-11-B5	C/W 600HR PHASE B5 INSPECTION IAW LEAR 60 M/M 5-10-11							
	PKG 11	MOS	24			05-OCT-2018	05-OCT-2020	19-OCT-2020
		HRS/MSC	600	+14d/-14d		6634.6	7234.6	7259.6
	REF: AMM 05-10-11	AFL		+25/-25		4467		
05-10-12-B6	C/W 600HR PHASE B6 INSPECTION IAW LEAR 60 M/M 5-10-12							
	PKG 12	MOS	24			05-OCT-2018	05-OCT-2020	19-OCT-2020
		HRS/MSC	600	+14d/-14d		6634.6	7234.6	7259.6
	REF: AMM 05-10-12	AFL		+25/-25		4467		
05-10-13-C1	C/W 1200HR PHASE C1 INSPECTION IAW LEAR 60 M/M 5-10-13							
	PKG 13	MOS	48			05-OCT-2018	05-OCT-2022	19-OCT-2022
		HRS/MSC	1200	+14d/-14d		6634.6	7834.6	7859.6
	REF: AMM 05-10-13	AFL		+25/-25		4467		
05-10-14-C2	C/W 1200HR PHASE C2 INSPECTION IAW LEAR 60 M/M 5-10-14							
	PKG 14	MOS	48			05-OCT-2018	05-OCT-2022	19-OCT-2022
		HRS/MSC	1200	+14d/-14d		6634.6	7834.6	7859.6
	REF: AMM 05-10-14	AFL		+25/-25		4467		
05-10-15-C3	C/W 1200HR PHASE C3 INSPECTION IAW LEAR 60 M/M 5-10-15							
	PKG 15	MOS	48			05-OCT-2018	05-OCT-2022	19-OCT-2022
		HRS/MSC	1200	+14d/-14d		6634.6	7834.6	7859.6
	REF: AMM 05-10-15	AFL		+25/-25		4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-16-C4	C/W 1200HR PHASE C4 INSPECTION IAW LEAR 60 M/M 5-10-16							
	PKG 16	MOS	48			05-OCT-2018	05-OCT-2022	19-OCT-2022
		HRS/MSC	1200	+14d/-14d		6634.6	7834.6	7859.6
	REF: AMM 05-10-16	AFL		+25/-25		4467		
05-10-17-C5	C/W 1200HR PHASE C5 INSPECTION IAW LEAR 60 M/M 5-10-17							
	PKG 17	MOS	48			05-OCT-2018	05-OCT-2022	19-OCT-2022
		HRS/MSC	1200	+14d/-14d		6634.6	7834.6	7859.6
	REF: AMM 05-10-17	AFL		+25/-25		4467		
05-10-18-C6	C/W 1200HR PHASE C6 INSPECTION IAW LEAR 60 M/M 5-10-18							
	PKG 18	MOS	48			05-OCT-2018	05-OCT-2022	19-OCT-2022
		HRS/MSC	1200	+14d/-14d		6634.6	7834.6	7859.6
	REF: AMM 05-10-18	AFL		+25/-25		4467		
05-10-19-D1	C/W 2400HR PHASE D1 INSPECTION IAW LEAR 60 M/M 5-10-19							
	PKG 19	MOS	96			16-OCT-2012	16-OCT-2020	30-OCT-2020
		HRS/MSC	2400	+14d/-14d		4757.3	7157.3	7182.3
	REF: AMM 05-10-19	AFL		+25/-25		3315		
05-10-20-D2	C/W 2400HR PHASE D2 INSPECTION IAW LEAR 60 M/M 5-10-20							
	PKG 20	MOS	96			16-OCT-2012	16-OCT-2020	30-OCT-2020
		HRS/MSC	2400	+14d/-14d		4757.3	7157.3	7182.3
	REF: AMM 05-10-20	AFL		+25/-25		3315		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-21-D3	C/W 2400HR PHASE D3 INSPECTION IAW LEAR 60 M/M 5-10-21							
	PKG 21	MOS	96			16-OCT-2012	16-OCT-2020	30-OCT-2020
		HRS/MSC	2400	+14d/-14d		4757.3	7157.3	7182.3
	REF: AMM 05-10-21	AFL		+25/-25		3315		
05-10-22-D4	C/W 2400HR PHASE D4 INSPECTION IAW LEAR 60 M/M 5-10-22							
	PKG 22	MOS	96			16-OCT-2012	16-OCT-2020	30-OCT-2020
		HRS/MSC	2400	+14d/-14d		4757.3	7157.3	7182.3
	REF: AMM 05-10-22	AFL		+25/-25		3315		
05-10-23-D5	C/W 2400HR PHASE D5 INSPECTION IAW LEAR 60 M/M 5-10-23							
	PKG 23	MOS	96			16-OCT-2012	16-OCT-2020	30-OCT-2020
		HRS/MSC	2400	+14d/-14d		4757.3	7157.3	7182.3
	REF: AMM 05-10-23	AFL		+25/-25		3315		
05-10-24-D6	C/W 2400HR PHASE D6 INSPECTION IAW LEAR 60 M/M 5-10-24							
	PKG 24	MOS	96			16-OCT-2012	16-OCT-2020	30-OCT-2020
		HRS/MSC	2400	+14d/-14d		4757.3	7157.3	7182.3
	REF: AMM 05-10-24	AFL		+25/-25		3315		
05-10-25-3000 LDG	C/W 3000 LANDING INSPECTION IAW LEAR 60 M/M 05-10-25							
	PKG 25	MOS				25-NOV-2011		
		HRS/MSC				4140.97		
	REF: AMM 05-10-25	AFL	3000	+25/-25		2967	5967	5992

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-26-6000 LDG	C/W 6000 LANDINGS MAJOR LANDING GEAR INSPECTION IAW LEAR 60 M/M 05-10-26							
	PKG 26	MOS				10-MAY-2002		
		HRS/MSC				0		
	REF: AMM 05-10-26	AFL	6000	+25/-25		0	6000	6025
05-10-27-12 YR	C/W 12YR/6000LANDING AIRFRAME INSPECTION IAW LEAR 60 M/M 05-10-27							
	PKG 27	MOS	144	+14d/-14d		29-SEP-2014	29-SEP-2026	13-OCT-2026
		HRS/MSC				5979.4		
	REF: AMM 05-10-27	AFL	6000	+25/-25		4026	10026	10051
05-10-28-12000 HR	C/W 12000HR AIRFRAME INSPECTION IAW LEAR 60 M/M 05-10-28							
	PKG 28	MOS				10-MAY-2002		
		HRS/MSC	12000	+25/-25		0	12000	12025
	REF: AMM 05-10-28	AFL				0		

ENGINE NO. 1	Model : PW305/PW305A/PW305B (CIMMS)	Serial #	PCE-305018	Part #	31B4067-02
052000	NO. 1 ENGINE - MINOR INSPECTION ITEMS				
	PKG 0	MOS	24	+12m	
		HRS/MSC	600	+25/-25	
	REF: GENERIC NO REF	ENC			
					12-APR-2018
					9230.9
					6367
					12-APR-2020
					(9830.9) 7180.9
					12-APR-2021
					9855.9

ENGINE NO. 2	Model : PW305/PW305A/PW305B (CIMMS)	Serial #	PCE-305110	Part #	31B4067-02
052000	NO. 2 ENGINE - MINOR INSPECTION ITEMS				
	PKG 0	MOS	24	+12m	
		HRS/MSC	600	+25/-25	
	REF: GENERIC NO REF	ENC			
					12-APR-2018
					9852.6
					6710
					12-APR-2020
					(10452.6) 7180.9
					12-APR-2021
					10477.6

CHAPTER 70 STANDARD PRACTICES - ENGINES

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
700010	LEFT ENGINE INSPECTION-AIRFRAME ITEMS							
	PKG 29	MOS				05-AUG-2011		
	REF: GENERIC CUSTOM	HRS/MSC AFL	3600	+50		3848.65 2794	7448.65	7498.65
700020	RIGHT ENGINE INSPECTION-AIRFRAME ITEMS							
	PKG 30	MOS				18-APR-2013		
	REF: GENERIC CUSTOM	HRS/MSC AFL	3600	+50		5046.42 3489	8646.42	8696.42

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
CI60-150730	REVIEW LEARJET 60 AMM REV A13, DATED 22-JUN-2015								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI60	HRS/MSC -							
		AFL							
CI60-161006	REVIEW LEARJET 60 AMM REVISION A15								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI60	HRS/MSC -							
		AFL							
CI60-170728	REVIEW LEARJET 60 AMM REVISION A16								
		MOS							
REQUIREMENT CHANGE FORMS	REF: RCF CI60	HRS/MSC -							
		AFL							
ENGINE NO. 1 Model : PW305A Serial # PCE-305018 Part # 31B4067-02									
EC24-151014-1	NO. 1 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 63.0 DATED NOV 24/2014 - CAMP CHANGE FORM								
		MOS							
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC -							
		ENC							
EC24-151014-2	NO. 1 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 64.0 DATED JUN 15/2015 - CAMP CHANGE FORM								
		MOS							
REQUIREMENT CHANGE FORMS	REF: RCF EC24	HRS/MSC -							
		ENC							

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC24-151014-3	NO. 1 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 65.0 DATED JUL 20/2015 - CAMP CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-160115	NO. 1 ENGINE - REVIEW PWC, PW305/305A/305B ENGINE MAINTENANCE MANUAL REV NO. 65.1 DATED DEC 9/2015								
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-160516	NO. 1 ENGINE - REVIEW PW305/PW305A/PW305B (CIMMS) EMM REV 66.0						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-161024	NO. 1 ENGINE - REVIEW PW305/PW305A/PW305B EMM REV 67.0								
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-161220	NO. 1 ENGINE - REVIEW PW305/305A305B MM REV 67.1								
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-170116	NO. 1 ENGINE - REVIEW PW 305/305A/305B MM REV 67.2						(EBT)		
REQUIREMENT CHANGE FORMS	REF:	MOS HRS/MSC - ENC							

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC24-170619	NO. 1 ENGINE - REVIEW	PW305/PW305A/PW305B	REV 68.0						
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-171030	NO. 1 ENGINE - REVIEW	PWC PW305/PW305A/PW305B	EMM REV 69.0						
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-180214	NO. 1 ENGINE - REVIEW	PW305/PW305A/PW305B	EMM REV 69.1						
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC					(EBT)		
ENGINE NO. 2 Model : PW305A Serial # PCE-305110 Part # 31B4067-02									
EC24-151014-1	NO. 2 ENGINE - REVIEW	PWC, PW305/305A/305B	ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 63.0 DATED NOV 24/2014 - CAMP CHANGE FORM						
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-151014-2	NO. 2 ENGINE - REVIEW	PWC, PW305/305A/305B	ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 64.0 DATED JUN 15/2015 - CAMP CHANGE FORM						
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-151014-3	NO. 2 ENGINE - REVIEW	PWC, PW305/305A/305B	ENGINE MAINTENANCE MANUAL(P/N 30B1402) REVISION NO. 65.0 DATED JUL 20/2015 - CAMP CHANGE FORM						
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC24-160115	NO. 2 ENGINE - REVIEW	PWC, PW305/305A/305B	ENGINE MAINTENANCE MANUAL REV NO. 65.1 DATED DEC 9/2015						
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-160516	NO. 2 ENGINE - REVIEW	PW305/PW305A/PW305B (CIMMS)	EMM REV 66.0				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-161024	NO. 2 ENGINE - REVIEW	PW305/PW305A/PW305B	EMM REV 67.0						
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-161024	NO. 2 ENGINE - REVIEW	PW305/PW305A/PW305B	EMM REV 67.0						
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-161220	NO. 2 ENGINE - REVIEW	PW305/305A305B	MM REV 67.1						
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-161220	NO. 2 ENGINE - REVIEW	PW305/305A305B	MM REV 67.1						
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC24-170116	NO. 2 ENGINE - REVIEW	PW 305/305A/305B	MM	REV 67.2					
REQUIREMENT CHANGE FORMS	REF:	MOS HRS/MSC - ENC					(EBT)		
EC24-170619	NO. 2 ENGINE - REVIEW	PW305/PW305A/PW305B		REV 68.0					
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-170619	NO. 2 ENGINE - REVIEW	PW305/PW305A/PW305B		REV 68.0					
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-171030	NO. 2 ENGINE - REVIEW	PWC PW305/PW305A/PW305B		EMM REV 69.0					
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-171030	NO. 2 ENGINE - REVIEW	PWC PW305/PW305A/PW305B		EMM REV 69.0					
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC							
EC24-180214	NO. 2 ENGINE - REVIEW	PW305/PW305A/PW305B		EMM REV 69.1					
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC - ENC					21-OCT-1992 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC24-180214	NO. 2 ENGINE - REVIEW	PW305/PW305A/PW305B	EMM	REV 69.1					
		MOS					21-OCT-1992		
		HRS/MSC	-				0		
REQUIREMENT CHANGE FORMS	REF: RCF EC24	ENC					0		
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS									
05-50-05 (s)	PERFORM NO. 2 ENGINE UNSCHEDULED ENGINE CHANGE / REMOVAL INSPECTIONS (REFER TO 5-50-00)						PKG		
	PKG 29,30	MOS					10-MAY-2002		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05-50-00	AFL					0		
05-50-15	MAINTENANCE PROCEDURES ON AIRCRAFT EXTERIOR SURFACE WITHIN SALT INFLUENCED ENVIRONMENTS (REFER TO 5-50-00)								
		MOS					10-MAY-2002		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05-50-00	AFL					0		
05-50-16	PERFORM FLAP OVERSPEED INSPECTION AND REPAIR (REFER TO 5-50-00)								
		MOS					10-MAY-2002		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05-50-00	AFL					0		
05-50-17	PERFORM FOREIGN OBJECT DAMAGE INSPECTION (REFER TO 5-50-00)								
		MOS							
		HRS/MSC	A/R						
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05-50-00	AFL							
05-PATS-490005	VISUALLY INSPECT ALL MOUNT PARTS AND FUSELAGE ATTACHMENT POINTS FOR CRACKS OR DAMAGE								
		MOS					29-SEP-2014		
		HRS/MSC	3000				5979.4		8979.4
	REF: SMM 49-11-03	AFL					4026		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-PATS-490006	PERFORM EXHAUST & INLET DOUBLER FRAMES & STRINGERS	MOS					10-MAY-2002		
	REF: SMM 49-11-03	HRS/MSC AFL	10000				0 0		10000
APU Model : T-20G-10C3A (CIMMS) Serial # SP-E990310 Part # 4503135									
05-PATS-490001	APU - INSPECT APU PER MANUFACTURERS INSTRUCTIONS	MOS					03-JUN-2019		
	REF: SMM 49-11-03	HRS/MSC APUS	200				2624.1 5055		2824.1
05-PATS-490002	APU - VISUAL INSPECTION APU SUPPORT STRUCTURE	MOS	12				03-JUN-2019		03-JUN-2020
	REF: SMM 49-11-03	HRS/MSC APUS					2624.1 5055		
05-PATS-490004	APU - DETAILED INSPECTION APU SUPPORT STRUCTURE	MOS					21-DEC-2007		
	REF: SMM 49-11-03	HRS/MSC APUS	3000				1046 2637		4046
05-PATS-490007	APU - DRAIN EPA SUMP	MOS					11-NOV-2009		
	REF:	HRS/MSC APUS	O/C				1267 3175		
05-T20G-490001	APU - PERFORM OIL LEVEL CHECK	MOS	1				03-JUN-2019		03-JUL-2019
	REF: MM 49-20-00	HRS/MSC APUS					2624.1 5055		
05-T20G-490002	APU - CHECK EXTERNAL FUEL AND OIL LEAKAGE, AIR INLET AND EXHAUST DUCTS FOR OBSTRUCTION AND ATTACHING BOLTS AND SCREWS FOR ATTACHMENT AND SECURITY	MOS					06-AUG-2015		
	REF: MM 49-20-00	HRS/MSC APUS	500				2232 4492		2732

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-T20G-HS-490003	APU - PERFORM APU OIL & FILTER CHANGE REF: See Workcard	MOS HRS/MSC APUS	24 500				01-AUG-2017 2351 4782	01-AUG-2019 2851	
05-T20G-HS-490004	APU - VISUAL INSPECTION ENGINE HARNESS REF: MM 49-20-00	MOS HRS/MSC APUS	500				06-AUG-2015 2232 4492	2732	
05-T20G-HS-490005	APU - INSPECT IGNITER PLUG 160544-1 NSN REF: MM 49-20-00	MOS HRS/MSC APUS	500				06-AUG-2015 2232 4492	2732	
05-T20G-HS-490006	APU - INSPECT COMBUSTOR FUEL DRAIN LINE REF: MM 49-20-00	MOS HRS/MSC APUS	500				06-AUG-2015 2232 4492	2732	
05-T20G-HS-490007	APU - INSPECT OIL OVERFILL TUBE ASSEMBLY FOR CLEANLINESS AND OBSTRUCTIONS REF: MM 49-20-00	MOS HRS/MSC APUS	500				06-AUG-2015 2232 4492	2732	
05-T20G-HS-490010	APU - INSPECT APU HOUSING, COVERS AND BRACKETS REF: MM 49-20-00	MOS HRS/MSC APUS	500				06-AUG-2015 2232 4492	2732	
05-T20G-HS-490011	APU - REPLACE FUEL INLET FILTER REF: MM 49-20-00	MOS HRS/MSC APUS	24 500				01-AUG-2017 2351 4782	01-AUG-2019 2851	

ENGINE NO. 1 Model : PW305A Serial # PCE-305018 Part # 31B4067-02

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
055002	NO. 1 ENGINE - PERFORM FOREIGN OBJECT DAMAGE (FOD) CHECKS (REFER TO 05-50-00)								
		MOS					25-OCT-1993		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	ENC					0		
055003	NO. 1 ENGINE - PERFORM ENGINE WINDMILLING IN FLIGHT INSPECTION/CHECK (REFER TO 05-50-00)								
		MOS					25-OCT-1993		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	ENC					0		
055004	NO. 1 ENGINE - PERFORM LOW AND / OR FLUCTUATING OIL PRESSURE CHECK (REFER TO 05-50-00)								
		MOS					25-OCT-1993		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	ENC					0		
055005	NO. 1 ENGINE - PERFORM LIGHTNING STRIKE INSPECTION (REFER TO 05-50-00)								
		MOS					25-OCT-1993		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 05-50-00	ENC					0		
055008	NO. 1 ENGINE - PERFORM ENGINE OPERATION IN VISIBLE VOLCANIC ASH INSPECTION (REFER TO 05-50-00)								
		MOS					25-OCT-1993		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	ENC					0		
055009	NO. 1 ENGINE - PERFORM ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT PROCEDURE (REFER TO 05-50-00)								
		MOS					25-OCT-1993		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 05-50-00	ENC					0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
055010	NO. 1 ENGINE - PERFORM HEAVY LANDING INSPECTION / CHECK (REFER TO 05-50-00)								
		MOS					25-OCT-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 05-50-00	HRS/MSC A/R					0		
		ENC					0		
055011	NO. 1 ENGINE - PERFORM SUSTAINED RUNNING AT AN OIL TEMPERATURE OUTSIDE OF LIMITS INSPECTION / CHECK (REFER TO 05-50-00)								
		MOS					25-OCT-1993		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 05-50-00	HRS/MSC A/R					0		
		ENC					0		
ENGINE NO. 2 Model : PW305A Serial # PCE-305110 Part # 31B4067-02									
055002	NO. 2 ENGINE - PERFORM FOREIGN OBJECT DAMAGE (FOD) CHECKS (REFER TO 05-50-00)								
		MOS					21-OCT-1992		
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	HRS/MSC A/R					0		
		ENC					0		
055003	NO. 2 ENGINE - PERFORM ENGINE WINDMILLING IN FLIGHT INSPECTION/CHECK (REFER TO 05-50-00)								
		MOS					21-OCT-1992		
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	HRS/MSC A/R					0		
		ENC					0		
055004	NO. 2 ENGINE - PERFORM LOW AND / OR FLUCTUATING OIL PRESSURE CHECK (REFER TO 05-50-00)								
		MOS					21-OCT-1992		
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	HRS/MSC A/R					0		
		ENC					0		
055005	NO. 2 ENGINE - PERFORM LIGHTNING STRIKE INSPECTION (REFER TO 05-50-00)								
		MOS					21-OCT-1992		
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 05-50-00	HRS/MSC A/R					0		
		ENC					0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
055008	NO. 2 ENGINE - PERFORM	ENGINE OPERATION IN VISIBLE VOLCANIC ASH INSPECTION (REFER TO 05-50-00)						21-OCT-1992	
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	MOS					0		
		HRS/MSC	A/R				0		
		ENC					0		
055009	NO. 2 ENGINE - PERFORM	ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT PROCEDURE (REFER TO 05-50-00)						21-OCT-1992	
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 05-50-00	MOS					0		
		HRS/MSC	A/R				0		
		ENC					0		
055010	NO. 2 ENGINE - PERFORM	HEAVY LANDING INSPECTION / CHECK (REFER TO 05-50-00)						21-OCT-1992	
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 05-50-00	MOS					0		
		HRS/MSC	A/R				0		
		ENC					0		
055011	NO. 2 ENGINE - PERFORM	SUSTAINED RUNNING AT AN OIL TEMPERATURE OUTSIDE OF LIMITS INSPECTION / CHECK (REFER TO 05-50-00)						21-OCT-1992	
UNSCHEDULED MAINTENANCE CHECK	REF: EMM 05-50-00	MOS					0		
		HRS/MSC	A/R				0		
		ENC					0		

CHAPTER 05-50 TIME LIMITS/MAINTENANCE CHECKS

ENGINE NO. 1 Model : PW305A Serial # PCE-305018 Part # 31B4067-02

055012	NO. 1 ENGINE - PERFORM	STARTER GENERATOR FAIL INDICATION INSPECTION (REFER TO 05-50-00)						25-OCT-1993	
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	MOS					0		
		HRS/MSC	A/R				0		
		ENC					0		

ENGINE NO. 2 Model : PW305A Serial # PCE-305110 Part # 31B4067-02

055012	NO. 2 ENGINE - PERFORM	STARTER GENERATOR FAIL INDICATION INSPECTION (REFER TO 05-50-00)						21-OCT-1992	
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	MOS					0		
		HRS/MSC	A/R				0		
		ENC					0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 08 LEVELING AND WEIGHING									
082000 (s)	PERFORM WEIGHT AND BALANCE								
		MOS	48				08-APR-2015		
		HRS/MSC					6131.38		
	REF:	AFL					4116		
CHAPTER 11 PLACARDS AND MARKINGS									
T1130001 (s)	CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS. (REFER TO 11-30-00.)						PKG		
	PKG 20	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: AMM 11-30-00	AFL					3315		
CHAPTER 12 SERVICING									
121005	PERFORM NOSE AND MAIN TIRE PRESSURE CHECKS								
		MOS					30-MAR-2012		
		HRS/MSC	A/R				4362.92		
	REF: AMM 12-10-05	AFL					3097		
D1221001 (s)	LUBRICATE NOSE LANDING GEAR ACTUATOR - LUBRICATE ATTACH FITTING. (REFER TO 12-21-01)						PKG		
	PKG 5	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: AMM 12-21-01	AFL					4467		
D1221002 (s)	LUBRICATE NOSE LANDING GEAR ACTUATOR PISTON ROD FELT WIPER. (REFER TO 12-21-01)						PKG		
	PKG 11	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: AMM 12-21-01	AFL					4467		
D1221006 (s)	INSPECT THRUST REVERSERS - LUBRICATE IDLER LINKS AND DRIVE LINKS. (REFER TO 12-21-04)						PKG		
	PKG 3	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: AMM 12-21-04	AFL					4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
D1221010 (s)	LUBRICATE MAIN LANDING GEAR AFT TRUNNION PIN. (REFER TO 12-21-01) PKG 5	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-01	HRS/MSC AFL	300	+25/-25			6634.6 4467		
D1221011 (s)	LUBRICATE MAIN LANDING GEAR FORWARD TRUNNION PIN. (REFER TO 12-21-01) PKG 5	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-01	HRS/MSC AFL	300	+25/-25			6634.6 4467		
D1221012 (s)	LUBRICATE MAIN LANDING GEAR TORQUE LINK BUSHINGS. (REFER TO 12-21-01) PKG 5	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-01	HRS/MSC AFL	300	+25/-25			6634.6 4467		
D1221013 (s)	LUBRICATE MAIN LANDING GEAR ACTUATOR STRUT ATTACH POINT. (REFER TO 12-21-01) PKG 5	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-01	HRS/MSC AFL	300	+25/-25			6634.6 4467		
F1221008 (s)	LUBRICATE MAIN LANDING GEAR DOOR ACTUATOR (48C48608) PISTON ROD FELT WIPER. (REFER TO 12-21-01). PKG 11	MOS	24	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-01	HRS/MSC AFL	600	+25/-25			6634.6 4467		
G1221004 (s)	LUBRICATE NOSE LANDING GEAR DOORS HINGES. (REFER TO 12-21-01) PKG 5	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-01	HRS/MSC AFL	300	+25/-25			6634.6 4467		
G1221005 (s)	LUBRICATE MAIN LANDING GEAR DOORS HINGES. (REFER TO 12-21-01) PKG 5	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-01	HRS/MSC AFL	300	+25/-25			6634.6 4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
G1221007 (s)	LUBRICATE NOSE LANDING GEAR UPLATCH ACTUATOR PISTON ROD FELT WIPERS. (REFER TO 12-21-01). PKG 11	MOS	24	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-01	HRS/MSC AFL	600	+25/-25					
G1221019 (s)	LUBRICATE FUSELAGE FUEL FILLER DOOR HINGE. (REFER TO 12-21-03) PKG 6	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-03	HRS/MSC AFL	300	+25/-25					
G1221020 (s)	LUBRICATE SINGLE POINT REFUELING ACCESS DOOR HINGES. (REFER TO 12-21-03) PKG 6	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-03	HRS/MSC AFL	300	+25/-25					
G1221021 (s)	LUBRICATE EMERGENCY EXIT/BAGGAGE DOOR HINGES AND LATCH PINS. (REFER TO 12-21-03) PKG 6	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-03	HRS/MSC AFL	300	+25/-25					
G1221023 (s)	LUBRICATE TOILET SERVICING DOOR HINGE. (REFER TO 12-21-03) PKG 6	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-03	HRS/MSC AFL	300	+25/-25					
G1221024 (s)	LUBRICATE TAILCONE EQUIPMENT DOOR DOOR HINGE AND LATCH PINS. (REFER TO 12-21-03) PKG 6	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-03	HRS/MSC AFL	300	+25/-25					
G1221025 (s)	LUBRICATE TAILCONE BAGGAGE DOOR DOOR HINGE AND LATCH PINS. (REFER TO 12-21-03) PKG 6	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-03	HRS/MSC AFL	300	+25/-25					

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
G1221029 (s)	INSPECT LOWER NACELLE - LUBRICATE HINGES. (REFER TO 12-21-03) PKG 3	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-03	HRS/MSC AFL	300	+25/-25			6634.6 4467		
G1221030 (s)	LUBRICATE OXYGEN SERVICING ACCESS DOOR HINGE. (REFER TO 12-21-03) PKG 2	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-03	HRS/MSC AFL	300	+25/-25			6634.6 4467		
G1230000 (s)	INSPECT ALCOHOL ANTI-ICE TANK - CHECK FOR QUANTITY OF FLUID. (REFER TO 12-10-08) PKG 2	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-10-08	HRS/MSC AFL	300	+25/-25			6634.6 4467		
H1221003 (s)	LUBRICATE NOSE LANDING GEAR ACTUATOR DOWN-LOCK SWITCH BALL. (REFER TO 12-21-01.) PKG 17	MOS	48	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-01	HRS/MSC AFL	1200	+25/-25			6634.6 4467		
H1221028 (s)	LUBRICATE UPPER AND LOWER ENTRY DOORS HINGES AND LATCH PINS. (REFER TO 12-21-03) PKG 12	MOS	24	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-03	HRS/MSC AFL	600	+25/-25			6634.6 4467		
L1221017 (s)	LUBRICATE FLAP CAM FOLLOWERS. (REFER TO 12-21-02) PKG 4	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-02	HRS/MSC AFL	300	+25/-25			6634.6 4467		
L1221036 (s)	LUBRICATE SPOILER ACTUATOR PISTON ROD FELT WIPER. (REFER TO 12-21-02). PKG 10	MOS	24	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-02	HRS/MSC AFL	600	+25/-25			6634.6 4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
M1221038 (s)	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 6027100) WING ATTACH POINTS. (REFER TO 12-21-01) PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
M1221040 (s)	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 6027100) ACTUATOR DOWN-LOCK SWITCH BALL. (REFER TO 12-21-01.) PKG 17 REF: AMM 12-21-01	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
M1221041 (s)	INSPECT THRUST REVERSERS - LUBRICATE GUIDE RODS. (REFER TO 12-21-04) PKG 3 REF: AMM 12-21-04	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
P1210051 (s)	CHECK NOSE GEAR SHOCK STRUT FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. (REFER TO 12-10-03) PKG 5 REF: AMM 12-10-03	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
P1210052 (s)	CHECK MAIN GEAR SHOCK STRUTS FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. (REFER TO 12-10-04) PKG 5 REF: AMM 12-10-04	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
P1210053 (s)	INSPECT EMERGENCY AIR PRESSURE GAUGE - CHECK FOR PROPER AIR PRESSURE (1800 TO 3000 PSI). (REFER TO 12-10-07) PKG 1 REF: AMM 12-10-07	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
P1210054 (s)	INSPECT OXYGEN PRESSURE GAUGE - CHECK FOR PROPER INFLATION (1500 TO 1850 PSI). (REFER TO 12-10-09) PKG 1 REF: AMM 12-10-09	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P1210055 (s)	CHECK NOSE AND MAIN TIRES FOR PROPER INFLATION. (REFER TO 12-10-05) PKG 5	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-10-05	HRS/MSC AFL	300	+25/-25			6634.6 4467		
P1210056 (s)	INSPECT HYDRAULIC AND THRUST REVERSER ACCUMULATORS - CHECK ACCUMULATOR PRECHARGE (850 PSI). (REFER TO 12-21-04) PKG 3	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-10-01	HRS/MSC AFL	300	+25/-25			6634.6 4467		
P1221043 (s)	LUBRICATE NOSE LANDING GEAR TRUNNION PINS. (REFER TO 12-21-01) PKG 5	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-01	HRS/MSC AFL	300	+25/-25			6634.6 4467		
R1221039 (s)	LUBRICATE MAIN LANDING GEAR ACTUATOR (P/N 2327100) PISTON ROD FELT WIPER. (REFER TO 12-21-01). PKG 11	MOS	24	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-01	HRS/MSC AFL	600	+25/-25			6634.6 4467		
X1221045 (s)	LUBRICATE R/H AVIONICS DOORS HINGES. (REFER TO 12-21-03)(EFFECTIVE ON AIRCRAFT 60-002 THRU 60-184) PKG 2	MOS	N/A				PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-03	HRS/MSC AFL	N/A				6634.6 4467		
X1221046 (s)	LUBRICATE L/H AVIONICS DOORS HINGES. (REFER TO 12-21-03)(EFFECTIVE ON AIRCRAFT 60-002 THRU 60-184) PKG 2	MOS	N/A				PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 12-21-03	HRS/MSC AFL	N/A				6634.6 4467		
CHAPTER 20	STANDARD PRACTICES - AIRFRAME								
206100	PERFORM PRECIPITATION STATIC (P-STATIC) TEST	MOS					10-APR-2015 6131.38 4116		
	REF:	HRS/MSC AFL	O/C				6131.38 4116		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 21	AIR CONDITIONING								
05-10-29-U2130007	C/W 1200HR CABIN LEAK RATE CHECK IAW LEAR 60 M/M 21-30-00	MOS					05-OCT-2018		
	REF: AMM 21-30-00	HRS/MSC AFL	1200	+25/-25			6634.6 4467	7834.6	7859.6
212001	COCKPIT AIR CHECK VALVE	MOS					10-MAY-2002		
	6600423-7	HRS/MSC	O/C	TSN:0			0		
	1047	AFL		TSN:0			0		
	REF: AMM 21-20-01			TSN:0			0		
212003	LEFT CABIN AIR CHECK VALVE	MOS					10-MAY-2002		
	6600423-10	HRS/MSC	O/C	TSN:0			0		
	554	AFL		TSN:0			0		
	REF: AMM 21-20-02			TSN:0			0		
212004	RIGHT CABIN AIR CHECK VALVE	MOS					10-MAY-2002		
	PN	HRS/MSC	O/C				0		
	SN-UNKNOWN	AFL					0		
	REF: AMM 21-20-02						0		
212007	AFT EVAPORATOR BLOWER ASSEMBLY	MOS					19-NOV-2007		
	66-0261-2	HRS/MSC	O/C	TSO:0			2236.2		
	6602612-050	AFL		TSO:0			1783		
	REF: AMM 21-51-10	ACH		TSO:0			0		
212007A	INSPECT AFT EVAPORATOR BLOWER ASSEMBLY BRUSHES	MOS					19-NOV-2007		
	66-0261-2	HRS/MSC	O/C				2236.2		
	6602612-050	AFL					1783		
	REF: GENERIC CUSTOM	ACH					0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212008	FWD EVAPORATOR BLOWER ASSEMBLY 660251-4SB 6602511-186 REF: AMM 21-51-08	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			26-OCT-2007 2217.72 1764		
212101	CABIN EVAPORATOR BLOWER PN SN-UNKNOWN REF: AMM 21-21-01	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
212104	COCKPIT EVAPORATOR BLOWER PN SN-UNKNOWN REF: AMM 21-21-04	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
213001	PRIMARY OUTFLOW VALVE 6600812-10 61-C0080 REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
213002	SECONDARY OUTFLOW VALVE 6600812-11 81-80278 REF: AMM 21-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
213003	CABIN AIR PRESSURE SELECTOR 6600812-13 51-B0244 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
213004	CABIN PRESSURE CONTROLLER 2119830-4 106-F0090 REF: AMM 21-30-04	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			26-AUG-2005 1204 998		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213005	MANUAL PRESSURE CONTROLLER 6600812-9 1133C REF: AMM 21-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
213008	PRESSURIZATION MODE SWITCH PN SN-UNKNOWN REF: AMM 21-30-08	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
213009	EMERGENCY DEPRESSURIZATION SWITCH PN SN-UNKNOWN REF: AMM 21-30-09	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
213010	CABIN PRESSURE INDICATOR 6608506-004 B0670 REF: AMM 21-30-10	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0			19-MAR-2011 3580.3 2618		
213011	VACUUM REGULATOR 6600812-6 538D REF: AMM 21-30-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
213012	VACUUM PUMP 5300-1 M4604 REF: AMM 21-30-12	MOS HRS/MSC AFL	O/C				03-MAR-2015 6100.78 4103		
213013	VACUUM CHECK VALVE 6600812-016 61-2452 REF: AMM 21-30-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213056-02	R EMER PRESS ANEROID SWITCH 2E37C-30 802 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-FEB-2010 2929.12 2246		
213101	LEFT EMERGENCY PRESSURIZATION VALVE 6600252-3 891 REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
213102	RIGHT EMERGENCY PRESSURIZATION VALVE 6600252-3 892 REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
213103	LEFT EMERGENCY PRESSURIZATION ANEROID SWITCH 2E37C-30 661 REF: AMM 21-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
213104	RIGHT EMERGENCY PRESSURIZATION ANEROID SWITCH E45C-47 4682 REF: AMM 21-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
213105	LEFT CONDITIONED AIR CHECK VALVE 6600210-5 7190AC REF: AMM 21-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
213106	RIGHT CONDITIONED AIR CHECK VALVE 6600210-5 7188AC REF: AMM 21-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213181	LEFT CHECK, AIR VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
213182	RIGHT CHECK, AIR VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
214001	FLOW CONTROL VALVE 320335-3 075 REF: AMM 21-40-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			21-MAR-2006 1495 1239		
214002	HEAT EXCHANGER 6608060-009 A124 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
214201	LEFT AUXILIARY CABIN HEATER 7026-3 184 REF: AMM 21-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
214202	RIGHT AUXILIARY CABIN HEATER 7026-4 0190 REF: AMM 21-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
215001	AIR CONDITIONING COMPRESSOR JBS222-1 JBS2221-444 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215003	CONDENSER 7608061-1 879 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
215004	RECEIVER/DRYER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
215007	C/W 2000 A/C HRS FREON COMPRESSOR DRIVE MOTOR OVERHAUL IAW LEAR 60 M/M 21-51-02 JBS222-1 K61225 REF: AMM 21-51-02 OVERHAUL	MOS HRS/MSC AFL ACH	2000	+25/-25	TSO:0		06-AUG-2015 6288.98 4196 820.7	2820.7	2845.7
215007A	C/W 1200 A/C HRS FREON COMPRESSOR DRIVE MOTOR BRUSHES INSPECTION IAW LEAR 60 M/M 21-51-02 JBS222-1 K61225 REF: AMM 21-51-02	MOS HRS/MSC AFL ACH	1200	+25/-25			06-AUG-2015 6288.98 4196 820.7	2020.7	2045.7
215009	CABIN EVAPORATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
215016	FREON MOTOR DIFFERENTIAL CURRENT SENSOR 268-1-1 0039025 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
215043	AFT EVAPORATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215044	FORWARD EVAPORATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
215049	COCKPIT EXPANSION VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
215090	REFRIGERANT HOSE 66-0858-1 1564451 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			03-NOV-2006 1806.22 1474		
216004	TEMPERATURE CONTROL INDICATOR 6608472-1 278 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
216005	COCKPIT TEMPERATURE CONTROLLER 625734-2 048C0752 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-OCT-2018 6635.2 4468		
216006	CABIN TEMPERATURE CONTROLLER 6600423-2 081C-0989 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
216009	COCKPIT TEMPERATURE SENSOR BLOWER PN SN-UNKNOWN REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216010	CABIN TEMPERATURE SENSOR BLOWER PN SN-UNKNOWN REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
216011	COCKPIT SKIN TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 21-60-06	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
216012	CABIN SKIN TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 21-60-06	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
216013	COCKPIT TEMPERATURE CONTROL VALVE 6600423-016 523 REF: AMM 21-60-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
216014	CABIN TEMPERATURE CONTROL VALVE 6600423-017 486 REF: AMM 21-60-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
216015	COCKPIT TEMPERATURE CONTROL VALVE TORQUE MOTOR 6600423-8 5305 REF: AMM 21-60-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
216016	CABIN TEMPERATURE CONTROL VALVE TORQUE MOTOR 6600423-8 5304 REF: AMM 21-60-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216017	SERVO AIR PRESSURE REGULATOR 6600245-004 843 REF: AMM 21-60-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
216018	COCKPIT AIR DISTRIBUTION CHECK VALVE PN SN-UNKNOWN REF: AMM 21-60-10	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
216019	CABIN AIR DISTRIBUTION CHECK VALVE PN SN-UNKNOWN REF: AMM 21-60-10	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
216020	COCKPIT DUCT TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 21-60-11	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
216021	CABIN DUCT TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 21-60-11	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
216022	COCKPIT DUCT OVERHEAT THERMOSTAT PN SN-UNKNOWN REF: AMM 21-60-12	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
216023	CABIN DUCT OVERHEAT THERMOSTAT PN SN-UNKNOWN REF: AMM 21-60-12	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216024	CLIMATE CONTROL BOX PN SN-UNKNOWN REF: AMM 21-60-13	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
216025	PILOT ELECTRICAL EQUIPMENT BOX PN SN-UNKNOWN REF: AMM 21-60-14	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
216101	CABIN TEMPERATURE INDICATOR 6608486-1 286 REF: AMM 21-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
216102	CABIN TEMPERATURE INDICATOR SENSOR PN SN-UNKNOWN REF: AMM 21-61-02	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
B2121004 (s)	INSPECT POSITIVE VENTILATION CHECK VALVE. (REFER TO 21-31-04.) PKG 25 REF: AMM 21-31-04	MOS HRS/MSC AFL	3000	+25/-25			PKG 25-NOV-2011 4140.97 2967		
C2132030 (s)	INSPECT CABIN (PRESSURE) CONDITIONED AIR CHECK VALVES. (REFER TO 21-31-03.) PKG 25 REF: AMM 21-31-03	MOS HRS/MSC AFL	3000	+25/-25			PKG 25-NOV-2011 4140.97 2967		
C2132031 (s)	INSPECT CABIN AIR AND COCKPIT AIR CHECK VALVES. (REFER TO 21-20-01 AND 21-20-02.) PKG 25 REF: See Workcard	MOS HRS/MSC AFL	3000	+25/-25			PKG 25-NOV-2011 4140.97 2967		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E2130005 (s)	BORESCOPE INSPECTION PRIMARY AND SECONDARY OUTFLOW VALVE POPPETS AND SEATS FOR CONTAMINATION. (REFER TO 21-30-00).						PKG		
	PKG 13	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: AMM 21-30-00	AFL					4467		
E2130064 (s)	REMOVE AND REPLACE CABIN AIR FILTER. (REFER TO 21-30-06).						PKG		
	PKG 13	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: AMM 21-30-06	AFL					4467		
H2132004 (s)	PERFORM FUNCTIONAL TEST OF EMERGENCY PRESSURIZATION SYSTEM. (REFER TO 21-31-00)						PKG		
	PKG 7	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: AMM 21-31-00	AFL					4467		
H2150000 (s)	INSPECT REFRIGERATION (AIR CONDITIONING) SYSTEM COMPONENTS INSTALLATION FOR PROPER V-BELT TENSION, SECURITY OF MOUNTING, AND GENERAL CONDITION. IF OIL LEAKS ARE VISIBLE AND/OR REFRIGERANT DUMPED, CHECK COMPRESSOR OIL LEVEL (SOME LEAKAGE IS ALLOWABLE AROUND SHAFT)						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: See Workcard	AFL					4467		
K2150006 (s)	PERFORM REFRIGERATION COMPRESSOR MOTOR BRUSH WEAR INSPECTION. (REFER TO 21-50-02)						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: AMM 21-50-02	AFL					4467		
L2150048 (s)	FUNCTIONAL TEST OF REFRIGERATION SYSTEM PRESSURE SWITCH. (REFER TO 21-50-05.)						PKG		
	PKG 21	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: AMM 21-50-05	AFL					3315		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
N2131010 (s)	FUNCTIONAL TEST OF CABIN PRESSURE WARNING SYSTEM. (REFER TO 21-30-00.) PKG 13 REF: AMM 21-30-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
N2144000 (s)	FUNCTIONAL TEST OF TAILCONE BAGGAGE COMPARTMENT HEATING SYSTEM. (REFER TO 21-44-00.) PKG 21 REF: AMM 21-44-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 16-OCT-2012 4757.3 3315		
N2150017 (s)	PERFORM A FLUORESCENT PENETRANT INSPECTION OF THE AIR CONDITIONER COMPRESSOR MOTOR FAN BLADES. PARTICULAR ATTENTION SHOULD BE GIVEN TO THE FAN BLADES IN THE AREA OF THE HUB. (REFER TO NDI MANUAL [NDI-2], PART 5, 21-50-01.) PKG 15 REF: NDT 21-50-01	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
P2130070 (s)	FUNCTIONAL TEST OF CABIN PRESSURIZATION SYSTEM. (REFER TO 21-30-00) PKG 13 REF: AMM 21-30-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
T2120001 (s)	INSPECT RAM AIR DUCTING AND HEAT EXCHANGER FRO SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00.) PKG 21 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 16-OCT-2012 4757.3 3315		
T2130012 (s)	PERFORM FUNCTIONAL TEST OF PRESSURIZATION SYSTEM VACUUM PUMP HEATING ELEMENT. (REFER TO 21-30-12) PKG 8 REF: AMM 21-30-12	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T2130069 (s)	PERFORM OPERATIONAL CHECK OF CABIN PRESSURIZATION SYSTEM. (REFER TO 21-30-00)						PKG		
	PKG 7	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: AMM 21-30-00	AFL					4467		
T2142002 (s)	FUNCTIONAL TEST OF AUXILIARY CABIN HEAT SYSTEM. (REFER TO 21-42-00.)						PKG		
	PKG 13	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: AMM 21-42-00	AFL					4467		
T2144010 (s)	VISUALLY INSPECT TAILCONE BAGGAGE COMPARTMENT HEATER BLANKETS. (REFER TO 5-10-00.)						PKG		
	PKG 21	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: GENERIC NO REF	AFL					3315		
CHAPTER 22 AUTO FLIGHT									
221001	AUTOPILOT CONTROLLER								
	501-1679-02	MOS					TSR:5	23-AUG-2013	
	1133	HRS/MSC	O/C				TSR:0	5370.27	
	REF: AMM 22-10-01	AFL					TSR:0	3666	
221003	PITCH SERVO ACTUATOR								
	622-5027-102	MOS					TSN:0	10-MAY-2002	
	HCDX	HRS/MSC	O/C				TSN:0	0	
	REF: AMM 22-10-03	AFL					TSN:0	0	
221004	PITCH SERVO MOUNT								
	622-5029-101	MOS					TSN:0	10-MAY-2002	
	G1PK	HRS/MSC	O/C				TSN:0	0	
	REF: AMM 22-10-04	AFL					TSN:0	0	
221005	AUTOPITCH TRIM AMPLIFIER BOX ASSEMBLY								
	PN	MOS					TSN:0	10-MAY-2002	
	SN-UNKNOWN	HRS/MSC	O/C				TSN:0	0	
	REF: AMM 22-10-05	AFL					TSN:0	0	

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221006	ROLL SERVO ACTUATOR 622-5027-102 GW1B REF: AMM 22-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
221007	ROLL DISCONNECT RELAY BOX PN SN-UNKNOWN REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
221008	YAW DISCONNECT RELAY BOX PN SN-UNKNOWN REF: AMM 22-10-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
221009	YAW SERVO ACTUATOR 622-5027-102 104M REF: AMM 22-10-09	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-JUN-2006 1586.95 1324		
221010	YAW SERVO MOUNT 622-5029-101 GCFD REF: AMM 22-10-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
221011	ROLL SERVO MOUNT 6080014-2 FJMX REF: AMM 22-10-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
221012	REMOTE TUNING RELAY BOX PN SN-UNKNOWN REF: AMM 22-10-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221013	NO. 1 FLIGHT GUIDANCE COMPUTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
221014	NO. 2 FLIGHT GUIDANCE COMPUTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
222001	MACH TRIM COMPUTER 501-1132-04 2371 REF: AMM 22-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
222002	MACH TRIM ADAPTER 902-1-2 0134301 REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
222003	MACH TRIM POSITION (FOLLOW UP) SENSOR PN SN-UNKNOWN REF: AMM 22-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
225001	YAW FORCE INTERFACE BOX PN SN-UNKNOWN REF: AMM 22-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
225002	PILOT FORCE SENSOR 6608498-3 1877 REF: AMM 22-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
225003	COPILOT FORCE SENSOR 6608498-3 1906 REF: AMM 22-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
B2211016 (s)	CHECK PRIMARY YAW DAMPER SERVO ACTUATOR AND SERVO MOUNT CLUTCH TORQUE. (REFER TO 22-10-09.) PKG 28 REF: See Workcard	MOS HRS/MSC AFL	12000	+25/-25			10-MAY-2002 0 0		
B2212013 (s)	CHECK PITCH SERVO MOUNT CLUTCH TORQUE. (REFER TO 22-10-06.) PKG 28 REF: AMM 22-10-04	MOS HRS/MSC AFL	12000	+25/-25			10-MAY-2002 0 0		
B2213006 (s)	CHECK AUTOPILOT ROLL SERVO MOUNT CLUTCH TORQUE. (REFER TO 22-10-06.) PKG 28 REF: AMM 22-10-11	MOS HRS/MSC AFL	12000	+25/-25			10-MAY-2002 0 0		
H2211034 (s)	CHECK ROLL SERVO CABLE TENSION. (REFER TO 22-10-11.) PKG 17 REF: AMM 22-10-11	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			05-OCT-2018 6634.6 4467		
H2211039 (s)	CHECK PITCH SERVO AND YAW SERVO CABLE TENSION. (REFER TO 22-10-04 AND 22-10-10.) PKG 15 REF: See Workcard	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			05-OCT-2018 6634.6 4467		
T2211022 (s)	CHECK YAW SERVO CABLE FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. SERVO FOR CONDITION AND SECURITY. PKG 15 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			05-OCT-2018 6634.6 4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T2212022 (s)	INSPECT ELEVATOR SERVO CABLES FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. SERVO FOR GENERAL CONDITION AND SECURITY.						PKG		
	PKG 15	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
CHAPTER 23 COMMUNICATIONS									
231101	NO. 1 VHF TRANSCEIVER								
	822-1115-001	MOS					08-SEP-2005		
	4A3A	HRS/MSC	O/C				1235.18		
	REF: AMM 23-11-01	AFL					1019		
231102	NO. 2 VHF TRANSCEIVER								
	822-1115-001	MOS					11-OCT-2005		
	1RYDL	HRS/MSC	O/C				1272		
	REF: AMM 23-11-01	AFL					1056		
231103	NO. 1 VHF ANTENNA								
	VF10-347	MOS					17-AUG-2010		
	5917	HRS/MSC	O/C				3263.28		
	REF: AMM 23-11-02	AFL					2431		
231104	NO. 2 VHF ANTENNA								
	VF10-347	MOS					17-AUG-2010		
	5918	HRS/MSC	O/C				3263.28		
	REF: AMM 23-11-02	AFL					2431		
231121	AERO M SATCOM ANTENNA								
	10101-00	MOS					21-AUG-2015		
	OP000703	HRS/MSC	O/C						
	REF: GENERIC NO REF	AFL					4196		
231201	NO. 1 HF RECEIVER/EXCITER								
	064-1015-01	MOS					30-JAN-2014		
	33301	HRS/MSC	O/C				5695.42		
	REF: AMM 23-12-01	AFL					3848		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231202	NO. 2 HF RECEIVER/EXCITER 064-1015-01 32351 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C				30-JAN-2014 5695.42 3848		
231204	STANDBY POWER AMPLIFIER/ANTENNA COUPLER 064-1017-01 17478 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			17-AUG-2010 3263.28 2431		
231205	HF ANTENNA 071-1269-02 1479 REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
231207	NO. 1 HF CONTROL UNIT 064-1016-03 3835 REF: AMM 23-12-04	MOS HRS/MSC AFL	O/C				19-AUG-2010 3264.92 2432		
231208	NO. 2 HF CONTROL UNIT 064-1016-03 11681 REF: AMM 23-12-04	MOS HRS/MSC AFL	O/C				19-AUG-2010 3264.92 2432		
231211	(CBR8) HF REMOTE CIRCUIT BREAKER 10RC1C-25 7510 REF: AMM 23-12-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
231307	COCKPIT FLIGHT PHONE (TT-3000) HANDSET 405621B-UAW 00838649 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231308	CABIN FLIGHT PHONE (TT-3000) HANDSET 405621A-UAW 00897326 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
231351	SATELLITE DATA (SDU) UNIT 403068A-UAT 437 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-AUG-2013 5370.27 3666		
231402	SELCAL DECODER 2800-0012-105 2095004 REF: AMM 23-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
233001	LEFT FORWARD CABIN STEREO SPEAKER EN-MT-60-8 080100971 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
233002	RIGHT FORWARD CABIN STEREO SPEAKER EN-MT-60-8 010100165 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
233003	LEFT AFT CABIN STEREO SPEAKER EN-MT-60-8 010100406 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
233004	RIGHT AFT CABIN STEREO SPEAKER EN-MT-60-8 100001547 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233007	DVD PLAYER DVD-011-401 100200510 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
233023	FORWARD WOOFER, CABIN SPEAKER EN-W-60-4 03000633 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
233024	AFT WOOFER, CABIN SPEAKER EN-W-60-4 060101228 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
233084	FORWARD 15.1 LCD COLOR DISPLAY AI-LCD151-01-1 10200110 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
233087	FORWARD 10.4 LCD COLOR DISPLAY AI-LCD104-01-1 030100421 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
234101	INTERPHONE AUDIO AMPLIFIER MODEL 204 1850 REF: AMM 23-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
235001	PILOT AUDIO CONTROL PANEL 802-002 618 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	TSR:15 TSR:0 TSR:0			25-NOV-2011 4140.97 2967		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
235002	COPILOT AUDIO CONTROL PANEL 802-002 757 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
235003	LEFT AUDIO AMPLIFIER 700-002 718 REF: AMM 23-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
235004	RIGHT AUDIO AMPLIFIER 700-002 791 REF: AMM 23-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
237002	CVR REMOTE MICROPHONE AMPLIFIER 1635-02 287 REF: AMM 23-70-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
237003	CVR REMOTE AREA MICROPHONE 16301-01 1172 REF: AMM 23-70-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
237004	CVR INERTIA SWITCH 3L0-453/8 L8858 REF: AMM 23-70-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
237021	CVR UNDERWATER LOCATOR (ULB) BEACON DK120 SD13216 REF: AMM 25-63-00	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			03-JUN-2019 6787.9 4531		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237021A	CLEAN/FUNCTIONAL TEST CVR UNDERWATER LOCATOR (ULB) BEACON SWITCH, BEACON AND BATTERY DK120 SD13216 REF: See Workcard	MOS HRS/MSC AFL	24	+14d/-14d			03-JUN-2019 6787.9 4531	03-JUN-2021	17-JUN-2021
237021B	REPLACE CVR UNDERWATER LOCATOR (ULB) BEACON BATTERY - 05-11-00-F2566000 DK120 SD13216 REF: AMM 25-63-00	MOS HRS/MSC AFL	DUE				03-JUN-2019 6787.9 4531	01-FEB-2025 M	
238001	NO. 1 RADIO TUNING (RTU) UNIT 822-1825-102 1GJ7V REF: AMM 23-80-01	MOS HRS/MSC AFL	O/C	TSO:1 TSO:0 TSO:0			05-OCT-2018		
238002	NO. 2 RADIO TUNING (RTU) UNIT 822-1825-102 1604 REF: AMM 23-80-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-APR-2018 6580.9 4431		
239008	NO. 2 SWITCHING MODULE MSM9660 010101411 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
239015	ORDINANCE SIGN SWITCH SP-60-004 050200709 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
239021-701	CD, 10 DISK CHANGER MCD-102-RU-1 02990060 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
239024-701	INFRARED DETECTOR IFR485-00 010300168 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
239027-701	#3 PASSENGER CONTROL UNIT SP-60-001B 050200802 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
239029-701	#4 PASSENGER CONTROL UNIT SP-60-001B 050200711 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
239029-702	#5 PASSENGER CONTROL UNIT SP-60-002B 050200708 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
239030-701	#6 PASSENGER CONTROL UNIT SP-60-001B 050200710 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
239030-702	#6 PASSENGER CONTROL UNIT SP-60-002B 050200828 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
23CUS1	C/W 12 MONTH ICA FOR AEROWAVE 100 SYSTEM IAW DOC. 89800015-002 REV 0 REF:	MOS HRS/MSC AFL	12				03-JUN-2019 6787.9 4531	03-JUN-2020	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23CUS2	AEROWAVE 100 SYSTEM HDU 90402045 299 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-DEC-2016 6451.4 4328		
E2360010 (s)	VISUALLY INSPECT STATIC DISCHARGERS. (REFER TO 23-60-00) PKG 6 REF: AMM 23-60-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
E2360011 (s)	VISUALLY INSPECT STATIC DISCHARGERS. (REFER TO 23-60-00) PKG 6 REF: AMM 23-60-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
H2360021 (s)	FUNCTIONAL TEST OF STATIC DISCHARGERS. (REFER TO 23-60-00.) PKG 22 REF: AMM 23-60-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 16-OCT-2012 4757.3 3315		
P2360022 (s)	FUNCTIONAL TEST OF STATIC DISCHARGERS. (REFER TO 23-60-00.) PKG 24 REF: AMM 23-60-00	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 16-OCT-2012 4757.3 3315		
CHAPTER 24 ELECTRICAL POWER									
05-10-29-B2432010	C/W 6 MONTH MAIN AIRCRAFT BATTERY INSTALLATION IAW LEAR 60 M/M 05-10-29 REF:	MOS HRS/MSC AFL	6	+14d/-14d			03-JUN-2019 6787.9 4531	03-DEC-2019	17-DEC-2019
05-10-29-H2431017	C/W 300HR BATTERY CABLES, CONNECTOR, & RECEPTACLES INSPECTION IAW LEAR 60 M/M 24-31-01 REF: AMM 24-31-01	MOS HRS/MSC AFL	300	+25/-25	18.28		07-MAR-2018 6570.7 4417	6888.98	6913.98

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-CUS-001	PANEL ASSY M6088221-012 BAS018021-01	MOS HRS/MSC AFL	O/C				16-DEC-2014 5978.6 4025		
CUSTOMER CODE	REF:								
242001	LEFT PRIMARY AC POWER INVERTER 6608483-1 1914 REF: AMM 24-20-01	MOS HRS/MSC AFL	O/C				06-AUG-2015 4196		
242002	RIGHT SECONDARY AC POWER INVERTER 6608483-1 1891 REF: AMM 24-20-01	MOS HRS/MSC AFL	O/C				06-AUG-2015 4196		
242003	POWER MONITOR INDICATOR 11003-003 A01075 REF: AMM 24-20-03	MOS HRS/MSC AFL	O/C	TSR:3 TSR:0 TSR:0			25-NOV-2011 4140.97 2967		
242009	NO. 1 GROUND FAULT TRANSFORMER N717-9018 2975 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
242010	NO. 2 GROUND FAULT TRANSFORMER N717-9018 2914 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
242016	GENERATOR CONTROL PANEL 6018812-007 10310845 REF: AMM 24-30-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			28-FEB-2007 1930.45 1560		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
242031	DC AMMETER SENSOR PN SN-UNKNOWN REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
242032	NO. 1 DC CURRENT SENSOR 952-500-C 2856 REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
242033	NO. 2 DC CURRENT SENSOR PN SN-UNKNOWN REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
242081	1200 VA, 115 VAC, 60 HZ INVERTER SS120(C) 151 REF: AMM 24-20-01	MOS HRS/MSC AFL	O/C				14-FEB-2017 6482.4 4351		
242505	GROUND FAULT INTERRUPTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
242507	60HZ POWER SYSTEM ANEROID SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
243001	C/W 1000HR #1 STARTER/GENERATOR OVERHAUL IAW LEAR 60 M/M 24-30-01 400SG138Q-2 2587 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			03-JUL-2017 6506 4372		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243001A	OVERHAUL NO. 1 STARTER/GENERATOR - (Y2431025) 400SG138Q-2 2587 REF: AMM 24-30-01	MOS HRS/MSC AFL	1000	+25/-25			03-JUL-2017 6506 4372	7506	7531
243002	C/W 1000HR #2 STARTER/GENERATOR OVERHAUL IAW LEAR 60 M/M 24-30-01 6608512-006 5324 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C				06-AUG-2015 6288.98 4196		
243002A	OVERHAUL NO. 2 STARTER/GENERATOR - (Y2431025) 6608512-006 5324 REF: AMM 24-30-01	MOS HRS/MSC AFL	1000	+25/-25			06-AUG-2015 6288.98 4196	7288.98	7313.98
243003	C/W 1000 APU HRS APU STARTER/GENERATOR OVERHAUL IAW CMM 49 400SG159Q 3454 REF: SMM 49-11-02	MOS HRS/MSC AFL APH	O/C				29-SEP-2014 5979.4 4026 2086		
243003A	OVERHAUL/REPLACE APU STARTER/GENERATOR BRUSHES 400SG159Q 3454 REF:	MOS HRS/MSC AFL APH	1000				29-SEP-2014 5979.4 4026 2086	3086	
243005	LEFT (GCU) GENERATOR CONTROL UNIT GCSG505-16B 1074B REF: AMM 24-30-03	MOS HRS/MSC AFL	O/C				08-FEB-2011 3558.22 2602		
243006	RIGHT (GCU) GENERATOR CONTROL UNIT GCSG505-16B 1535B REF: AMM 24-30-03	MOS HRS/MSC AFL	O/C				08-FEB-2011 3558.22 2602		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243007	A11 GENERATOR CURRENT TRANSFORMER PN SN-UNKNOWN REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
243008	2A11 GENERATOR CURRENT TRANSFORMER PN SN-UNKNOWN REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
243009	A12 GENERATOR CURRENT TRANSFORMER PN SN-UNKNOWN REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
243010	2A12 GENERATOR CURRENT TRANSFORMER PN SN-UNKNOWN REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
243011	LEFT DC AMMETER CURRENT SENSOR 256-1 206410004 REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-JAN-2007 1897.37 1537		
243012	RIGHT DC AMMETER CURRENT SENSOR 256-1 012217 REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
243049	C/W 4YR #2 LEAD ACID BATTERY REPLACEMENT IAW LEAR 60 M/M 24-31-01 RG-380E/60L 40818281 REF: See Workcard	MOS HRS/MSC AFL	48	TSN:0 TSN:0 TSN:0			13-SEP-2016 6435.5 4311	13-SEP-2020	

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243049B	CAPACITY CHECK UPPER / RIGHT / NO. 2 LEAD-ACID (CAPTIVE) BATTERY RG-380E/60L 40818281 REF: AMM 12-22-00	MOS HRS/MSC AFL	6	05-10-29-G1222002			03-JUN-2019 6787.9 4531	03-DEC-2019	
243050	C/W 4YR #1 LEAD ACID BATTERY REPLACEMENT IAW LEAR 60 M/M 24-31-01 RG380E/60L 40872899 REF: See Workcard	MOS HRS/MSC AFL	48	TSN:0 TSN:0 TSN:0			01-AUG-2017 4376	01-AUG-2021	
243050B	C/W 6 MONTH #1 LEAD ACID BATTERY CAPACITY CHECK IAW LEAR 60 M/M 12-22-00 RG380E/60L 40872899 REF: AMM 12-22-00	MOS HRS/MSC AFL	6				03-JUN-2019 6787.9 4531	03-DEC-2019	
243055	EMERGENCY POWER (24VDC TO 5VDC) CONVERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
243062	NO. 1 EMERGENCY POWER BATTERY 501-1712-02 1285 REF: AMM 24-32-01	MOS HRS/MSC AFL	O/C	TSR:56 TSR:-3999.83 TSR:1347			05-FEB-2019 6735 4497		
243062A	C/W 6 MONTH #1 EMERGENCY POWER SUPPLY OPERATIONAL CHECK IAW LEAR 60 M/M 24-32-01 501-1712-02 1285 REF: AMM 24-32-01	MOS HRS/MSC AFL	6	+14d/-14d			03-JUN-2019 6787.9 4531	03-DEC-2019	17-DEC-2019
243062B	C/W 12 MONTH #1 EMERGENCY POWER SUPPLY DISCHARGE CHECK IAW CMM 24-30-08 501-1712-02 1285 REF: See Workcard	MOS HRS/MSC AFL	12	+14d/-14d			05-OCT-2018 6634.6 4467	05-OCT-2019	19-OCT-2019

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243063	NO. 2 EMERGENCY POWER BATTERY 501-1712-02 3552 REF: AMM 24-32-01	MOS HRS/MSC AFL	O/C	TSR:67 TSR:771			05-FEB-2019 6735 4497		
243063A	C/W 6 MONTH #2 EMERGENCY POWER SUPPLY OPERATIONAL CHECK IAW LEAR 60 M/M 24-32-01 501-1712-02 3552 REF: AMM 24-32-01	MOS HRS/MSC AFL	6	+14d/-14d			03-JUN-2019 6787.9 4531	03-DEC-2019	17-DEC-2019
243063B	C/W 12 MONTH #2 EMERGENCY POWER SUPPLY DISCHARGE CHECK IAW CMM 24-30-08 501-1712-02 3552 REF: See Workcard	MOS HRS/MSC AFL	12	+14d/-14d			05-OCT-2018 6634.6 4467	05-OCT-2019	19-OCT-2019
243301	NO. 1 EMERGENCY EXIT LIGHTING BATTERY PACK M6088352-025 B0005623-01(A) REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			17-FEB-2012		
243301A	C/W 12 MONTH #1 EMERGENCY EXIT LIGHTING BATTERY PACK CHARGE IAW LEAR 60 M/M 12-23-02 M6088352-025 B0005623-01(A) REF: AMM 12-23-02	MOS HRS/MSC AFL	12	+14d/-14d			05-OCT-2018 6634.6 4467	05-OCT-2019	19-OCT-2019
243302	NO. 2 EMERGENCY EXIT LIGHTING BATTERY PACK M6088352-025 A00285994-01 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2014 5979.4 4026		
243302A	C/W 12 MONTH #2 EMERGENCY EXIT LIGHTING BATTERY PACK CHARGE IAW LEAR 60 M/M 12-23-02 M6088352-025 A00285994-01 REF: AMM 12-23-02	MOS HRS/MSC AFL	12	+14d/-14d			05-OCT-2018 6634.6 4467	05-OCT-2019	19-OCT-2019

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
244002	GROUND POWER MONITOR- PN SN-UNKNOWN REF: AMM 24-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
245001	PILOT CIRCUIT BREAKER PANEL PN SN-UNKNOWN REF: AMM 24-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
245002	COPILOT CIRCUIT BREAKER PANEL PN SN-UNKNOWN REF: AMM 24-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
245003	LEFT OVERLOAD (CBR2) SENSOR PN SN-UNKNOWN REF: AMM 24-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
245004	RIGHT OVERLOAD (CBR2) SENSOR PN SN-UNKNOWN REF: AMM 24-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
245055	DUAL BOOST CONVERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
AA2432003 (s)	PERFORM OPERATIONAL CHECK OF AC POWER SYSTEM PKG 19 REF: AMM 24-20-00	MOS HRS/MSC AFL	96	+14d/-14d 2400 +25/-25			PKG 10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H2400004 (s)	INSPECT PEDESTAL INTERIOR WIRING FOR WIRE ROUTING, CLEARANCES, DETERIORATION, AND GENERAL CONDITION. PKG 14	MOS	48	+14d/-14d			PKG	05-OCT-2018	
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25			6634.6 4467		
H2432001 (s)	OPERATIONAL CHECK EMERGENCY DC POWER DISTRIBUTION SYSTEM. (REFER TO 24-51-00.) PKG 13	MOS	48	+14d/-14d			PKG	05-OCT-2018	
	REF: AMM 24-51-00	HRS/MSC AFL	1200	+25/-25			6634.6 4467		
H2450021 (s)	REMOVE ATTACHING PARTS SECURING CIRCUIT BREAKER PANEL TO STRUCTURE. CHECK FOR LOOSE CIRCUIT BREAKER TERMINALS, LOOSE WIRE TERMINALS, CORRODED TERMINALS OR BUS BARS, AND EVIDENCE OF WIRE INSULATION DAMAGE. PKG 19	MOS	96	+14d/-14d			PKG	16-OCT-2012	
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+25/-25			4757.3 3315		
P2400008 (s)	INSPECT ELECTRICAL WIRING FOR ROUTING, CLEARANCE, AND GENERAL CONDITION (THAT PORTION VISIBLE THROUGH WHEEL WELLS). PKG 11	MOS	24	+14d/-14d			PKG	05-OCT-2018	
	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			6634.6 4467		
Q2400006 (s)	PERFORM INSPECTION OF ALL 4 AWG OR GREATER ELECTRICAL CABLES. VERIFY THERE IS NO HEAT DAMAGE TO THE LARGE GAUGE WIRE TERMINAL CONNECTIONS TO THE POWER DISTRIBUTION ASSEMBLY. INSPECT CONNECTORS AND TERMINAL LUGS FOR CONDITION AND SECURITY. INSPECT CABLE ROUTING TO PKG 9	MOS	24	+14d/-14d			PKG	05-OCT-2018	
	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			6634.6 4467		
T2400003 (s)	INSPECT ELECTRICAL WIRING, HYDRAULIC, AND PNEUMATIC LINES UNDER FLOORBOARDS FOR EVIDENCE OF LEAKAGE, SECURITY OF CLAMPS, AND CONDITION. (REFER TO 5-10-00.) PKG 20	MOS	96	+14d/-14d			PKG	16-OCT-2012	
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+25/-25			4757.3 3315		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T2400009 (s)	INSPECT ELECTRICAL WIRING FOR ROUTING, CLEARANCES SECURITY, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00.)						PKG		
	PKG 15	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
T2432000 (s)	OPERATIONAL CHECK OF DC POWER DISTRIBUTION SYSTEM. (REFER TO 24-50-00.)						PKG		
	PKG 19	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: AMM 24-50-00	AFL					3315		
T2450020 (s)	CHECK SWITCH AND CIRCUIT BREAKER PANELS FOR GENERAL CONDITION. ENSURE MARKINGS ARE CLEAR AND READABLE.						PKG		
	PKG 13	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		

CHAPTER	25	EQUIPMENT/FURNISHINGS							
251001		PILOT CREW SEAT							
		3A213-0007-01-2	MOS				TSN:0	10-MAY-2002	
		38010	HRS/MSC	O/C			TSN:0	0	
		REF: AMM 25-10-01	AFL				TSN:0	0	
251002		COPILOT CREW SEAT							
		3A213-0008-01-2	MOS				TSN:0	10-MAY-2002	
		38422	HRS/MSC	O/C			TSN:0	0	
		REF: AMM 25-10-01	AFL				TSN:0	0	
251005		PILOT LIGHTED CHART HOLDER							
		10-62-01	MOS				TSN:0	29-JAN-2003	
		3744	HRS/MSC	O/C			TSN:0	17	
		REF: AMM 25-10-05	AFL				TSN:0	12	

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251006	COPILOT LIGHTED CHART HOLDER 10-62-01 3860 REF: AMM 25-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
253052	VOLTAGE REGULATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
254001	ASSEMBLY TOILET 9060-10 U20509 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
255050	MICROWAVE OVEN 400-1726-01-L 08-02-43001 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:1 TSR:0 TSR:0			11-JUL-2012 4544.6 3211		
255050A (s)	ANNUAL INSPECTION MICROWAVE OVEN M100367ICT-SMM-1 (25-35-13) 400-1726-01-L 08-02-43001 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	12				22-MAR-2016 6382.8 4275		
ICA									
256001	(ELT) EMERGENCY LOCATOR TRANSMITTER 453-5000 09142 REF: AMM 25-62-01	MOS HRS/MSC AFL	O/C				13-SEP-2016 6435.5 4311		
256001A	C/W 12 MONTH FAR 91.207 ELT INSPECTION IAW LEAR 60 M/M 25-62-00 453-5000 09142 REF: AMM 25-62-00	MOS HRS/MSC AFL	12	+14d/-14d			05-OCT-2018 6634.6 4467	05-OCT-2019	19-OCT-2019

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256001B	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER BATTERY - 05-11-00-L2564000 453-5000 09142 REF: GENERIC NO REF	MOS HRS/MSC AFL	DUE				13-SEP-2016 6435.5 4311	30-SEP-2021 M	
256010	ELT/NAV INTERFACE 453-6500 01162 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
256060	INFANT LIFE VEST P0640-101 12030810247 REF:	MOS HRS/MSC AFL	O/C				03-OCT-2013 5478.82 3729		
256060A (s)	C/W 5YR INFANT LIFE VEST INSPECTION IAW MANUFACTURER'S INSTRUCTIONS P0640-101 12030810247 REF:	MOS HRS/MSC AFL	60	TSI:19			03-OCT-2013 5478.82 3729		
256061	NO. 1 LIFE VEST P01074-101 17020320009 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-AUG-2017		
256061A	C/W 5YR #1 LIFE VEST INSPECTION IAW MANUFACTURER'S INSTRUCTIONS P01074-101 17020320009 REF: See Workcard	MOS HRS/MSC AFL	60				01-AUG-2017	01-AUG-2022	
256062	NO. 2 LIFE VEST P01074-101 17020230010 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-AUG-2017		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256062A	C/W 5YR #2 LIFE VEST INSPECTION IAW MANUFACTURER'S INSTRUCTIONS P01074-101 17020230010 REF: See Workcard	MOS HRS/MSC AFL	60				01-AUG-2017	01-AUG-2022	
256063	NO. 3 LIFE VEST P01074-101 17020320013 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-AUG-2017		
256063A	C/W 5YR #3 LIFE VEST INSPECTION IAW MANUFACTURER'S INSTRUCTIONS P01074-101 17020320013 REF: See Workcard	MOS HRS/MSC AFL	60				01-AUG-2017	01-AUG-2022	
256064	NO. 4 LIFE VEST P01074-101 17020320014 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-AUG-2017		
256064A	C/W 5YR #4 LIFE VEST INSPECTION IAW MANUFACTURER'S INSTRUCTIONS P01074-101 17020320014 REF: See Workcard	MOS HRS/MSC AFL	60				01-AUG-2017	01-AUG-2022	
256065	NO. 5 LIFE VEST P01074-101 17020320015 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-AUG-2017		
256065A	C/W 5YR #5 LIFE VEST INSPECTION IAW MANUFACTURER'S INSTRUCTIONS P01074-101 17020320015 REF: See Workcard	MOS HRS/MSC AFL	60				01-AUG-2017	01-AUG-2022	

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256066	NO. 6 LIFE VEST P01074-101 17020320021 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-AUG-2017		
256066A	C/W 5YR #6 LIFE VEST INSPECTION IAW MANUFACTURER'S INSTRUCTIONS P01074-101 17020320021 REF: See Workcard	MOS HRS/MSC AFL	60				01-AUG-2017	01-AUG-2022	
256067	NO. 7 LIFE VEST P01074-101 17020320023 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-AUG-2017		
256067A	C/W 5YR #7 LIFE VEST INSPECTION IAW MANUFACTURER'S INSTRUCTIONS P01074-101 17020320023 REF: See Workcard	MOS HRS/MSC AFL	60				01-AUG-2017	01-AUG-2022	
256068	NO. 8 LIFE VEST D21343-153 L1935905 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:2 TSN:0 TSN:0			16-OCT-2012 4757.3 3315		
256068A (s)	C/W 5YR #8 LIFE VEST INSPECTION IAW MANUFACTURER'S INSTRUCTIONS D21343-153 L1935905 REF: See Workcard	MOS HRS/MSC AFL	60				28-AUG-2012		
256071	PILOT LIFE VEST P01074-101 1702032003 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-AUG-2017		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256071A	C/W 5YR PILOT'S LIFE VEST INSPECTION IAW MANUFACTURER'S INSTRUCTIONS P01074-101 1702032003 REF: See Workcard	MOS HRS/MSC AFL	60				01-AUG-2017	01-AUG-2022	
256072	COPILOT LIFE VEST P01074-101 17020320005 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-AUG-2017		
256072A	C/W 5YR CO-PILOT'S LIFE VEST INSPECTION IAW MANUFACTURER'S INSTRUCTIONS P01074-101 17020320005 REF: AMM 25-61-00	MOS HRS/MSC AFL	60				01-AUG-2017	01-AUG-2022	
256076	C/W 10YR PBE-PROTECTIVE BREATHING EQUIPMENT-REPLACEMENT 802300-14 E10070252 REF:	MOS HRS/MSC AFL	120				26-OCT-2010 3382.42 2500	01-JUL-2020 M	
256202	ELT ANTENNA 110-337 1110683 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
258010	AIRSHOW DIGITAL INTERFACE UNIT 920040 1132 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				08-SEP-2013 5444.47 3709		
258012	AIRSHOW FLIGHT DECK CONTROLLER 922000-2 2015 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E2510010 (s)	INSPECT CREW SEATS AND SEAT BELTS FOR OPERATION, SECURITY OF MOUNTING, AND GENERAL CONDITION PKG 1	MOS	12	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+25/-25			6634.6 4467		
N2571002 (s)	PERFORM FUNCTIONAL TEST OF NOSE AVIONICS COMPARTMENT EXHAUST BLOWERS AND THEIR RESPECTIVE CONTROL TEMPERATURE SWITCHES. (REFER TO 25-71-01.) PKG 14	MOS	48	+14d/-14d			05-OCT-2018		
	REF: AMM 25-71-01	HRS/MSC AFL	1200	+25/-25			6634.6 4467		
P2520007 (s)	INSPECT CABIN SEATS AND SEAT BELTS FOR CONDITION; BAGGAGE COMPARTMENT, STOWAGE CABINETS, STOWAGE CABINET LATCHES, RUGS, HEADLINER, AND SIDE PANELS FOR SECURITY AND CONDITION. PKG 2	MOS	12	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+25/-25			6634.6 4467		
U2510005 (s)	GENERAL VISUAL INSPECTION GLARESHIELD, HEADLINER, AND TRIM STRIPS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00) PKG 1	MOS	12	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+25/-25			6634.6 4467		
U2540004 (s)	INSPECT ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD. PKG 8	MOS	24	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			6634.6 4467		
CHAPTER 26	FIRE PROTECTION								
261001	NO. 1 FIRE DETECTION CONTROL UNIT								
	377-02833	MOS			TSN:0		10-MAY-2002		
	0132-037	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 26-11-02	AFL			TSN:0		0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261002	NO. 2 FIRE DETECTION CONTROL UNIT 377-02833 0132-042 REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
261006	TAILCONE BLEED AIR OVERHEAT (E267) CONTROL BOX 35009-20 D8211 REF: AMM 26-13-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-FEB-2019 6744.6 4505		
261007	TAILCONE BLEED AIR OVERHEAT (E268) CONTROL BOX 35009-20 D1755 REF: AMM 26-13-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
261008	TAILCONE BLEED AIR OVERHEAT (E269) CONTROL BOX PN SN-UNKNOWN REF: AMM 26-13-02	MOS HRS/MSC AFL	-	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
261026	NO. 2 ENGINE NO 2 FIRE DETECTION SENSOR ELEMENT 244-09135 073503 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-MAR-2011 3580.3 2618		
261051	NO. 1 TEE DOUBLE CHECK VALVE PN SN-UNKNOWN REF: AMM 26-21-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
261052	NO. 2 TEE DOUBLE CHECK VALVE PN SN-UNKNOWN REF: AMM 26-21-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261207	BAGGAGE COMPARTMENT SMOKE DETECTOR SENSOR ASSEMBLY FR2222 FX724 REF: AMM 26-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
262013	FORWARD FIRE EXTINGUISHER BOTTLE 32700004-1 20173C1 REF: AMM 26-21-03	MOS HRS/MSC AFL	O/C	TSN:183 TSO:9 TSO:0 TSO:0			06-AUG-2015 6288.98 4196		
262013A	C/W 6 MONTH FORWARD FIRE EXTINGUISHER BOTTLE INSPECTION IAW LEAR 60 M/M 26-21-00 - PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY. (REF TO 05-10-00) 32700004-1 20173C1 REF: AMM 26-21-00	MOS HRS/MSC AFL	6	+14d/-14d			03-JUN-2019 6787.9 4531	03-DEC-2019	17-DEC-2019
262013C	C/W 5YR FORWARD FIRE EXTINGUISHER BOTTLE HYDROSTATIC TEST IAW LEAR 60 M/M 05-10-29 32700004-1 20173C1 REF:	MOS HRS/MSC AFL	60	+14d/-14d			18-NOV-2014	18-NOV-2019	02-DEC-2019
262014	AFT FIRE EXTINGUISHER BOTTLE 32700004-1 12173C1 REF: AMM 26-21-03	MOS HRS/MSC AFL	O/C	TSN:273 TSO:8 TSO:0 TSO:0			06-AUG-2015 6288.98 4196		
262014A	C/W 6 MONTH AFT FIRE EXTINGUISHER BOTTLE INSPECTION IAW LEAR 60 M/M 26-21-00 - PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY. (REF TO 05-10-00) 32700004-1 12173C1 REF: AMM 26-21-00	MOS HRS/MSC AFL	6	+14d/-14d			03-JUN-2019 6787.9 4531	03-DEC-2019	17-DEC-2019
262014C	C/W 5YR AFT FIRE EXTINGUISHER BOTTLE HYDROSTATIC TEST IAW LEAR 60 M/M 05-10-29 32700004-1 12173C1 REF:	MOS HRS/MSC AFL	60	+14d/-14d			01-DEC-2014	01-DEC-2019	15-DEC-2019

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262036	C/W 6YR FORWARD ENGINE FIRE EXTINGUISHER FORWARD SQUIB REPLACEMENT IAW LEAR 60 M/M 26-21-04 - SERVICE LIFE 30903823 LOT:ESD14H160-001 REF: AMM 26-21-04	MOS HRS/MSC AFL	72	+14d/-14d	TSN:0		06-AUG-2015 6288.98 4196	06-AUG-2021	20-AUG-2021
SERVICE LIFE LIMIT									
262036A	C/W 9YR FORWARD ENGINE FIRE EXTINGUISHER FORWARD SQUIB REPLACEMENT IAW LEAR 60 M/M 26-21-04 - LIFE LIMIT 30903823 LOT:ESD14H160-001 REF: AMM 26-21-04	MOS HRS/MSC AFL	108	+14d/-14d			01-NOV-2014	01-NOV-2023	15-NOV-2023
LIFE LIMIT									
262037	C/W 6YR AFT ENGINE FIRE EXTINGUISHER FORWARD SQUIB REPLACEMENT IAW LEAR 60 M/M 26-21-04 - SERVICE LIFE 30903823 LOT:ESD14F149-001 REF: AMM 26-21-04	MOS HRS/MSC AFL	72	+14d/-14d	TSN:0		06-AUG-2015 6288.98 4196	06-AUG-2021	20-AUG-2021
SERVICE LIFE LIMIT									
262037A	C/W 9YR AFT ENGINE FIRE EXTINGUISHER FORWARD SQUIB REPLACEMENT IAW LEAR 60 M/M 26-21-04 - LIFE LIMIT 30903823 LOT:ESD14F149-001 REF: AMM 26-21-04	MOS HRS/MSC AFL	108	+14d/-14d			01-DEC-2014	01-DEC-2023	15-DEC-2023
LIFE LIMIT									
262038	C/W 6YR FORWARD ENGINE FIRE EXTINGUISHER AFT SQUIB REPLACEMENT IAW LEAR 60 M/M 26-21-04 - SERVICE LIFE 30903823 LOT:ESD14H160-001 REF: AMM 26-21-04	MOS HRS/MSC AFL	72	+14d/-14d	TSN:0		06-AUG-2015 6288.98 4196	06-AUG-2021	20-AUG-2021
SERVICE LIFE LIMIT									
262038A	C/W 9YR FORWARD ENGINE FIRE EXTINGUISHER AFT SQUIB REPLACEMENT IAW LEAR 60 M/M 26-21-04 - LIFE LIMIT 30903823 LOT:ESD14H160-001 REF: AMM 26-21-04	MOS HRS/MSC AFL	108	+14d/-14d			01-NOV-2014	01-NOV-2023	15-NOV-2023
LIFE LIMIT									

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262039	C/W 6YR AFT ENGINE FIRE EXTINGUISHER AFT SQUIB REPLACEMENT IAW LEAR 60 M/M 26-21-04 - SERVICE LIFE 30903823 LOT:ESD14H160-001 REF: AMM 26-21-04	MOS HRS/MSC AFL	72	+14d/-14d	TSN:0		06-AUG-2015 6288.98 4196	06-AUG-2021	20-AUG-2021
SERVICE LIFE LIMIT									
262039A	C/W 9YR AFT ENGINE FIRE EXTINGUISHER AFT SQUIB REPLACEMENT IAW LEAR 60 M/M 26-21-04 - LIFE LIMIT 30903823 LOT:ESD14H160-001 REF: AMM 26-21-04	MOS HRS/MSC AFL	108	+14d/-14d			01-DEC-2014	01-DEC-2023	15-DEC-2023
LIFE LIMIT									
262041	PILOT PORTABLE FIRE EXTINGUISHER 344T Y-32167 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:13 TSN:0 TSN:0		23-AUG-2013 5370.27 3666		
262041B	C/W 12YR PILOT PORTABLE FIRE EXTINGUISHER HYDROSTATIC TEST IAW LEAR 60 M/M 05-10-29 344T Y-32167 REF:	MOS HRS/MSC AFL	144	+14d/-14d			13-JUL-2012	13-JUL-2024	27-JUL-2024
262041D	C/W 6YR PILOT PORTABLE HAND HELD FIRE EXTINGUISHER MAINTENANCE ITEMS IAW OM05604E REF:	MOS HRS/MSC AFL	72				23-AUG-2013 5370.27 3666	23-AUG-2019	
CUSTOMER CODE									
262042	COPILOT PORTABLE FIRE EXTINGUISHER 344T Y-32166 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:13 TSN:0 TSN:0		23-AUG-2013 5370.27 3666		
262042B	C/W 12YR CO-PILOT PORTABLE FIRE EXTINGUISHER HYDROSTATIC TEST IAW LEAR 60 M/M 05-10-29 344T Y-32166 REF:	MOS HRS/MSC AFL	144	+14d/-14d			13-JUL-2012	13-JUL-2024	27-JUL-2024

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262042D	C/W 6YR CO-PILOT PORTABLE HAND HELD FIRE EXTINGUISHER MAINTENANCE ITEMS IAW OM05604E	MOS	72				23-AUG-2013 5370.27 3666	23-AUG-2019	
CUSTOMER CODE	REF:	HRS/MSC AFL							
262045	NO. 1 ENGINE FIRE - PULL SWITCH 6608480-3 587 REF: AMM 26-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
262046	NO. 2 ENGINE FIRE - PULL SWITCH 6608480-3 610 REF: AMM 26-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
262050	APU FIRE EXTINGUISHER 50-1200 02-1011 REF: SMM 49-61-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			09-NOV-2017 6532.6 4390		
262050C	C/W 12 MONTH APU FIRE EXTINGUISHER WEIGHT CHECK 50-1200 02-1011 REF: SMM 49-11-03	MOS HRS/MSC AFL	12				05-FEB-2019	05-FEB-2020	
262051	CABIN PORTABLE FIRE EXTINGUISHER C352TS Y-299663 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:9 TSN:0 TSN:0			23-AUG-2013 5370.27 3666		
262051B	C/W 12YR CABIN PORTABLE FIRE EXTINGUISHER HYDROSTATIC TEST IAW LEAR 60 M/M 05-10-29 C352TS Y-299663 REF:	MOS HRS/MSC AFL	144	+14d/-14d			01-NOV-2012	01-NOV-2024	15-NOV-2024

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262051D	C/W 6YR CABIN PORTABLE HAND HELD FIRE EXTINGUISHER MAINTENANCE ITEMS IAW OM05604E	MOS	72				23-AUG-2013	23-AUG-2019	
CUSTOMER CODE	REF:	HRS/MSC					5370.27		
		AFL					3666		
262057	C/W 5YR APU FIRE BOTTLE SQUIB REPLACEMENT	MOS	60	TSN:8			05-FEB-2019	05-JUN-2023	
LIFE LIMIT	REF: See Workcard	HRS/MSC		TSN:0			6735		
		AFL		TSN:0			4497		
H2610010 (s)	INSPECT FIREWALL AND ACCESSORY GEARBOX FIRE DETECTOR ELEMENTS FOR CHAFING, SECURITY OF CLAMPS, AND GENERAL CONDITION.						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC	600	+25/-25			6634.6		
		AFL					4467		
H2620020 (s)	DISCONNECT PLUMBING FROM THE FIRE EXTINGUISHER TWO-WAY CHECK VALVE ASSEMBLY. INSPECT FOR FREEDOM OF MOVEMENT OF THE TWO-WAY CHECK VALVE, EVIDENCE OF DEFECTS, WEAR, AND CORROSION. REPLACE VALVE CAP O-RING. (REFER TO 26-21-05.)						PKG		
	PKG 21	MOS	96	+14d/-14d			16-OCT-2012		
	REF: AMM 26-21-05	HRS/MSC	2400	+25/-25			4757.3		
		AFL					3315		
P2620041 (s)	INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						PKG		
	PKG 2	MOS	12	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC	300	+25/-25			6634.6		
		AFL					4467		
Q2620010 (s)	PERFORM WEIGHT CHECK OF FIRE EXTINGUISHER CONTAINERS. AFTER INSTALLATION OF CONTAINERS, PERFORM FUNCTIONAL TEST OF ENGINE FIRE EXTINGUISHER SYSTEM. (REFER TO 26-21-00).						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
	REF: AMM 26-21-00	HRS/MSC	600	+25/-25			6634.6		
		AFL					4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T2614000 (s)	PERFORM FUNCTIONAL TEST OF BAGGAGE COMPARTMENT SMOKE DETECTOR SYSTEM. (REFER TO 26-12-00) PKG 8	MOS	24	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 26-12-00	HRS/MSC AFL	600	+25/-25			6634.6 4467		
+ T2620045 (s)	INSPECT COPILOT PORTABLE HAND HELD FIRE EXTINGUISHER (IF EQUIPPED) FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE PKG 1	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+25/-25			6634.6 4467		
T2620045 (s)	INSPECT PILOT PORTABLE HAND HELD FIRE EXTINGUISHER (IF EQUIPPED) FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE. PKG 1	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+25/-25			6634.6 4467		
U2610020A (s)	INSPECT NO. 1 ENGINE TAILCONE FIRE DETECTION ELEMENT PKG 29	MOS					PKG 22-MAR-2016 6382.8 4275		
	REF:	HRS/MSC AFL	3600	+50			6382.8 4275		
U2610020B (s)	INSPECT NO. 2 ENGINE TAILCONE FIRE DETECTION ELEMENT PKG 30	MOS					PKG 22-MAR-2016 6382.8 4275		
	REF:	HRS/MSC AFL	3600	+50			6382.8 4275		
CHAPTER 27	FLIGHT CONTROLS								
05-10-29-H2750044L	C/W 1200HR LEFT FLAP CAM FOLLOWER BEARING DETAILED INSPECTION IAW LEAR 60 M/M 05-10-00	MOS					29-SEP-2014 5979.4 4026		
	REF: AMM 05-10-00	HRS/MSC AFL	1200	+25/-25			5979.4 4026	7179.4	7204.4

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-29-H2750044R	C/W 1200HR RIGHT FLAP CAM FOLLOWER BEARING DETAILED INSPECTION IAW LEAR 60 M/M 05-10-00	MOS					29-SEP-2014		
	REF: AMM 05-10-00	HRS/MSC AFL	1200	+25/-25			5979.4 4026	7179.4	7204.4
05-11-00-E2710010L	C/W 3600HR LEFT AILERON DRIVE YOKE BOLT REPLACEMENT IAW LEAR 60 M/M 27-10-02	MOS					19-MAR-2011		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	3600				3580.3 2618	7180.3	
05-11-00-E2710010R	C/W 3600HR RIGHT AILERON DRIVE YOKE BOLT REPLACEMENT IAW LEAR 60 M/M 27-10-02	MOS					19-MAR-2011		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	3600				3580.3 2618	7180.3	
05-11-00-E2710013L	C/W 3600HR LEFT AILERON CENTER HINGE BOLT REPLACEMENT IAW LEAR 60 M/M 27-10-02	MOS					19-MAR-2011		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	3600				3580.3 2618	7180.3	
05-11-00-E2710013R	C/W 3600HR RIGHT AILERON CENTER HINGE BOLT REPLACEMENT IAW LEAR 60 M/M 27-10-02	MOS					19-MAR-2011		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	3600				3580.3 2618	7180.3	
05-11-00-E2710020L	C/W 20000HR LEFT AILERON CLEVIS BOLT REPLACEMENT IAW LEAR 60 M/M 27-10-02	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0	20000	
05-11-00-E2710020R	C/W 20000HR RIGHT AILERON CLEVIS BOLT REPLACEMENT IAW LEAR 60 M/M 27-10-02	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0	20000	

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E2710022L	C/W 20000HR LEFT AILERON SECTOR REPLACEMENT IAW LEAR M/M 27-10-10	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-10-10	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2710022R	C/W 20000HR RIGHT AILERON SECTOR REPLACEMENT IAW LEAR 60 M/M 27-10-10	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-10-10	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2710024L	C/W 20000HR LEFT AILERON CLEVIS REPLACEMENT IAW LEAR 60 M/M 27-10-02	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2710024R	C/W 20000HR RIGHT AILERON CLEVIS REPLACEMENT IAW LEAR 60 M/M 27-10-02	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2710026L	C/W 20000HR LEFT AILERON YOKE ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-10-02	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2710026R	C/W 20000HR RIGHT AILERON YOKE ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-10-02	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2710028L	C/W 20000HR LEFT AILERON BEARING SUPPORT ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-20-10	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-20-10	HRS/MSC AFL	20000				0 0		20000

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E2710028R	C/W 20000HR RIGHT AILERON BEARING SUPPORT ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-20-10	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-20-10	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2710031L	C/W 20000HR LEFT AILERON HINGE BRACKET ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 57-40-00	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 57-40-00	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2710031R	C/W 20000HR RIGHT AILERON HINGE BRACKET ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 57-40-00	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 57-40-00	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2720020	C/W 20000HR RUDDER HINGE BOLTS REPLACEMENT IAW LEAR 60 M/M 27-20-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-20-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2720022	C/W 20000HR RUDDER SECTOR BEARING ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-20-09	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-20-09	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2720026	C/W 20000HR RUDDER HINGE BRACKETS REPLACEMENT IAW LEAR 60 M/M 55-30-00 - 5431005 & 5431056	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 55-30-00	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2730021L	C/W 20000HR LEFT ELEVATOR BELLCRANKS REPLACEMENT IAW LEAR 60 M/M 27-30-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-30-01	HRS/MSC AFL	20000				0 0		20000

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E2730021R	C/W 20000HR RIGHT ELEVATOR BELLCRANKS REPLACEMENT IAW LEAR 60 M/M 27-30-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-30-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2730022L	C/W 20000HR LEFT ELEVATOR UPPER PUSH-PULL TUBES REPLACEMENT IAW LEAR 60 M/M 27-30-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-30-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2730022R	C/W 20000HR RIGHT ELEVATOR UPPER PUSH-PULL TUBES REPLACEMENT IAW LEAR M/M 27-30-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-30-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2730024L	C/W 20000HR LEFT ELEVATOR HINGE BOLTS REPLACEMENT IAW LEAR 60 M/M 05-11-00	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 04-11-00	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2730024R	C/W 20000HR RIGHT ELEVATOR HINGE BOLTS REPLACEMENT IAW LEAR 60 M/M 05-11-00	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 04-11-00	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2740010	C/W 20000HR HORIZONTAL STABILIZER HINGE PIN REPLACEMENT IAW LEAR 60 M/ 27-40-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-40-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-E2750002L	C/W 1200HR LEFT FLAP NOSE ROLLER BUSHINGS REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					29-SEP-2014		
	REF: AMM 27-50-01	HRS/MSC AFL	1200	+25/-25			5979.4 4026		7179.4 7204.4

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E2750002R	C/W 1200HR RIGHT FLAP NOSE ROLLER BUSHINGS REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					29-SEP-2014		
	REF: AMM 27-50-01	HRS/MSC AFL	1200	+25/-25			5979.4 4026	7179.4	7204.4
05-11-00-E2750035L	C/W 6000 LANDING LEFT FLAP SECTOR REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					10-MAY-2002		
	REF: AMM 27-50-01	HRS/MSC AFL	6000				0 0	6000	
05-11-00-E2750035R	C/W 6000 LANDING RIGHT FLAP SECTOR REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					10-MAY-2002		
	REF: AMM 27-50-01	HRS/MSC AFL	6000				0 0	6000	
05-11-00-E2760059L	C/W 4500HR LEFT SPOILER ATTACH BOLTS REPLACEMENT IAW LEAR 60 M/M 27-60-01 - NAS464-P5A14	MOS					15-JUN-2012		
LIFE LIMIT	REF: AMM 27-60-01	HRS/MSC AFL	4500				4445.85 3150	8945.85	
05-11-00-E2760059R	C/W 4500HR RIGHT SPOILER ATTACH BOLTS REPLACEMENT IAW LEAR 60 M/M 27-60-01	MOS					15-JUN-2012		
LIFE LIMIT	REF: AMM 27-60-01	HRS/MSC AFL	4500				4445.85 3150	8945.85	
05-11-00-E2760061L	C/W 4500HR LEFT SPOILER ACTUATOR ARM REPLACEMENT IAW LEAR 60 M/M 27-60-04	MOS					15-JUN-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4445.85 3150	8945.85	
05-11-00-E2760061R	C/W 4500HR RIGHT SPOILER ACTUATOR ARM REPLACEMENT IAW LEAR 60 M/M 27-60-04	MOS					15-JUN-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4445.85 3150	8945.85	

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E2760062L	C/W 4500HR LEFT SPOILER ACTUATOR BOLT REPLACEMENT IAW LEAR 60 M/M 27-60-04	MOS					15-JUN-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4445.85 3150		8945.85
05-11-00-E2760062R	C/W 4500HR RIGHT SPOILER ACTUATOR BOLT REPLACEMENT IAW LEAR 60 M/M 27-60-04	MOS					15-JUN-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4445.85 3150		8945.85
05-11-00-E2760063L	C/W 4500HR LEFT SPOILER CENTER PIVOT BOLT REPLACEMENT IAW LEAR 60 M/M 27-60-04	MOS					15-JUN-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4445.85 3150		8945.85
05-11-00-E2760063R	C/W 4500HR RIGHT SPOILER CENTER PIVOT BOLT REPLACEMENT IAW LEAR 60 M/M 27-60-04	MOS					15-JUN-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4445.85 3150		8945.85
05-11-00-E2760064LI	C/W 4500HR LEFT INBOARD SPOILER HINGE BOLT REPLACEMENT IAW LEAR 60 M/M 27-60-04	MOS					15-JUN-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4445.85 3150		8945.85
05-11-00-E2760064LO	C/W 4500HR LEFT OUTBOARD SPOILER HINGE BOLT REPLACEMENT IAW LEAR 60 M/M 27-60-04	MOS					15-JUN-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4445.85 3150		8945.85
05-11-00-E2760064RI	C/W 4500HR RIGHT INBOARD SPOILER HINGE BOLT REPLACEMENT IAW LEAR 60 M/M 27-60-04	MOS					15-JUN-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4445.85 3150		8945.85

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E2760064RO	C/W 4500HR RIGHT OUTBOARD SPOILER HINGE BOLT REPLACEMENT IAW LEAR 60 M/M 27-60-04	MOS					15-JUN-2012		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	4500				4445.85 3150	8945.85	
05-11-00-F2710036	C/W 2400HR PRIMARY AILERON CONTROL CABLES REPLACEMENT IAW LEAR 60 M/M 27-10-07	MOS					16-OCT-2012		
	REF: AMM 27-10-07	HRS/MSC AFL	2400				4757.3 3315	7157.3	
05-11-00-F2720029	C/W 2400HR PRIMARY RUDDER CONTROL CABLES REPLACEMENT IAW LEAR 60 M/M 27-20-10	MOS					16-OCT-2012		
	REF: AMM 27-20-10	HRS/MSC AFL	2400	+25/-25			4757.3 3315	7157.3	7182.3
05-11-00-F2730030	C/W 2400HR PRIMARY ELEVATOR CONTROL SYSTEM CABLES REPLACEMENT IAW LEAR 60 M/M 27-30-05	MOS					29-SEP-2014		
	REF: AMM 27-30-05	HRS/MSC AFL	2400				5979.4 4026	8379.4	
05-11-00-G2740011	C/W 12YR/6000LANDING HORIZONTAL STABILIZER ACTUATOR ATTACH BOLTS REPLACEMENT IAW LEAR 60 M/M 27-40-02	MOS					29-SEP-2014	29-SEP-2026	
	REF: AMM 27-40-02	HRS/MSC AFL	144 6000				5979.4 4026	10026	
05-11-00-G2750034L	C/W 12YR/6000LANDING LEFT WING FLAP SECTOR MOUNTING BOLT REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					29-SEP-2014	29-SEP-2026	13-OCT-2026
	REF: AMM 27-50-01	HRS/MSC AFL	144 6000	+14d/-14d +25/-25			5979.4 4026	10026	10051
05-11-00-G2750034R	C/W 12YR/6000LANDING RIGHT WING FLAP SECTOR MOUNTING BOLT REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					29-SEP-2014	29-SEP-2026	13-OCT-2026
	REF: AMM 27-50-01	HRS/MSC AFL	144 6000	+14d/-14d +25/-25			5979.4 4026	10026	10051

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-L2750027LI	C/W 20000 LANDING LEFT INBOARD FLAP TRACK ASSEMBLY REPLACEMENT IAW LEAR M/M 27-50-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-L2750027LO	C/W 20000 LANDING LEFT OUTBOARD FLAP TRACK ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-L2750027RI	C/W 20000 LANDING RIGHT INBOARD FLAP TRACK ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-L2750027RO	C/W 20000 LANDING RIGHT OUTBOARD FLAP TRACK ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-L2750028	C/W 20000 LANDING INBOARD NOSE ROLLER TRACK REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-L2750029	C/W 20000 LANDING OUTBOARD NOSE ROLLER TRACK REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-L2750033L	C/W 10000 LANDING LEFT LOWER FLAP SECTOR BRACKET ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	10000				0 0		10000

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-L2750033R	C/W 10000 LANDING RIGHT LOWER FLAP SECTOR BRACKET ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	10000				0 0		10000
05-11-00-M2710021LI	C/W 20000HR LEFT INBOARD AILERON HINGE BOLTS REPLACEMENT IAW LEAR 60 M/M 27-10-02	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0		20000
05-11-00-M2710021LO	C/W 20000HR LEFT OUTBOARD AILERON HINGE BOLTS REPLACEMENT IAW LEAR 60 M/M 27-10-02	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0		20000
05-11-00-M2710021RI	C/W 20000HR RIGHT INBOARD AILERON HINGE BOLTS REPLACEMENT IAW LEAR 60 M/M 27-10-02	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0		20000
05-11-00-M2710021RO	C/W 20000HR RIGHT OUTBOARD AILERON HINGE BOLTS REPLACEMENT IAW LEAR 60 M/M 27-10-02	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-10-02	HRS/MSC AFL	20000				0 0		20000
05-11-00-M2730031	C/W 20000HR HORIZONTAL STABILIZER HINGE ASSEMBLIES REPLACEMENT IAW LEAR 60 M/M 27-30-01 - (2332013 OUTBOARD, 2332018, 2393009-801, 3532003 CENTER, AND 2332019 INBOARD)	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-30-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-M2750049LI	C/W 20000 LANDING LEFT INBOARD FLAP SUPPORT FITTING REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		20000

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-M2750049LO	C/W 20000 LANDING LEFT OUTBOARD FLAP SUPPORT FITTING REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-M2750049RI	C/W 20000 LANDING RIGHT INBOARD FLAP SUPPORT FITTING REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-M2750049RO	C/W 20000 LANDING RIGHT OUTBOARD FLAP SUPPORT FITTING REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-N2750025	C/W 6000 LANDING INBOARD FLAP TRACK HINGE FITTING REPLACEMENT IAW LEAR 60 M/M 27-50-01 - (P/N 2625023)	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	6000				0 0		6000
05-11-00-N2750026	C/W 6000 LANDING OUTBOARD FLAP TRACK HINGE FITTING REPLACEMENT IAW LEAR 60 M/M 27-50-01 - (P/N 2625024)	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	6000				0 0		6000
05-11-00-N2750031	C/W 3000 LANDING INBOARD AND OUTBOARD FLAP SUPPORT FITTING REPLACEMENT IAW LEAR 60 M/M 27-50-01 - (6022521-1 THRU-8)	MOS					25-NOV-2011		
NOT APPLICABLE	REF: AMM 27-50-01	HRS/MSC AFL	N/A				4140.97 2967		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-N2750032	C/W 3000 LANDING UPPER FLAP SECTOR BRACKET ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-50-01 - (6022511-1, -2, -801, AND -802)	MOS					25-NOV-2011		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	3000				4140.97 2967		5967
05-11-00-N2750051	C/W 20000 LANDING INBOARD FLAP HINGE FITTING REPLACEMENT IAW LEAR 60 M/M 27-50-01 - (P/N 6025022)	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-N2750052	C/W 20000 LANDING OUTBOARD FLAP HINGE FITTING REPLACEMENT IAW LEAR 60 M/M 27-50-01 - (P/N 6025021)	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-R2750050L	C/W 20000 LANDING LEFT UPPER FLAP SECTOR BRACKET REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-R2750050R	C/W 20000 LANDING RIGHT UPPER FLAP SECTOR BRACKET REPLACEMENT IAW LEAR 60 M/M 27-50-01	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-50-01	HRS/MSC AFL	20000				0 0		20000
05-11-00-R2760079L	C/W 10000HR LEFT SPOILER ACTUATOR ATTACH FITTING AND BOLT REPLACEMENT IAW LEAR 60 M/M 27-60-04	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	10000				0 0		10000
05-11-00-R2760079R	C/W 10000HR RIGHT SPOILER ACTUATOR ATTACH FITTING AND BOLT REPLACEMENT IAW LEAR 60 M/M 27-60-04	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 27-60-04	HRS/MSC AFL	10000				0 0		10000

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-06-082	LEFT INBOARD FLAP NOSE ROLLER SUPPORT ARM PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
27-51-06-082	LEFT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
27-51-06-082	RIGHT INBOARD FLAP NOSE ROLLER SUPPORT ARM PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
27-51-06-082	RIGHT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
27-51-06-085	LEFT FLAP LEADING EDGE RIB PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
27-51-06-085	RIGHT FLAP LEADING EDGE RIB PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
270505	TRIM SWITCH PANEL ASSEMBLY PN SN-UNKNOWN REF: AMM 27-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271013	AILERON TRIM TAB ASSEMBLY PN SN-UNKNOWN REF: AMM 27-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
271015	LEFT AILERON BALANCE TAB ASSEMBLY PN SN-UNKNOWN REF: AMM 27-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
271016	RIGHT AILERON BALANCE TAB ASSEMBLY PN SN-UNKNOWN REF: AMM 27-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
271019	AILERON TRIM ACTUATOR 6600156-034 B0192 REF: AMM 27-10-11	MOS HRS/MSC AFL	O/C				30-DEC-2011 4179.47 2988		
271025	PILOT CONTROL WHEEL 2415151-017 2620 REF: AMM 27-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
271026	COPILOT CONTROL WHEEL 2415151-018 2670 REF: AMM 27-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
271027	PILOT CONTROL COLUMN 5415150-023-623 MRP949559 REF: AMM 27-30-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271028	COPILOT CONTROL COLUMN PN SN-UNKNOWN REF: AMM 27-30-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
271031	AILERON TRIM TAB ACTUATOR POTENTIOMETER PN SN-UNKNOWN REF: AMM 27-10-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
271126	AILERON TRIM POSITION INDICATOR 6608217-21 400 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-MAR-2011 3580.3 2618		
271131	LEFT AILERON POSITION SENSOR 501-1123-03 6882 REF: AMM 27-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
271132	RIGHT AILERON POSITION SENSOR 501-1123-03 6884 REF: AMM 27-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
271701	C/W 20000HR LEFT AILERON ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-10-02 2424000-295 W679 REF: AMM 27-10-02	MOS HRS/MSC AFL	20000	TSN:71 TSN:2360.78 TSN:1868			11-APR-2008 2360.78 1868		20000
271702	C/W 20000HR RIGHT AILERON ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-10-02 2424000-292 W655 REF: AMM 27-10-02	MOS HRS/MSC AFL	20000	TSN:71 TSN:2360.78 TSN:1868			11-APR-2008 2360.78 1868		20000

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272001	C/W 20000HR RUDDER ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-20-01 5433000-20 W471 REF: AMM 27-20-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0	20000	
LIFE LIMIT									
272005	AFT RUDDER SECTOR PN SN-UNKNOWN REF: AMM 27-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
272007	RUDDER TRIM TAB PN SN-UNKNOWN REF: AMM 27-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
272013	RUDDER TRIM TAB ACTUATOR 6600156-033 B0069 REF: AMM 27-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
272020	RUDDER TRIM TAB POTENTIOMETER PN SN-UNKNOWN REF: AMM 27-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
272026	RUDDER TRIM INDICATOR 6608217-20 260 REF: AMM 27-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
272031	PILOT RUDDER PEDAL ACTUATOR 6600418-4 227 REF: AMM 27-20-07	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			29-MAR-2007 1963.3 1588		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272032	COPILOT RUDDER PEDAL ACTUATOR 6600418 642 REF: AMM 27-20-07	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0			10-DEC-2009 2831.13 2200		
273001	C/W 20000HR LEFT ELEVATOR ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-30-01 2434000-177 633 REF: AMM 27-30-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0	20000	
LIFE LIMIT									
273002	C/W 20000HR RIGHT ELEVATOR ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-30-01 2434000-178 666 REF: AMM 27-30-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0	20000	
LIFE LIMIT									
273013	STALL WARNING COMPUTER 6608263-18 GST02557 REF: AMM 27-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
273017	PILOT STICK SHAKER 6608289-3 871A REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
273018	COPILOT STICK SHAKER 6608289-3 876A REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
273101	PILOT STALL WARNING TRANSDUCER 6608263-019 GST04001 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			15-AUG-2005 1203.65 997		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273102	COPILOT STALL WARNING TRANSDUCER 25147A-12 GST04104 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
273105	PILOT ANGLE-OF-ATTACK (AOA) INDICATOR 6608515-2 01022953 REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C				19-MAR-2011 3580.3 2618		
273106	COPILOT ANGLE-OF-ATTACK (AOA) INDICATOR 6608515-2 01085218 REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
273110	ANGLE-OF-ATTACK (AOA) VANE PN SN-UNKNOWN REF: AMM 27-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
274001	HORIZONTAL STABILIZER 2332000-60 363 REF: AMM 27-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
274003	HORIZONTAL STABILIZER ACTUATOR CONTROLLER EM2079-9 1193A REF: AMM 27-40-03	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			28-JUL-2012 4599 3240		
274010	TRIM-IN-MOTION DETECTOR 6608326-004 0227066 REF: AMM 27-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
274013	C/W 600HR HORIZONTAL STABILIZER ACTUATOR OVERHAUL IAW LEAR 60 M/M 27-40-02								
	5435005-028	MOS		TSO:0			07-MAR-2018		
OVERHAUL	302 REF: AMM 27-40-02	HRS/MSC AFL	600 +25/-25	TSO:0 TSO:0	8.7		6570.7 4417	7179.4	7204.4
274062	PITCH TRIM INDICATOR								
	6608514-1	MOS		TSN:0			10-MAY-2002		
	282 REF: AMM 27-40-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
274070	STABILIZER POSITION SWITCH								
	CS402-3	MOS		TSN:0			10-MAY-2002		
	10032 REF: AMM 27-40-06	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
274072	STABILIZER POSITION SENSOR								
	501-1123-03	MOS		TSN:0			10-MAY-2002		
	6892 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
275001	C/W 10000 LANDING LEFT FLAP ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-50-01								
	6025010-031	MOS		TSN:0			10-MAY-2002		
LIFE LIMIT	W1437 REF: AMM 27-50-01	HRS/MSC AFL	10000	TSN:0 TSN:0			0 0	10000	
275002	C/W 10000 LANDING RIGHT FLAP ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-50-01								
	6025010-032	MOS		TSN:0			10-MAY-2002		
LIFE LIMIT	W1433 REF: AMM 27-50-01	HRS/MSC AFL	10000	TSN:0 TSN:0			0 0	10000	
2750058	* LEFT FLAP LEADING EDGE RIB - REPLACE (AWL*)								
	PN	MOS					10-MAY-2002		
NOT APPLICABLE	SN-UNKNOWN REF: See Workcard	HRS/MSC AFL	N/A				0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 2750058	* LEFT INBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				10-MAY-2002 0 0		
+ 2750058	* LEFT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				10-MAY-2002 0 0		
2750058	* RIGHT FLAP LEADING EDGE RIB - REPLACE (AWL*) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				10-MAY-2002 0 0		NOT APPLICABLE
+ 2750058	* RIGHT INBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				10-MAY-2002 0 0		
+ 2750058	* RIGHT OUTBOARD FLAP NOSE ROLLER SUPPORT ARM - REPLACE (AWL*) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				10-MAY-2002 0 0		
275010	FLAP & ENGINE SYNCHRONIZER RELAY BOX ASSEMBLY PN SN-UNKNOWN REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
275012	FLAP POSITION POTENTIOMETER PN SN-UNKNOWN REF: AMM 27-50-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275019	LEFT LIMIT, INBOARD FLAP/STABILIZER SWITCH CS402-3 9848 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
275020	RIGHT LIMIT, INBOARD FLAP/STABILIZER SWITCH CS402-3 9321 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
275021	LEFT POSITION, OUTBOARD FLAP/STABILIZER SWITCH CS402-3 9799 REF: AMM 27-50-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
275022	RIGHT POSITION, OUTBOARD FLAP/STABILIZER SWITCH CS402-3 9925 REF: AMM 27-50-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
275031	FLAP CONTROL (FLAP/SPOILER) VALVE 6600362-1 1028A REF: AMM 27-50-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
275036	FLAP RESTRICTOR VALVE 2R1047-0312 2126 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
275037	LEFT FLAP ACTUATOR 6600493-2 0411 REF: AMM 27-50-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275038	RIGHT FLAP ACTUATOR 6600493-2 0406 REF: AMM 27-50-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
275200	FLAP POSITION INDICATOR 6608475-004 221 REF: AMM 27-50-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
275213	FLAP PRESSURE RELIEF VALVE AN6245A4 188O3 REF: AMM 27-50-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
275217	FLAP ACTUATION CHECK VALVE PN SN-UNKNOWN REF: AMM 27-50-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
275407	FLAP SELECT SWITCH PN SN-UNKNOWN REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
276001	C/W 4500HR LEFT SPOILER ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-60-01 2422510-131 132 REF: AMM 27-60-01	MOS HRS/MSC AFL	4500	TSN:5 TSN:0 TSN:0			15-JUN-2012 4445.85 3150	8945.85	
LIFE LIMIT									
276002	C/W 4500HR RIGHT SPOILER ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-60-01 2422510-130 101 REF: AMM 27-60-01	MOS HRS/MSC AFL	4500	TSN:6 TSN:0 TSN:0			15-JUN-2012 4445.85 3150	8945.85	
LIFE LIMIT									

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276005	LEFT SPOILER FLOW CONTROL SERVO VALVE PN SN-UNKNOWN REF: AMM 27-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
276006	RIGHT SPOILER FLOW CONTROL SERVO VALVE PN SN-UNKNOWN REF: AMM 27-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
276010	SPOILER COMPUTER 6608454-3 1524 REF: AMM 27-60-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			25-MAY-2005 1124.7 919		
276013	C/W 10000HR LEFT SPOILER ACTUATOR ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-60-04 2417015-5 2157 REF: AMM 27-60-04	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0	10000	
LIFE LIMIT									
276014	C/W 10000HR RIGHT SPOILER ACTUATOR ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 27-60-04 2417015-5 2138 REF: AMM 27-60-04	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0	10000	
LIFE LIMIT									
276037	LEFT SPOILER POSITION SENSOR 501-1123-03 6345 REF: AMM 27-60-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
276038	RIGHT SPOILER POSITION SENSOR 501-1123-03 6448 REF: AMM 27-60-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276043	SPOILER POTENTIOMETER PN SN-UNKNOWN REF: AMM 27-60-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
276049	SPOILER POSITION INDICATOR 6608476-3 261 REF: AMM 27-60-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
276128	SPOILER MANIFOLD VALVE 2627023-1 1087 REF: AMM 27-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
276265	WHEEL SPEED DETECTION BOX 6018366-005 BAS002423-01C REF: AMM 27-60-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-AUG-2005 1203.65 997		
B2760050 (s)	PERFORM FUNCTIONAL TEST OF SPOILER (UP LIMIT) SWITCH. (REFER TO 27-60-05.) PKG 28 REF: AMM 27-60-05	MOS HRS/MSC AFL	12000	+25/-25			PKG 10-MAY-2002 0 0		
C2700011 (s)	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION. PKG 27 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 02-SEP-2014 5979.4 4026		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C2700013 (s)	WITH ALL MOVEABLE FLIGHT CONTROL SURFACES REMOVED (FLAPS, AILERONS, AND SPOILERS), INSPECT ALL BEARINGS, BUSHINGS, AND ROLLERS FOR SECURITY, ROUGHNESS, SEIZURE, RUST OR CORROSION, AND WEAR. INSPECT ASSEMBLIES FOR CORROSION, FATIGUE CRACKS, WEAR, EVIDENCE						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014	5979.4	
	REF: GENERIC NO REF	AFL	6000	+25/-25			4026		
C2700019 (s)	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION.						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014	5979.4	
	REF: GENERIC NO REF	AFL	6000	+25/-25			4026		
C2700020 (s)	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION.						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014	5979.4	
	REF: GENERIC NO REF	AFL	6000	+25/-25			4026		
C2700022 (s)	INSPECT THE BEARINGS OF ALL CONTROL SYSTEM BELLCRANKS AND SECTORS FOR WEAR, ROUGHNESS, SECURITY, GENERAL CONDITION, AND EASE OF OPERATION.						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014	5979.4	
	REF: GENERIC NO REF	AFL	6000	+25/-25			4026		
C2700023 (s)	WITH ALL MOVEABLE FLIGHT CONTROL SURFACES REMOVED (RUDDER AND ELEVATORS), INSPECT ALL BEARINGS, BUSHINGS, AND ROLLERS FOR SECURITY, ROUGHNESS, SEIZURE, RUST OR CORROSION, AND WEAR. INSPECT ASSEMBLIES FOR CORROSION, FATIGUE CRACKS, WEAR, EVIDENCE OF INTERF						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014	5979.4	
	REF: GENERIC NO REF	AFL	6000	+25/-25			4026		
E2700031 (s)	CHECK ELEVATOR AND RUDDER CONTROL CABLES FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEY, PULLEY BRACKETS, AND GUARDS FOR SECURITY AND GENERAL CONDITION.						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018	6634.6	
	REF: GENERIC NO REF	AFL	600	+25/-25			4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E2700032 (s)	INSPECT CONTROL CABLES UNDER FLOORBOARDS FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEYS, GUARDS, AND SAFETIES FOR PROPER OPERATION. PKG 8	MOS	24	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			6634.6 4467		
E2710005 (s)	HOLD CONTROL WHEEL INA FIXED POSITION AND APPLY UP AND DOWN LOADS ON THE AILERON TRAILING EDGE. OBSERVE AILERON DRIVE ASSEMBLY AREA FOR WEAR IN SHAFT KEYWAYS, FAILURE OF BEARINGS, AND AILERON YOKE SLIPPAGE. PKG 16	MOS	48	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25			6634.6 4467		
E2730025 (s)	INSPECT CONTROL COLUMNS (INCLUDING CONTROL WHEELS AND BOOTS) FOR CONDITION, PROPER OPERATION, AND CLEARANCES. PKG 1	MOS	12	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+25/-25			6634.6 4467		
F2740020 (s)	REMOVE STABILIZER ACTUATOR. INSPECT UPPER AND LOWER ATTACHMENT STRUCTURE FOR FATIGUE CRACKS, DISTORTION, WEAR, CORROSION, AND GENERAL SECURITY. PKG 27	MOS	144	+14d/-14d			02-SEP-2014		
	REF: AMM 27-40-02	HRS/MSC AFL	6000	+25/-25			5979.4 4026		
H2700018 (s)	VISUALLY INSPECT SPOILER, FLAP, AILERON, AND AILERON TRIM TAB ELECTRICAL BONDING JMPERS FRO SECURITY AND GENERAL CONDITION. PKG 10	MOS	24	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			6634.6 4467		
H2700021 (s)	INSPECT THE RUDDER AND ELEVATOR BALANCE WEIGHT INSTALLATIONS AND SUPPORTING STRUCTURE. INSPECT FOR EVIDENCE OF VIBRATION, FASTENER WORKING, FATIGUE CRACKS, AND GENERAL SECURITY. REMOVE ACCESS COVERS FOR DEFINITIVE INSPECTION OF INTERNAL MOUNTING BRACKETS OR STRUC PKG 18	MOS	48	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25			6634.6 4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H2700024 (s)	INSPECT THE AILERON BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE. INSPECT FOR EVIDENCE OF VIBRATION, FASTENER WORKING, FATIGUE CRACKS, AND GENERAL SECURITY. REMOVE ACCESS COVERS FOR DEFINITIVE INSPECTION OF INTERNAL MOUNTING BRACKETS OR STRUCTURE.						PKG		
	PKG 16	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
H2710032 (s)	CHECK AILERON, RUDDER, AND ELEVATOR CONTROL SYSTEM CABLE TENSIONS. (REFER TO 27-10-00, 27-20-00 AND 27-30-00.)						PKG		
	PKG 14	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: See Workcard	AFL					4467		
H2731000 (s)	PERFORM STALL WARNING SYSTEM FUNCTIONAL TEST. (REFER TO 27-31-00)						PKG		
	PKG 7	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: AMM 27-31-00	AFL					4467		
P2700049 (s)	REMOVE ALL PANELS REQUIRED TO GAIN ACCESS TO CABLES, PULLEYS, SECTORS, AND ASSOCIATED EQUIPMENT. VISUALLY INSPECT ACCESSIBLE PORTIONS OF FLIGHT CONTROLS FOR PROPER CONDITION, CABLE CLEARANCE, AND GENERAL CONDITION. PAY PARTICULAR ATTENTION TO FLIGHT CONTROL CABL						PKG		
	PKG 11	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
P2700050 (s)	CHECK FOR FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS.						PKG		
	PKG 1	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
P2700055 (s)	VISUALLY INSPECT ELEVATOR, RUDDER, AND RUDDER TRIM TAB ELECTRICAL BONDING JUMPERS FOR SECURITY AND GENERAL CONDITION.						PKG		
	PKG 12	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P2700057 (s)	CHECK FOR FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS. PKG 4 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
P2710044 (s)	CHECK AILERON AND FLAP SYSTEM CONTROL CABLE TENSIONS. (REFER TO 27-10-00 AND 27-50-00.) PKG 16 REF: See Workcard	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
P2710045 (s)	REMOVE CONTROL WHEEL SECTOR AND TURNBUCKLE COVERPLATE FROM CONTROL COLUMN. MOVE CONTROL WHEEL TO BOTH EXTREME RIGHT AND LEFT WHILE INSPECTING FOR FRAYED OR DAMAGED CABLES. PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
P2710046 (s)	DISASSEMBLE CONTROL COLUMN AS REQUIRED TO INSPECT PULLEYS, BEARINGS, ELECTRICAL WIRING FOR PROPER ROUTING AND CHAFING, AND CONTROL COLUMNS FOR GENERAL CONDITION. PKG 19 REF: AMM 27-30-06	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 16-OCT-2012 4757.3 3315		
P2760003 (s)	INSPECT SPOILER ACTUATOR INSTALLATION FOR SECURITY, SUPPORT STRUCTURE CRACKS, AND GENERAL CONDITION. PKG 10 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
Q2700051 (s)	INSPECT RUDDER AND ELEVATOR CONTROLS (INCLUDING DOWNSPRING INSTALLATION WHEN INSTALLED AND PUSH-PULL TUBES) FOR PROPER OPERATION, GENERAL CONDITION AND SECURITY. PKG 18 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T2700017 (s)	INSPECT STRUCTURE, PULLEY BRACKETS, AND CONTROLS UNDER FLOORBOARDS FROM PEDESTAL AND CONTROL COLUMN AFT TO FRAME 24 FOR OPERATION, CLEARANCES, CRACKS, AND GENERAL CONDITION. PAY PARTICULAR ATTENTION TO THE ELEVATOR PULLEY BRACKET CUTOUT AREA RADIUS FOR CRACKS. (S						PKG		
	PKG 14	MOS	48	+14d/-14d			05-OCT-2018	6634.6	
	REF: GENERIC NO REF	HRS/MSC	1200	+25/-25			4467		
		AFL							
T2700052 (s)	USING THE PROPER COCKPIT CONTROLS, CHECK FLAPS, SPOILERS, HORIZONTAL STABILIZER, AND TRIM TABS FOR PROPER OPERATION AND ACCURATE INDICATION.						PKG		
	PKG 13	MOS	48	+14d/-14d			05-OCT-2018	6634.6	
	REF: See Workcard	HRS/MSC	1200	+25/-25			4467		
		AFL							
T2700056 (s)	CHECK FOR FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS.						PKG		
	PKG 12	MOS	24	+14d/-14d			05-OCT-2018	6634.6	
	REF: GENERIC NO REF	HRS/MSC	600	+25/-25			4467		
		AFL							
T2700058 (s)	CHECK FOR FULL TRAVEL AND FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS AND FOR PROPER ENGAGEMENTS OF PRIMARY STOPS.						PKG		
	PKG 20	MOS	96	+14d/-14d			16-OCT-2012	4757.3	
	REF: GENERIC NO REF	HRS/MSC	2400	+25/-25			3315		
		AFL							
T2700059 (s)	CHECK FOR FULL TRAVEL AND FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS AND FOR PROPER ENGAGEMENTS OF PRIMARY STOPS.						PKG		
	PKG 24	MOS	96	+14d/-14d			16-OCT-2012	4757.3	
	REF: GENERIC NO REF	HRS/MSC	2400	+25/-25			3315		
		AFL							
T2700060 (s)	CHECK FOR FULL TRAVEL AND FREEDOM OF MOVEMENT OF ALL FLIGHT CONTROLS AND FOR PROPER ENGAGEMENTS OF PRIMARY STOPS.						PKG		
	PKG 22	MOS	96	+14d/-14d			16-OCT-2012	4757.3	
	REF: GENERIC NO REF	HRS/MSC	2400	+25/-25			3315		
		AFL							

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T2710042 (s)	INSPECT AILERON AND AILERON TABS AND DRIVE MECHANISM FOR SECURITY, OPERATION, AND GENERAL CONDITION.						PKG		
	PKG 16	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: AMM 27-10-04	AFL					4467		
T2720027 (s)	INSPECT RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS FOR SECURITY, PROPER OPERATION, AND CLEARANCES.						PKG		
	PKG 20	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: GENERIC NO REF	AFL					3315		
T2730029 (s)	CHECK CONTROL COLUMN ASSEMBLY FREE PLAY. (REFER TO 27-30-06.)						PKG		
	PKG 20	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: AMM 27-30-06	AFL					3315		
T2731075 (s)	FUNCTIONAL TEST OF STALL WARNING ALTITUDE SWITCHES. (REFER TO 27-31-00.)						PKG		
	PKG 19	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: AMM 27-31-00	AFL					3315		
T2760030 (s)	INSPECT SPOILER AND HINGE INSTALLATION FOR SECURITY, CRACKS, AND GENERAL CONDITION.						PKG		
	PKG 16	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
T2760031 (s)	INSPECT SPOILER CENTER ANGLE BRACKET RIVETS, LOWER SKIN CENTER RIB AND SUBSPAR RIVETS FOR EVIDENCE OF WORKING. WITH SPOILERS EXTENDED, APPLY ALTERNATE UP AND DOWN LOADS TO SPOILER TRAILING EDGE. CHECK MOTION AT CENTER HINGE. INSPECT SPOILER ACTUATOR MECHANISM AND						PKG		
	PKG 16	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T2760040 (s)	FUNCTIONAL TEST OF SPOILER RESTRICTOR BYPASS VALVE COMPUTER CIRCUITRY AND WIRING. (REFER TO 27-60-03.)						PKG		
	PKG 16	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: AMM 27-60-03	AFL					4467		
T2760084 (s)	VISUAL INSPECTION SPOILER CENTER ANGLE BRACKET RIVETS AND UPPER AND LOWER SKIN CENTER RIB AREA. (REFER TO 5-10-00.)						PKG		
	PKG 4	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
U2700033 (s)	INSPECT ALL CABLES, PULLEYS, SECTORS, AND PULLEY GUARD FOR PROPER OPERATION AND GENERAL CONDITION. PARTICULAR ATTENTION SHOULD BE GIVEN TO THOSE AREAS OF CABLES THAT PASS OVER PULLEYS, SECTORS, OR THROUGH FAIRLEADS.						PKG		
	PKG 10	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
U2710006 (s)	RUDDER TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK. (REFER TO 27-20-02.)						PKG		
	PKG 18	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: AMM 27-20-02	AFL					4467		
U2710033 (s)	AILERON TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK.						PKG		
	PKG 16	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: AMM 27-10-04	AFL					4467		
U2710034 (s)	GENERAL VISUAL INSPECTION AILERON TRIM TAB INSTALLATION. (REFER TO 5-10-00.)						PKG		
	PKG 4	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
U2710035 (s)	GENERAL VISUAL INSPECTION PKG 6 REF: GENERIC NO REF	RUDDER TRIM TAB INSTALLATION. (REFER TO 5-10-00) MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
U2731050 (s)	VISUAL INSPECTION PKG 2 REF: GENERIC NO REF	ANGLE-OF-ATTACK VANES. (REFER TO 5-10-00) MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
W2700062 (s)	CHECK CONTROL CABLES UNDER FLOORBOARDS FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND SECURITY. CHECK PULLEYS, GUARDS, AND SAFETIES FOR PROPER OPERATION. (REFER TO 5-10-00.) PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		

CHAPTER 28 FUEL

05-10-29-L2812002L	C/W 24 MONTH LEFT INNER WING STRUCTURE OUTBOARD OF WS 213.602 INSPECTION IAW LEAR 60 M/M 05-10-29 MOS HRS/MSC AFL REF: GENERIC NO REF	24	+14d/-14d			05-OCT-2018 6634.6 4467	05-OCT-2020	19-OCT-2020
05-10-29-L2812002R	C/W 24 MONTH RIGHT INNER WING STRUCTURE OUTBOARD OF WS 213.602 INSPECTION IAW LEAR 60 M/M 05-10-29 MOS HRS/MSC AFL REF: GENERIC NO REF	24	+14d/-14d			05-OCT-2018 6634.6 4467	05-OCT-2020	19-OCT-2020
05-10-29-L2812010L	C/W 24 MONTH LEFT INNER WING BETWEEN WS 53.0 & 92.0 INSPECTION FOR CORROSION & BACTERIA IAW LEAR 60 M/M 05-10-29 MOS HRS/MSC AFL REF: GENERIC NO REF	24	+14d/-14d			05-OCT-2018 6634.6 4467	05-OCT-2020	19-OCT-2020

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-29-L2812010R	C/W 24 MONTH RIGHT INNER WING BETWEEN WS 53.0 & 92.0 INSPECTION FOR CORROSION & BACTERIA IAW LEAR 60 M/M 05-10-29	MOS HRS/MSC AFL	24	+14d/-14d			05-OCT-2018 6634.6 4467	05-OCT-2020	19-OCT-2020
	REF: GENERIC NO REF								
05-10-29-L2812020L	C/W 24 MONTH LEFT INNER WING, INBOARD OF WS 72 INSPECTION FOR CORROSION/CONDITION IAW LEAR 60 M/M 05-10-29	MOS HRS/MSC AFL	24	+14d/-14d			05-OCT-2018 6634.6 4467	05-OCT-2020	19-OCT-2020
	REF: GENERIC NO REF								
05-10-29-L2812020R	C/W 24 MONTH RIGHT INNER WING INBOARD OF WS 72 INSPECTION FOR CORROSION/CONDITION IAW LEAR 60 M/M 05-10-29	MOS HRS/MSC AFL	24	+14d/-14d			05-OCT-2018 6634.6 4467	05-OCT-2020	19-OCT-2020
	REF: GENERIC NO REF								
05-10-29-T2820012	CLEAN AND LEAK CHECK LOW PRESSURE FUEL FILTERS	MOS HRS/MSC AFL	-	TSI:0			16 0		
	REF: AMM 28-20-04								
05-11-00-G2820003	REPLACE ALL FUEL HOSE ASSEMBLIES (EXCLUDING ALL HOSES IN ENGINE NACELLE AREA) IN AIRCRAFT (PRESSURE)	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
TEFLON	REF: AMM 28-00-00								
280002	FUEL CONTROL SWITCH PANEL ASEMBLY	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
	PN SN-UNKNOWN REF: AMM 28-00-02								

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280003	LEFT WING DEFUEL VALVE 6600145-3 3898 REF: AMM 28-00-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
280004	RIGHT WING DEFUEL VALVE 6600145-3 3874 REF: AMM 28-00-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
280105	FUEL CONTROL OVERLAY ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281007	LEFT CHECK, CROSSFLOW VALVE 7600004-1 1032038 REF: AMM 28-14-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281008	RIGHT CHECK, CROSSFLOW VALVE 7600004-1 1032044 REF: AMM 28-14-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281201	AFT FUSELAGE FUEL CELL 6600501-003 88973 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281202	FORWARD FUSELAGE FUEL CELL 6600501-005 87826 REF: AMM 28-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281283	FUSELAGE DRAIN VALVE PN SN-UNKNOWN REF: AMM 28-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281301	LEFT WING FUEL VENT FLOAT VALVE 6600346-2 3912 REF: AMM 28-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281302	RIGHT WING FUEL VENT FLOAT VALVE 6600346-2 3755 REF: AMM 28-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281303	FUSELAGE FUEL VENT FLOAT VALVE 6600346-2 3935 REF: AMM 28-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281305	LEFT WING FLAME ARRESTOR PN SN-UNKNOWN REF: AMM 28-13-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281306	RIGHT WING FLAME ARRESTOR PN SN-UNKNOWN REF: AMM 28-13-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281307	LEFT FUEL CELL PRESSURE RELIEF VALVE PN SN-UNKNOWN REF: AMM 28-13-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281308	RIGHT FUEL CELL PRESSURE RELIEF VALVE PN SN-UNKNOWN REF: AMM 28-13-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281309	FUSELAGE FLAME ARRESTOR 9909018-101 455 REF: AMM 28-13-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281401	LEFT FUSELAGE CELL TRANSFER PUMP 2380060-50 C3662 REF: AMM 28-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281402	RIGHT FUSELAGE CELL TRANSFER PUMP 2380060-50 C3663 REF: AMM 28-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281403	LEFT INBOARD WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281404	RIGHT INBOARD WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281405	LEFT CENTER WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281406	RIGHT CENTER WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281407	LEFT OUTBOARD WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281408	RIGHT OUTBOARD WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281409	LEFT SCAVENGE PUMP 2380060-42 C3537 REF: AMM 28-14-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281410	RIGHT SCAVENGE PUMP 2380060-42 C3665 REF: AMM 28-14-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281411	LEFT FUEL TRANSFER VALVE 6600355-005 90406109 REF: AMM 28-14-04	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			26-AUG-2008 2508 1970		
281412	RIGHT FUEL TRANSFER VALVE 6600355-4 10815197 REF: AMM 28-14-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281413	CROSSFLOW VALVE PN SN-UNKNOWN REF: AMM 28-14-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281414	FUSELAGE HIGH-LEVEL FLOAT SWITCH L14F-94 261 REF: AMM 28-14-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281415	LEFT FUEL TRANSFER PRESSURE INDICATING SWITCH 7600002-3 1168 REF: AMM 28-14-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281416	RIGHT FUEL TRANSFER PRESSURE INDICATING SWITCH 7600002-3 1188 REF: AMM 28-14-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281417	LEFT WING HIGH-LEVEL FLOAT SWITCH L15H-8 11426 REF: AMM 28-14-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281418	RIGHT WING HIGH-LEVEL FLOAT SWITCH PN SN-UNKNOWN REF: AMM 28-14-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281419	LEFT WING LOW-LEVEL FLOAT SWITCH L15H-8 11502 REF: AMM 28-14-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281420	RIGHT WING LOW-LEVEL FLOAT SWITCH L15H-8 11573 REF: AMM 28-14-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
281421	FUEL FILL AND TRANSFER BOX PN SN-UNKNOWN REF: AMM 28-14-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282001	LEFT INBOARD JET PUMP PN SN-UNKNOWN REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282002	RIGHT INBOARD JET PUMP PN SN-UNKNOWN REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282003	LEFT STANDBY PUMP 2380060-49 C3809 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282004	RIGHT STANDBY PUMP 2380060-49 C3804 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282005	LEFT FUEL FILTER ASSEMBLY 6600488-4 1779 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282006	RIGHT FUEL FILTER ASSEMBLY 6600488-4 1790 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282007	LEFT ENGINE FUEL SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282008	RIGHT ENGINE FUEL SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282009	LEFT WING AND FUSELAGE MOTIVE FLOW SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282010	RIGHT WING AND FUSELAGE MOTIVE FLOW SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282011	LEFT ENGINE RELIEF VALVE 7600005-1 1081463 REF: AMM 28-20-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282012	RIGHT ENGINE RELIEF VALVE 7600005-1 10615167 REF: AMM 28-20-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282013	FUEL CONTROL RELAY PANEL PN SN-UNKNOWN REF: AMM 28-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282015	LEFT WING PILOT VALVE 2780610-102 1929 REF: AMM 28-20-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282016	RIGHT WING PILOT VALVE 2780610-102 2038 REF: AMM 28-20-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282017	LEFT WING REFUELING SHUTOFF VALVE 2780614-102 1305 REF: AMM 28-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282018	RIGHT WING REFUELING SHUTOFF VALVE 2780614-102 1301 REF: AMM 28-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282019	FUSELAGE PILOT VALVE 2780610-102 2048 REF: AMM 28-20-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282020	FUSELAGE VENT VALVE 2780612-103 815 REF: AMM 28-20-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282021	REFUELING CHECK VALVE 2780623-101 603 REF: AMM 28-20-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282022	FUSELAGE REFUELING SHUTOFF VALVE 2780624-102 770 REF: AMM 28-20-14	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282023	FUEL SOLENOID VALVE 2780613-101 0731 REF: AMM 28-20-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282024	PRESSURE REFUELING ADAPTER 2780609-101 783 REF: AMM 28-20-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282025	LEFT PRECHECK VALVE 2780615-102 1437 REF: AMM 28-20-17	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282026	RIGHT PRECHECK VALVE 2780615-102 1448 REF: AMM 28-20-17	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
282027	PRESSURE REFUELING CONTROL PANEL PN SN-UNKNOWN REF: AMM 28-20-18	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282050	RIGHT MOTIVE FLOW VALVE EM91-41 2110276 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-MAR-2010 3011.02 2287		
282050-02	R FUEL SHUTOFF VALVE 6600354-4 1080628 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
284001	LEFT INBOARD WING (MT5) FUEL PROBE 2326014-016 99030740 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C				24-MAR-2010 3011.02 2287		
284002	RIGHT INBOARD WING (MT6) FUEL PROBE 2326014-12 01010615 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
284003	LEFT OUTBOARD WING (MT7) FUEL PROBE 2326014-9 01032004 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
284004	RIGHT OUTBOARD WING (MT8) FUEL PROBE 2326014-9 02022101 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-FEB-2004 454 383		
284005	LEFT INBOARD WING EXTENSION STA 189 (MT9) FUEL PROBE 2826003-6 05031408 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-AUG-2005 1203.65 997		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284006	RIGHT INBOARD WING EXTENSION STA 189 (MT10) FUEL PROBE 2826003-6 00121189 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
284007	LEFT OUTBOARD WING EXTENSION STA 244 (MT11) FUEL PROBE PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
284008	RIGHT OUTBOARD WING EXTENSION STA 244 (MT12) FUEL PROBE 2826003-3 01041276 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
284009	FUSELAGE (MT18) FUEL PROBE 0118KTU01 018785 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
284011	LEFT ENGINE LOW FUEL PRESSURE SWITCH 7600002-2 3997 REF: AMM 28-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
284012	RIGHT ENGINE LOW FUEL PRESSURE SWITCH 7600002-2 3996 REF: AMM 28-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
284013	FUEL QUANTITY INDICATOR 6608529-001 203 REF: AMM 28-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B2813011 (s)	DEFUEL FUSELAGE FUEL CELL AND PERFORM FUEL CELL STATIC ELECTRICAL BONDING RESISTANCE CHECK. CHECK FUSELAGE FUEL CELL FOR CLEANLINESS. (REFER TO 28-12-00.)						PKG		
	PKG 25	MOS					25-NOV-2011		
		HRS/MSC					4140.97		
	REF: AMM 28-12-00	AFL	3000	+25/-25			2967		
C2820030 (s)	INSPECT FUEL SUPPLY LINE CHECK VALVE ORIFICES FOR CONDITION AND CLEANLINESS. (REFER TO 28-20-03.)						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014		
		HRS/MSC					5979.4		
	REF: AMM 28-20-03	AFL	6000	+25/-25			4026		
D2812030 (s)	WITH LOWER SURFACE ACCESS PLATES REMOVED, INSPECT INTERIOR AND EXTERIOR WING STRUCTURE FOR EVIDENCE OF FUEL LEAKAGE, FATIGUE CRACKS, LOOSE OR MISSING FASTENERS, BACTERIAL GROWTH, FILIFORM CORROSION, AND GENERAL CONDITION. INSPECT WING FLAPPER VALVES FOR F						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014		
		HRS/MSC					5979.4		
	REF: GENERIC NO REF	AFL	6000	+25/-25			4026		
E2820010 (s)	CLEAN AND LEAK CHECK LOW PRESSURE FUEL FILTERS. ON AIRCRAFT EQUIPPED WITH PAPER FILTERS, REMOVE AND REPLACE FILTERS. (REFER TO 28-20-04)						PKG		
	PKG 3	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: See Workcard	AFL					4467		
H2812060 (s)	OPERATIONAL CHECK OF WING LOW FUEL WARNING SYSTEM. (REFER TO 28-14-00.)						PKG		
	PKG 16	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: AMM 28-14-00	AFL					4467		
H2820020 (s)	PERFORM OPERATIONAL CHECK OF FUEL SUPPLY SHUTOFF VALVE AND HYDRAULIC SUPPLY SHUTOFF VALVES. (REFER TO 28-20-05 AND 29-10-01)						PKG		
	PKG 7	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: See Workcard	AFL					4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
N2814041 (s)	FUNCTIONAL TEST OF REDUNDANT FUEL VENT SYSTRM FUSELAGE TANK PRESSURE RELIEF VALVES. (REFER TO 28-13-07.)						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014		
		HRS/MSC					5979.4		
	REF:	AFL	6000	+25/-25			4026		
T2812070 (s)	OPERATIONAL CHECK OF FUEL CROSSFLOW VALVE AND MOTIVE FLOW CONTROL VALVES. (REFER TO 28-14-00 AND 28-20-00.)						PKG		
	PKG 22	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: See Workcard	AFL					3315		
T2814021 (s)	FUNCTIONAL TEST OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK PRESSURE RELIEF VALVES. (REFER TO 28-13-07.)						PKG		
	PKG 14	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: AMM 28-13-07	AFL					4467		
T2814039 (s)	FUNCTIONAL TEST OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK VACUUM RELIEF VALVES. (REFER TO 28-13-06.)						PKG		
	PKG 14	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: AMM 28-13-06	AFL					4467		
T2820001 (s)	VISUALLY INSPECT FUEL PLUMBING FOR ROUTING, CLEARANCE, LEAKS, SECURITY, AND GENERAL CONDITION. (REFER TO 5-10-00.) CHECK FUEL DRAINS FOR OPERATION.						PKG		
	PKG 15	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
T2820004 (s)	INSPECT LOWER INBOARD GEAR DOORS AND CHECK ENTIRE KEELBEAM AND WHEEL WELL AREA FOR FUEL OR HYDRAULIC LEAKS, PLUMBING FOR ROUTING, CLEARANCES, SECURITY OF CLAMPS, AND GENERAL CONDITION.						PKG		
	PKG 17	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Y2814041 (s)	PERFORM BENCH CHECK OF REDUNDANT FUEL VENT SYSTEM FUSELAGE TANK PRESSURE RELIEF VALVES. PKG 27	MOS	144	+14d/-14d			PKG 10-MAY-2002		
	REF: AMM 28-13-07	HRS/MSC AFL	6000	+25/-25			0 0		
CHAPTER 29 HYDRAULIC POWER									
05-11-00-G2900001	REPLACE HYDRAULIC HOSE ASSEMBLIES(EXCLUDING HOSES FOR THE LANDING GEAR AND THE HOSE ASSEMBLIES IN THE ENGINE NACELLE AREA)								
		MOS					10-MAY-2002		
TEFLON	REF:	HRS/MSC AFL	O/C				0 0		
290002	HYDRAULIC PRESSURE REGULATOR 55950-2 0281	MOS					21-JAN-2011 3529.52		
	REF: AMM 29-00-02	HRS/MSC AFL	O/C				2580		
290003	HYDRAULIC RESERVOIR PN SN-UNKNOWN	MOS			TSN:0		10-MAY-2002		
	REF: AMM 29-00-03	HRS/MSC AFL	O/C		TSN:0 TSN:0		0 0		
290005	PRESSURE REGULATOR CHECK VALVE PN SN-UNKNOWN	MOS			TSN:0		10-MAY-2002		
	REF: AMM 29-00-05	HRS/MSC AFL	O/C		TSN:0 TSN:0		0 0		
291001	LEFT ENGINE HYDRAULIC SUPPLY SHUTOFF VALVE 6600355-2 01104348	MOS			TSN:0		10-MAY-2002		
	REF: AMM 29-10-01	HRS/MSC AFL	O/C		TSN:0 TSN:0		0 0		
291002	RIGHT ENGINE HYDRAULIC SUPPLY SHUTOFF VALVE 6600355-2 01104339	MOS			TSN:0		10-MAY-2002		
	REF: AMM 29-10-01	HRS/MSC AFL	O/C		TSN:0 TSN:0		0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291003	LEFT ENGINE DRIVEN HYDRAULIC PUMP 66137 193813A REF: AMM 29-10-02	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-AUG-2011 3848.65 2794		
291004	RIGHT ENGINE DRIVEN HYDRAULIC PUMP 66137 (6607066-1) KO569AB REF: AMM 29-10-02	MOS HRS/MSC AFL	O/C				18-APR-2008 2369.37 1877		
291005	HYDRAULIC PRESSURE FILTER ASSEMBLY AD-3255-10Y13 N/A REF: AMM 29-10-03	MOS HRS/MSC AFL	O/C				18-APR-2008 2369.22 1877		
291006	HYDRAULIC RETURN FILTER ASSEMBLY AD-3258-10Y17 N/A REF: AMM 29-10-03	MOS HRS/MSC AFL	O/C				18-APR-2008 2369.22 1877		
291007	HYDRAULIC SYSTEM ACCUMULATOR 7629100004-001 8423-12172 REF: AMM 29-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			29-OCT-2010 3386.62 2502		
291008	HYDRAULIC THRUST REVERSER ACCUMULATOR MS28700-4 8424-15589 REF: AMM 29-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
291010	HYDRAULIC GROUND SERVICE PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291015	HYDRAULIC RELIEF VENT VALVE 2380103-1 10731168 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
291020	HYDRAULIC RESERVOIR RELIEF VALVE 5120T8TT20 10-09161110 REF: AMM 29-00-08	MOS HRS/MSC AFL	O/C	TSN:5 TSN:0 TSN:0			19-MAR-2011 3580.3 2618		
291220	THRUST REVERSER ISOLATION VALVE 6607070-1 266 REF: AMM 78-30-27	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
291225	HYDRAULIC PRESSURE RELIEF VALVE 1280 264 REF: AMM 29-00-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
292001	AUXILIARY HYDRAULIC PUMP 6600248-1 392 REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			25-JUN-2004 629 520		
293001	HYDRAULIC PRESSURE MT15 TRANSDUCER PN SN-UNKNOWN REF: AMM 29-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
293002	AUXILIARY HYDRAULIC PUMP PRESSURE SWITCH 730626 F1310 REF: AMM 29-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-JUL-2005 1189.3 984		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
293003	HYDRAULIC PRESSURE INDICATOR RC914UH09644 0097 REF: AMM 29-30-03	MOS HRS/MSC AFL	O/C				11-APR-2008 2360.78 1868		
293005	LEFT HYDRAULIC PUMP PRESSURE SWITCH 730635 808 REF: AMM 29-30-04	MOS HRS/MSC AFL	O/C				18-APR-2008 2369.37 1877		
293006	RIGHT HYDRAULIC PUMP PRESSURE SWITCH 730635 D999 REF: AMM 29-30-04	MOS HRS/MSC AFL	O/C	TSN:25 TSN:0 TSN:0			15-JUN-2012 4445.85 3150		
293010	HYDRAULIC SYSTEM PRESSURE GAUGE S218-2 1168 REF: AMM 29-30-05	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0			29-OCT-2010 3386.62 2502		
293015	THRUST REVERSER HYDRAULIC PRESSURE GAUGE S-218-2 1284 REF: AMM 29-30-05	MOS HRS/MSC AFL	O/C	TSN:53 TSO:0 TSN:1620 TSO:0 TSN:1761 TSO:0			09-FEB-2009 2623.7 2052		
H2910009 (s)	REMOVE AND CLEAN OR REPLACE AUXILIARY HYDRAULIC PUMP FILTER. (REFER TO 29-20-02.) PKG 15 REF: AMM 29-20-02	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
N2920000 (s)	FUNCTIONAL TEST THRUST REVERSER HYDRAULIC RETURN LINE CHECK VALVE. (REFER TO 78-30-03.) PKG 27 REF: AMM 29-10-05	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 02-SEP-2014 5979.4 4026		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P2910023 (s)	INSPECT HYDRAULIC RESERVOIR FILLER FILTER ELEMENT AND REPLACE IF REQUIRED. (REFER TO 29-00-04.) PKG 21	MOS	96	+14d/-14d			PKG 16-OCT-2012		
	REF: AMM 29-00-04	HRS/MSC AFL	2400	+25/-25			4757.3 3315		
Q2910019 (s)	REPLACE PRESSURE AND RETURN HYDRAULIC FILTER ELEMENTS. (REFER TO 29-10-03). PKG 9	MOS	24	+14d/-14d			PKG 05-OCT-2018		
	REF: AMM 29-10-03	HRS/MSC AFL	600	+25/-25			6634.6 4467		
S2900004 (s)	PERFORM A BENCH FUNCTIONAL TEST ON THE HYDRAULIC RESERVOIR PRESSURE RELIEF VALVE. (REFER TO 29-00-08.) PKG 15	MOS	48	+14d/-14d			PKG 05-OCT-2018		
	REF: AMM 29-00-08	HRS/MSC AFL	1200	+25/-25			6634.6 4467		
S2900005 (s)	PERFORM A BENCH FUNCTIONAL TEST ON THE HYDRAULIC RESERVOIR VACUUM RELIEF VALVE. (REFER TO 29-00-08.) PKG 15	MOS	48	+14d/-14d			PKG 05-OCT-2018		
	REF: AMM 29-00-08	HRS/MSC AFL	1200	+25/-25			6634.6 4467		
S2910008 (s)	REMOVE HYDRAULIC RESERVOIR REGULATOR FILTER, INSPECT AND CLEAN AS REQUIRED. INSPECT HYDRAULIC RESERVOIR CHECK VALVE AND PRESSURE REGULATOR FOR CONTAMINATION AND OPERATION. (REFER TO 29-00-01 AND 29-00-02.) PKG 15	MOS	48	+14d/-14d			PKG 05-OCT-2018		
	REF: See Workcard	HRS/MSC AFL	1200	+25/-25			6634.6 4467		
S2910025 (s)	REMOVE HYDRAULIC RESERVOIR PRESSURE REGULATOR FILTER, INSPECT AND CLEAN AS REQUIRED. INSPECT HYDRAULIC RESERVOIR CHECK VALVE AND PRESSURE REGULATOR FOR CONTAMINATION AND OPERATION. (REFER TO 29-00-01 AND 29-00-02.) PKG 9	MOS	24	+14d/-14d			PKG 05-OCT-2018		
	REF: See Workcard	HRS/MSC AFL	600	+25/-25			6634.6 4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T2900000 (s)	VISUALLY INSPECT HYDRAULIC PLUMBING FOR ROUTING, CLEARANCE, LEAKS, SECURITY, AND GENERAL CONDITION. (REFER TO 5-10-00.)						PKG		
	PKG 15	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
W2910024 (s)	INSPECT HYDRAULIC FILTERS (PRESSURE AND RETURN) DIFFERENTIAL PRESSURE INDICATORS FOR BYPASS INDICATION.						PKG		
	PKG 3	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: AMM 29-10-03	AFL					4467		
CHAPTER 30	ICE AND RAIN PROTECTION								
30-CUS-01 (s)	C/W 300HR HORIZONTAL STABILIZER HEATER BLANKETS INSPECTION								
		MOS					06-AUG-2015		
		HRS/MSC	300				6288.98		
CUSTOMER CODE	REF:	AFL					4196		
300001	COPILOT ELECTRICAL EQUIPMENT BOX								
	PN	MOS			TSN:0		10-MAY-2002		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 30-00-01	AFL			TSN:0		0		
301001	WING ANTI-ICE SHUTOFF AND PRESSURE REGULATING VALVE								
	6600259-3	MOS			TSO:43		23-AUG-2013		
	GWD35696	HRS/MSC	O/C		TSO:0		5370.27		
	REF: AMM 30-10-01	AFL			TSO:0		3666		
301002	WING RT10 ANTI-ICE TEMPERATURE SENSOR								
	PN	MOS			TSN:0		10-MAY-2002		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 30-10-02	AFL			TSN:0		0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301003	WING (SPARE 2RT10) ANTI-ICE TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
301004	WING (SPARE 3RT10) ANTI-ICE TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
301005	WING OVERHEAT WARNING THERMOSWITCH PN SN-UNKNOWN REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
301006	WING TEMPERATURE INDICATOR 6608210-32 573 REF: AMM 30-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
301007	LEFT WING ANTI-ICE BYPASS VALVE 1H95-8 3AP20 REF: AMM 30-10-05	MOS HRS/MSC AFL	O/C	TSO:14 TSO:0 TSO:0			23-AUG-2013 5370.27 3666		
301008	RIGHT WING ANTI-ICE BYPASS VALVE 1H95-8 12BB99 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:14 TSO:0 TSO:0			23-AUG-2013 5370.27 3666		
301009	LEFT WING BLEED AIR OVERHEAT SWITCH PN SN-UNKNOWN REF: AMM 30-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301010	RIGHT WING BLEED AIR OVERHEAT SWITCH PN SN-UNKNOWN REF: AMM 30-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
301011	WING UNDERHEAT WARNING SWITCH PN SN-UNKNOWN REF: AMM 30-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
301014	WING ANTI-ICE VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
301015	LEFT WING ANTI-ICE CHECK VALVE 1H95-8 12AN5 REF: AMM 30-10-08	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			03-AUG-2005 1202.68 996		
301016	RIGHT WING ANTI-ICE CHECK VALVE 1H95-8 8AT78 REF: AMM 30-10-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-OCT-2006 1806.22 1474		
301101	HORIZONTAL STABILIZER ANTI-ICE CONTROLLER 6608485-1 0133003 REF: AMM 30-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
301103	LEFT HORIZONTAL STABILIZER HEAT BLANKET (BOOT) 4065-3481 11-55268 REF: AMM 30-11-02	MOS HRS/MSC AFL	O/C	TSN:15 TSN:0 TSN:0			08-FEB-2013 4914.47 3412		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301104	RIGHT HORIZONTAL STABILIZER HEAT BLANKET (BOOT) PN SN-UNKNOWN REF: AMM 30-11-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			03-MAR-2011		
301109	CBR9 REMOTE CIRCUIT BREAKER SM600BA40A1 62775 REF: AMM 30-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
301110	CBR10 REMOTE CIRCUIT BREAKER SM600BA40A1 63170 REF: AMM 30-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
301111	CBR11 REMOTE CIRCUIT BREAKER SM600BA40A1 63206 REF: AMM 30-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
302101	LEFT NACELLE ANTI-ICE SHUTOFF VALVE 27441482-09 3AU23 REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSN:106 TSN:3580.3 TSN:2618			19-MAR-2011 3580.3 2618		
302102	RIGHT NACELLE ANTI-ICE SHUTOFF VALVE 27441482-09 7AU59 REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSN:106 TSN:3580.3 TSN:2618			19-MAR-2011 3580.3 2618		
302103	LEFT NACELLE ANTI-ICE PRESSURE SWITCH 7600020-1 3418TW REF: AMM 30-21-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
302104	RIGHT NACELLE ANTI-ICE PRESSURE SWITCH 7600020-1 3476TW REF: AMM 30-21-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
303001	LEFT PITOT HEAT MONITOR- 6608317-7 3101 REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
303002	RIGHT PITOT HEAT MONITOR- 6608317-7 3095 REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
303003	STANDBY PITOT HEAT MONITOR- 6608317-7 3103 REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
304001	WINDSHIELD ANTI-ICE SHUTOFF VALVE 6600201-1 2768 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
304002	WINDSHIELD ANTI-ICE MODULATING VALVE PN SN-UNKNOWN REF: AMM 30-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
304003	WINDSHIELD ANTI-ICE RAM AIR MODULATING VALVE 6600203-1 9AU57 REF: AMM 30-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304004	WINDSHIELD ANTI-ICE HEAT EXCHANGER 6600351-2 1069 REF: AMM 30-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
304005	WINDSHIELD ANTI-ICE TEMPERATURE SENSOR 6600203-7 4AU20 REF: AMM 30-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
304007	LEFT WINDSHIELD ANTI-ICE LOW-LIMIT (S83) THERMOSWITCH PN SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
304008	RIGHT WINDSHIELD ANTI-ICE LOW-LIMIT (S82) THERMOSWITCH PN SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
304009	LEFT WINDSHIELD ANTI-ICE HIGH-LIMIT (S85) THERMOSWITCH PN SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
304010	RIGHT WINDSHIELD ANTI-ICE HIGH-LIMIT (S84) THERMOSWITCH PN SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
304101	ALCOHOL SUPPLY TANK ASSEMBLY PN SN-UNKNOWN REF: AMM 30-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304102	ALCOHOL ANTI-ICE FLOAT SWITCH L14F-74 602 REF: AMM 30-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
304104	ALCOHOL PRESSURE RELIEF VALVE 6608260-3 1453 REF: AMM 30-41-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
304105	ANTI-ICE THREE-WAY SHUTOFF VALVE 6608258-2 1372 REF: AMM 30-41-05	MOS HRS/MSC AFL	O/C				09-OCT-2008 2574 2019		
304106	ALCOHOL ANTI-ICE SHUTOFF AND PRESSURE REGULATOR VALVE 6608257-1 1862A REF: AMM 30-41-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-SEP-2008 2554.33 2007		
304203	WINDSHIELD DEFOG RELAY BOX PN SN-UNKNOWN REF: AMM 30-42-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
308001	LEFT ICE DETECT LAMP PN SN-UNKNOWN REF: AMM 30-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
308002	RIGHT ICE DETECT LAMP PN SN-UNKNOWN REF: AMM 30-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
G3010001 (s)	OPERATIONAL CHECK WING ANTI-ICE CHECK VALVE. (REFER TO 30-10-08). PKG 9	MOS	24	+14d/-14d			PKG 05-OCT-2018		
	REF: AMM 30-10-08	HRS/MSC AFL	600	+25/-25			6634.6 4467		
H3020002 (s)	REMOVE INLET COWL ACCESS PANEL. VISUALLY INSPECT ANTI-ICE PLUMBING CONNECTOR FOR CONDITION, SECURITY, AND EVIDENCE OF LEAKAGE. (REFER TO 5-10-00) PKG 9	MOS	24	+14d/-14d			PKG 05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			6634.6 4467		
H3020003 (s)	REMOVE UPPER ENGINE ACCESS COWL AND PERFORM A VISUAL INSPECTION OF NACELLE ANTI-ICE PLUMBING AND ALOCHOL PRESSURE LINE. (REFER TO 5-10-00) PKG 9	MOS	24	+14d/-14d			PKG 05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			6634.6 4467		
T3040004 (s)	INSPECT WINDSHIELD DEFOG DUCTS AND EXTERNAL OUTLETS FOR SECURITY, CONTOUR, AND INTEGRITY OF SEALANT TO WINDSHIELD. CHECK THAT THE EXTERNAL ANTI-ICE NOZZLES ARE CLEAR OF OBSTRUCTIONS. PKG 14	MOS	48	+14d/-14d			PKG 05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25			6634.6 4467		
T3040008 (s)	FUNCTIONAL TEST OF WINDSHIELD ANTI-ICE SYSTEM TIMER CIRCUIT. (REFER TO 30-40-00.) PKG 19	MOS	96	+14d/-14d			PKG 16-OCT-2012		
	REF: AMM 30-40-00	HRS/MSC AFL	2400	+25/-25			4757.3 3315		
T3050003 (s)	OPERATIONAL CHECK OF ALCOHOL ANTI-ICE SYSTEM. (REFER TO 30-41-00.) PKG 14	MOS	48	+14d/-14d			PKG 05-OCT-2018		
	REF: AMM 30-41-00	HRS/MSC AFL	1200	+25/-25			6634.6 4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T3050009 (s)	CLEAN ALCOHOL ANTI-ICE FILTER ELEMENT. REPLACE FILTER ELEMENT IF MADE OF PAPER. (REFER TO 30-41-03.) PKG 14	MOS	48	+14d/-14d			05-OCT-2018		
	REF: AMM 30-41-03	HRS/MSC AFL	1200	+25/-25			6634.6 4467		
U3020001A (s)	INSPECT NO. 1 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION PKG 29	MOS					22-MAR-2016		
	REF:	HRS/MSC AFL	3600	+50			6382.8 4275		
U3020001B (s)	INSPECT NO. 2 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION PKG 30	MOS					22-MAR-2016		
	REF:	HRS/MSC AFL	3600	+50			6382.8 4275		
CHAPTER 31	INDICATING/RECORDING SYSTEMS								
312001	PILOT CREW CLOCK MN1500 MAR2014 REF: AMM 31-21-01	MOS HRS/MSC AFL					29-JUL-2008		
			O/C		TSN:0 TSN:0 TSN:0		2474.13 1953		
312002	COPILOT CREW CLOCK MN1500 MAR2014 REF: AMM 31-21-01	MOS HRS/MSC AFL					29-JUL-2008		
			O/C		TSN:0 TSN:0 TSN:0		2474.13 1953		
312011	C/W 24 MONTH PILOT CREW CLOCK BATTERY REPLACEMENT IAW LEAR 60 M/M 31-21-01 AL-AA ENERGIZER NA REF: CMM STANDARD AND OPTIONAL FEATURES	MOS HRS/MSC AFL	24				05-FEB-2019	05-FEB-2021	
					TSN:0 TSN:0 TSN:0		6735 4497		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
312012	C/W 24 MONTH CO-PILOT CREW CLOCK BATTERY REPLACEMENT IAW LEAR 60 M/M 31-21-01 AL-AA ENERGIZER NA REF: CMM STANDARD AND OPTIONAL FEATURES	MOS HRS/MSC AFL	24	TSN:0 TSN:0 TSN:0			05-FEB-2019 6735 4497	05-FEB-2021	
313001	FLIGHT DATA (FDR) RECORDER 2100-2042-00 000179776 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
313018	FDR INERTIA SWITCH 3L0-453/8 L10489 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
313103	MULTI-AXIAL ACCELEROMETER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
314002	IAPS CARD CAGE 822-0269-001 HTFV REF: AMM 31-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
314011	1A PWR-851A POWER SUPPLY CARD PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
314012	2A PWR-851A POWER SUPPLY CARD PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
314013	1B PWR-851A POWER SUPPLY CARD PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
314014	2B PWR-851A POWER SUPPLY CARD PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
314021	1A FLIGHT CONTROL CARD PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
314022	2A FLIGHT CONTROL CARD 822-0592-407 445 REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			16-OCT-2009 2734.47 2132		
314031	1B FLIGHT MANAGEMENT - FMC 851C CARD PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
314032	2B FLIGHT MANAGEMENT - FMC 851C CARD PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
314033	1B FLIGHT MANAGEMENT - FMC 852C CARD PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
314034	2B FLIGHT MANAGEMENT - FMC 852C CARD PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
314063	NO. 1 INPUT/OUTPUT CHANNEL A 851A CARD 622-9343-234 HRJN REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			25-OCT-2006 1806.22 1474		
314064	NO. 2 INPUT/OUTPUT CHANNEL A 851A CARD 622-9343-234 HRJP REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			25-OCT-2006 1806.22 1474		
314065	NO. 1 INPUT/OUTPUT CHANNEL B 851A CARD 622-9343-234 H63T REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			25-OCT-2006 1806.22 1474		
314066	NO. 2 INPUT/OUTPUT CHANNEL B 851A CARD 622-9343-234 J9VL REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			25-OCT-2006 1806.22 1474		
314101	DATA ACQUISITION UNIT PN SN-UNKNOWN REF: AMM 31-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
315101	AURAL WARNING CONTROL UNIT 6608108-2 2194 REF: AMM 31-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
315102	TONE GENERATOR PN SN-UNKNOWN REF: AMM 31-51-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
315103	AURAL WARNING MIXER 1882-1 571 REF: AMM 31-51-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
315201	GLARESHIELD ANNUNCIATOR PANEL 6608482-1 0137050 REF: AMM 31-52-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
315203	MASTER CAUTION/WARNING TRIGGER UNIT ASSEMBLY PN SN-UNKNOWN REF: AMM 31-52-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
316001	PILOT EFD-871 ELECTRONIC FLIGHT DISPLAY 622-9345-026 5ACM REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			26-SEP-2005 1264.37 1048		
316001-01	ELECTRONIC FLIGHT (PFD) DISPLAY 622-9345-026 HF9Y REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-NOV-2006 1814.1 1484		
316003	MULTIFUNCTION DISPLAY 622-9434-026 YYX REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
316004	MULTIFUNCTION DISPLAY 622-9434-026 276WH REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			01-JUN-2008 2409.07 1909		
316005	PILOT EFIS CONTROL PANEL PN SN-UNKNOWN REF: AMM 31-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
316006	COPILOT EFIS CONTROL PANEL PN SN-UNKNOWN REF: AMM 31-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
316011	NO. 1 DISPLAY IMT-871 TRAY 822-0278-001 GX2L REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
316012	NO. 2 DISPLAY IMT-871 TRAY 822-0278-001 GX2H REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
316013	NO. 3 DISPLAY IMT-871 TRAY 822-0278-001 GX2K REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
316014	NO. 4 DISPLAY IMT-871 TRAY 822-0278-001 GX2J REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
316101	SENSOR DISPLAY UNIT PN SN-UNKNOWN REF: AMM 31-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
316102	SENSOR DISPLAY DRIVER UNIT PN SN-UNKNOWN REF: AMM 31-61-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
316201	NO. 1 FILE SERVER (FSU) UNIT PN SN-UNKNOWN REF: AMM 31-61-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
316202	NO. 2 FILE SERVER (FSU) UNIT PN SN-UNKNOWN REF: AMM 31-61-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
316203	NO. 1 FILE SERVER EXTERNAL COMPENSATION UNIT (ECU-3000) PN SN-UNKNOWN REF: AMM 31-62-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
316204	NO. 2 FILE SERVER EXTERNAL COMPENSATION UNIT (ECU-3000) PN SN-UNKNOWN REF: AMM 31-62-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
317021	FDR UNDERWATER LOCATOR (ULB) BEACON DK120 SD04478 REF: AMM 25-63-00	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			05-OCT-2018 6634.6 4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
317021A	C/W 24 MONTH ULB CLEANING/FUNCTIONAL TEST IAW DUKANE CMM AND LEAR 60 M/M 05-10-29-F2565000 DK120 SD04478 REF: See Workcard	MOS HRS/MSC AFL	24	+14d/-14d			05-OCT-2018 6634.6 4467	05-OCT-2020	19-OCT-2020
317021B	REPLACE FDR UNDERWATER LOCATOR (ULB) BEACON BATTERY - 05-11-00-F2566000 DK120 SD04478 REF:	MOS HRS/MSC AFL	DUE				05-OCT-2018 6634.6 4467	01-APR-2024 M	
P3151001 (s)	PERFORM OPERATIONAL CHECK OF THE AUTOPILOT AURAL WARNING. (REFER TO 31-51-00) (EFFECTIVE ON AIRCRAFT 60-307, 60-319 AND SUBSEQUENT) PKG 1 REF: AMM 31-51-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			05-OCT-2018 6634.6 4467	PKG	
P3160001 (s)	PERFORM OPERATIONAL CHECK OF THE ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS). (REFER TO 31-60-03) PKG 7 REF: AMM 31-60-03	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			05-OCT-2018 6634.6 4467	PKG	
T3110000 (s)	INSPECT EQUIPMENT INSTALLATIONS BETWEEN FORWARD PRESSURE BULKHEAD AND INSTRUMENT PANEL FOR SECURITY OF MOUNTING, WIRE ROUTING, AND CLEARANCES OF WIRING AND PLUMBING. PKG 19 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			16-OCT-2012 4757.3 3315	PKG	
U3100001 (s)	GENERAL VISUAL INSPECTION INSTRUMENT PANEL (REFER TO 5-10-00.) PKG 1 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			05-OCT-2018 6634.6 4467	PKG	

CHAPTER 32 LANDING GEAR

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E3211066	C/W 6000 LANDING NLG ACTUATOR BOLT REPLACEMENT IAW LEAR 60 M/M 32-32-01 - (6042007-4)	MOS HRS/MSC AFL	6000	+25/-25			10-MAY-2002 0 0	6000	6025
	REF: AMM 32-32-01								
05-11-00-E3211074L	C/W 3000 LANDING LEFT MLG UPPER BEARINGS REPLACEMENT IAW LEAR 60 M/M 32-11-00 - (6041104)	MOS HRS/MSC AFL	3000				15-JUN-2012 4140.97 2967	5967	
LIFE LIMIT	REF: AMM 32-11-00								
05-11-00-E3211074R	C/W 3000 LANDING RIGHT MLG UPPER BEARINGS REPLACEMENT IAW LEAR 60 M/M 32-11-00 - (6041104)	MOS HRS/MSC AFL	3000				15-JUN-2012 4140.97 2967	5967	
LIFE LIMIT	REF: AMM 32-11-00								
05-11-00-E3211084L	C/W 20000 LANDING LEFT MLG ACTUATOR ATTACH PIN REPLACEMENT IAW LEAR 60 M/M 32-11-00 - (5441101)	MOS HRS/MSC AFL	20000				10-MAY-2002 0 0	20000	
LIFE LIMIT	REF: AMM 32-11-00								
05-11-00-E3211084R	C/W 20000 LANDING RIGHT MLG ACTUATOR ATTACH PIN REPLACEMENT IAW LEAR 60 M/M 32-11-00 - (5441101)	MOS HRS/MSC AFL	20000				10-MAY-2002 0 0	20000	
LIFE LIMIT	REF: AMM 32-11-00								
05-11-00-E3211090L	C/W 3000 LANDING LEFT MLG UPPER BEARING RETENTION PIN REPLACEMENT IAW LEAR 60 M/M 32-11-00 - (6041110-1)	MOS HRS/MSC AFL	3000				25-NOV-2011 4140.97 2967	5967	
LIFE LIMIT	REF: AMM 32-11-00								
05-11-00-E3211090R	C/W 3000 LANDING RIGHT MLG UPPER BEARING RETENTION PIN REPLACEMENT IAW LEAR 60 M/M 32-11-00 - (6041110-1)	MOS HRS/MSC AFL	3000				25-NOV-2011 4140.97 2967	5967	
LIFE LIMIT	REF: AMM 32-11-00								

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-E3211092L	C/W 6000 LANDING LEFT MLG UPPER BEARING REPLACEMENT IAW LEAR 60 M/M 32-11-00 - (7600839)	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	6000				0 0		6000
05-11-00-E3211092R	C/W 6000 LANDING RIGHT MLG UPPER BEARING REPLACEMENT IAW LEAR 60 M/M 32-11-00 - (7600839)	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	6000				0 0		6000
05-11-00-E3211093L	C/W 6000 LANDING LEFT MLG LOWER BEARING REPLACEMENT IAW LEAR 60 M/M 32-11-00 - (6041105)	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	6000				0 0		6000
05-11-00-E3211093R	C/W 6000 LANDING RIGHT MLG LOWER BEARING REPLACEMENT IAW LEAR 60 M/M 32-11-00 - (6041105)	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	6000				0 0		6000
05-11-00-G3210003	REPLACE HYDRAULIC HOSE ASSEMBLIES ATTACHED TO THE MAIN AND NOSE GEAR ACTUATORS, MAIN GEAR DOOR ACTUATORS, AND THE MAIN AND NOSE GEAR UPLATCH ACTUATOR	MOS					02-FEB-2010		
TEFLON	REF:	HRS/MSC AFL	O/C				2929.12 2246		
05-11-00-G3233007	REPLACE EMERGENCY AIR HOSE ASSEMBLIES FOR LANDING GEAR EMERGENCY FREEFALL EXTENSION, LANDING GEAR EMERGENCY BLOWDOWN, AND EMERGENCY BRAKING SYSTEMS	MOS					10-MAY-2002		
TEFLON	REF:	HRS/MSC AFL	O/C				0 0		
05-11-00-G3243040	REPLACE HYDRAULIC BRAKE HOSE ASSEMBLIES LOCATED ON THE STRUT AND IN WHEEL WELL AREA	MOS					29-MAY-2007		
TEFLON	REF:	HRS/MSC AFL	O/C				2056.55 1653		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-U3211091L	C/W 6000 LANDING LEFT MLG UPPER BEARING RETENTION PIN REPLACEMENT IAW LEAR 60 M/M 32-11-00 - (6041110-002 AND SUBSEQUENT)	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	6000				0 0		6000
05-11-00-U3211091R	C/W 6000 LANDING RIGHT MLG UPPER BEARING RETENTION PIN REPLACEMENT IAW LEAR 60 M/M 32-11-00 - (6041110-002 AND SUBSEQUENT)	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	6000				0 0		6000
321001	C/W 16500 LANDING LEFT MLG STRUT ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 32-11-00	MOS		TSN:0			10-MAY-2002		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL APH ACH	16500	TSN:0 TSN:0 TSN:0			0 0		16500
321002	C/W 16500 LANDING RIGHT MLG STRUT ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 32-11-00	MOS		TSN:0			10-MAY-2002		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL APH ACH	16500	TSN:0 TSN:0 TSN:0			0 0		16500
321003	C/W 6000 LANDING LEFT MLG SHOCK STRUT UPPER TORQUE ARM REPLACEMENT IAW LEAR 60 M/M 32-11-01	MOS		TSN:0			10-MAY-2002		
AIRWORTHINESS	REF: AMM 32-11-01	HRS/MSC AFL	6000	TSN:0 TSN:0 TSN:0			0 0		6000
321004	C/W 6000 LANDING RIGHT MLG SHOCK STRUT UPPER TORQUE ARM REPLACEMENT IAW LEAR 60 M/M 32-11-01	MOS		TSN:0			10-MAY-2002		
AIRWORTHINESS	REF: AMM 32-11-01	HRS/MSC AFL	6000	TSN:0 TSN:0 TSN:0			0 0		6000

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321005	C/W 6000 LANDING LEFT MLG SHOCK STRUT LOWER TORQUE ARM REPLACEMENT IAW LEAR 60 M/M 32-11-01								
	PN	MOS		TSN:0			10-MAY-2002		
	SN-UNKNOWN	HRS/MSC		TSN:0			0		
AIRWORTHINESS	REF: AMM 32-11-01	AFL	6000	TSN:0			0		6000
321006	C/W 6000 LANDING RIGHT MLG SHOCK STRUT LOWER TORQUE ARM REPLACEMENT IAW LEAR 60 M/M 32-11-01								
	PN	MOS		TSN:0			10-MAY-2002		
	SN-UNKNOWN	HRS/MSC		TSN:0			0		
AIRWORTHINESS	REF: AMM 32-11-01	AFL	6000	TSN:0			0		6000
321011	LEFT MAIN LANDING GEAR PISTON ASSEMBLY								
	PN	MOS		TSN:0			10-MAY-2002		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-11-00	AFL		TSN:0			0		
321012	RIGHT MAIN LANDING GEAR PISTON ASSEMBLY								
	PN	MOS		TSN:0			10-MAY-2002		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-11-00	AFL		TSN:0			0		
321013	LEFT MAIN LANDING GEAR AXLE								
	PN	MOS		TSN:0			10-MAY-2002		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-11-00	AFL		TSN:0			0		
321014	RIGHT MAIN LANDING GEAR AXLE								
	PN	MOS		TSN:0			10-MAY-2002		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-11-00	AFL		TSN:0			0		
321501	LEFT HYDRAULIC, GEAR RETRACTION RESTRICTOR								
	1R3665-035	MOS		TSN:0			10-MAY-2002		
	D7037	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-31-04	AFL		TSN:0			0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321502	RIGHT HYDRAULIC, GEAR RETRACTION RESTRICTOR 1R3665-035 D7037. REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
321511	LEFT HYDRAULIC, GEAR EXTENSION RESTRICTOR 1R3665-051 D3372 REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
321512	RIGHT HYDRAULIC, GEAR EXTENSION RESTRICTOR 1R3665-051 D3551 REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
321515	LEFT HYDRAULIC RESTRICTOR 1R3665-035 06952 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
321516	RIGHT HYDRAULIC RESTRICTOR 1R3665-059 02163 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
322001	C/W 10000 LANDING NOSE GEAR STRUT ASSEMBLY REPLACEMENT IAW LEAR 60 M/M 32-21-00 2342100-030 045 REF: AMM 32-21-00	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		10000
322002	C/W 10000 LANDING NLG & STEERING ASSEMBLY STRUT REPLACEMENT IAW LEAR 60 M/M 04-11-00 2342003-090 L-045 REF: GENERIC NO REF	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		10000

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323019	LEFT MAIN LANDING GEAR SQUAT SWITCH 426EN9-8 SN-UNKNOWN REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C	TSN:19			08-AUG-2013 5328.85 3646		
323020	RIGHT MAIN LANDING GEAR SQUAT SWITCH PN SN-UNKNOWN REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
323031	C/W 20000 LANDING LEFT MLG ACTUATOR REPLACEMENT IAW LEAR 60 M/M 32-31-01 6600264-003 054 REF: AMM 32-31-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			01-NOV-2004 790.8 662	20662	
LIFE LIMIT									
323032	C/W 20000 LANDING RIGHT MLG ACTUATOR REPLACEMENT IAW LEAR 60 M/M 32-31-01 6600264-003 055 REF: AMM 32-31-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			01-NOV-2004 790.8 662	20662	
LIFE LIMIT									
323043	LEFT MAIN LANDING GEAR INBOARD GEAR DOOR ACTUATOR 6600085-9 0154 REF: AMM 32-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
323044	RIGHT MAIN LANDING GEAR INBOARD GEAR DOOR ACTUATOR 6600085-9 0157 REF: AMM 32-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
323052	LANDING GEAR CONTROL PANEL ASSEMBLY PN SN-UNKNOWN REF: AMM 32-30-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323055	LEFT UPLOCK, MAIN LANDING GEAR INBOARD DOOR ACTUATOR 2417016-1 5543 REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
323056	RIGHT UPLOCK, MAIN LANDING GEAR INBOARD DOOR ACTUATOR 2417016-1 6815 REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			14-JUN-2013 5195.02 3575		
323057	LEFT UPLOCK, MAIN LANDING GEAR INBOARD DOOR FREEFALL ACTUATOR 2417016-1 5544 REF: AMM 32-33-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
323058	RIGHT UPLOCK, MAIN LANDING GEAR INBOARD DOOR FREEFALL ACTUATOR 2417016-1 6759 REF: AMM 32-33-04	MOS HRS/MSC AFL	O/C	TSN:11 TSN:0 TSN:0			23-AUG-2013 5370.27 3666		
323073	C/W 10000 LANDING NLG ACTUATOR REPLACEMENT IAW LEAR 60 M/M 32-32-01 2317100-016 KL0025 REF: AMM 32-32-01	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		10000
323079	NOSE LANDING GEAR UPLOCK ACTUATOR 2417016-1 6307 REF: AMM 32-32-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-OCT-2012 4757.3 3315		
323080	UPLOCK, NOSE LANDING GEAR FREEFALL ACTUATOR 2417016-1 5533 REF: AMM 32-33-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323098	GEAR DOOR CONTROL VALVE 6600361-1 1309 REF: AMM 32-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
323099	SELECT, LANDING GEAR VALVE 48C48641 1601 REF: AMM 32-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
323105	NOSE LANDING GEAR SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
323110	NOSE LANDING GEAR UPLATCH SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
323205	LEFT MAIN LANDING GEAR EXTEND SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
323210	RIGHT MAIN LANDING GEAR EXTEND SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
323222	C/W 20000 LANDING LEFT MLG ACTUATOR ATTACH PILLAR REPLACEMENT IAW LEAR 60 M/M 32-31-05 2341123-023 SN-UNKNOWN REF: AMM 32-31-05	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
LIFE LIMIT			20000	TSN:0			0		20000

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323223	C/W 20000 LANDING RIGHT MLG ACTUATOR ATTACH PILLAR REPLACEMENT IAW LEAR 60 M/M 32-31-05 2341123-023 SN-UNKNOWN	MOS HRS/MSC		TSN:0 TSN:0			10-MAY-2002 0		
LIFE LIMIT	REF: AMM 32-31-05	AFL	20000	TSN:0			0	20000	
323305	LEFT MAIN LANDING GEAR DOOR SHUTTLE VALVE PN SN-UNKNOWN	MOS HRS/MSC	O/C	TSN:0 TSN:0			10-MAY-2002 0		
	REF: See Workcard	AFL		TSN:0			0		
323310	RIGHT MAIN LANDING GEAR DOOR SHUTTLE VALVE PN SN-UNKNOWN	MOS HRS/MSC	O/C	TSN:0 TSN:0			10-MAY-2002 0		
	REF: AMM 32-00-01	AFL		TSN:0			0		
323315	LEFT MAIN LANDING GEAR DOOR UPLATCH SHUTTLE VALVE PN SN-UNKNOWN	MOS HRS/MSC	O/C	TSN:0 TSN:0			10-MAY-2002 0		
	REF: AMM 32-00-01	AFL		TSN:0			0		
323320	RIGHT MAIN LANDING GEAR DOOR UPLATCH SHUTTLE VALVE PN SN-UNKNOWN	MOS HRS/MSC	O/C	TSN:0 TSN:0			10-MAY-2002 0		
	REF: AMM 32-00-01	AFL		TSN:0			0		
323401	AFT EMERGENCY GEAR BLOWDOWN EXTENSION VALVE 6600078-6 2204	MOS HRS/MSC	O/C	TSN:0 TSN:0			10-MAY-2002 0		
	REF: AMM 32-33-02	AFL		TSN:0			0		
323402	FORWARD EMERGENCY GEAR FREEFALL EXTENSION VALVE 6600078-6 2271	MOS HRS/MSC	O/C	TSN:0 TSN:0			10-MAY-2002 0		
	REF: AMM 32-33-03	AFL		TSN:0			0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323405	LEFT CHECK, FREEFALL VALVE 7600833-001 0266 REF: AMM 32-33-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
323406	RIGHT CHECK, FREEFALL VALVE PN SN-UNKNOWN REF: AMM 32-33-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
323409	UPPER EMERGENCY GEAR EXTENSION RESTRICTOR 6R7742S-0135 4666 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
323410	LOWER EMERGENCY GEAR EXTENSION RESTRICTOR 6R7742S-0135 4668 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
323430	NO. 1 EMERGENCY AIR BLOWDOWN SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
324001	NOSE TIRE 031-613-8 5034S00361 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			08-JUL-2016 6419 4301		
324007	ASSEMBLY, NOSE WHEEL 9544207 MAY05-10003 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				13-JUL-2015 6260.78 4182		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324013	NO. 1 MAIN LANDING GEAR TIRE 178K43-1 62032863 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2018 6634.6 4467		
324014	NO. 2 MAIN LANDING GEAR TIRE 178K43-1 62012461 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2018 6634.6 4467		
324015	NO. 3 MAIN LANDING GEAR TIRE 178K43-1 80613034 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-MAR-2019 6784.5 4527		
324016	NO. 4 MAIN LANDING GEAR TIRE 178K43-1 90072470 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-MAR-2019 6784.5 4527		
324037	NO. 1 MAIN LANDING GEAR WHEEL 5011740 FEB01-1574/JUN01- REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				05-OCT-2018 6634.6 4467		
324038	NO. 2 MAIN LANDING GEAR WHEEL 5011740 JUL96-2891/MAY99-1111 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				05-OCT-2018 6634.6 4467		
324039	NO. 3 MAIN LANDING GEAR WHEEL 5011740 NOV00-1491 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			27-MAR-2019 6784.5 4527		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324040	NO. 4 MAIN LANDING GEAR WHEEL 5011740 SEP07-2625 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			27-MAR-2019 6784.5 4527		
324048	NO. 1 ASSEMBLY, MAIN LANDING GEAR BRAKE 90002424-2 MAY09-1169 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSO:2 TSO:0 TSO:0			29-SEP-2014 5979.4 4026		
324049	NO. 2 ASSEMBLY, MAIN LANDING GEAR BRAKE 90002424-2 MAY09-1168 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSO:2 TSO:0 TSO:0			29-SEP-2014 5979.4 4026		
324050	NO. 3 ASSEMBLY, MAIN LANDING GEAR BRAKE 90002424-2 APR08-0918 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSO:2 TSO:0 TSO:0			29-SEP-2014 5979.4 4026		
324051	NO. 4 ASSEMBLY, MAIN LANDING GEAR BRAKE 90002424-2 NOV09-0031 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSO:2 TSO:0 TSO:0			29-SEP-2014 5979.4 4026		
324061	NO. 1 POWER BRAKE, PILOTS VALVE 3321200-2 1706 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
324062	NO. 2 POWER BRAKE, PILOTS VALVE 3321200-2 1707 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324063	NO. 1 POWER BRAKE, COPILOTS VALVE 3321200-2 1719 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
324064	NO. 2 POWER BRAKE, COPILOTS VALVE 3321200-2 1755 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
324085	NO. 1 HYDRAULIC, BRAKE FUSE 2380114-1 6901 REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
324086	NO. 2 HYDRAULIC, BRAKE FUSE 2380114-1 6902 REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
324109	NO. 3 HYDRAULIC, BRAKE FUSE 2380114-1 6519 REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			18-JAN-2013 4898.73 3402		
324133	AFT PARKING BRAKE VALVE 6600392-2 1090 REF: AMM 32-41-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
324134	FWD PARKING BRAKE VALVE 6600392-2 1222 REF: AMM 32-41-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324145	NO. 1 WHEEL SPEED TRANSDUCER 40-911 7177 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
324146	NO. 2 WHEEL SPEED TRANSDUCER 40-911 6934 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C				25-DEC-2011 4179.47 2988		
324147	NO. 3 WHEEL SPEED TRANSDUCER 40-911 7170 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C				25-DEC-2011 4179.47 2988		
324148	NO. 4 WHEEL SPEED TRANSDUCER 40-911 7244 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
324169	LEFT ANTI-SKID VALVE 39-309-4 2094 REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C				16-OCT-2012 4757.3 3315		
324170	RIGHT ANTI-SKID VALVE 39-309-2 2474 REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			24-FEB-2004 463 388		
324175	ANTI-SKID CONTROL 42-379-1 1834B REF: AMM 32-42-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324413	PARK BRAKE ANNUNCIATOR BOX ASSEMBLY PN SN-UNKNOWN REF: AMM 32-42-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
324501	EMERGENCY BRAKE CONTROL VALVE 63500-2 452A REF: AMM 32-43-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
325001	NOSE WHEEL STEERING ACTUATOR 6608468-8 1204 REF: AMM 32-50-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
325005	NOSE WHEEL STEERING COMPUTER 501-1708-03 80045 REF: AMM 32-50-04	MOS HRS/MSC AFL	O/C				08-FEB-2013 4914.47 3412		
325015	LEFT RUDDER POSITION SENSOR 501-1123-03 6792 REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
325016	RIGHT RUDDER POSITION SENSOR 501-1123-03 6568 REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
325019	NOSE WHEEL STEERING ACTUATOR GEARBOX 3142020-3 263 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
325020	NOSE WHEEL STEERING FOLLOW UP ASSEMBLY PN SN-UNKNOWN REF: AMM 32-50-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
325024	RIGHT NOSE WHEEL STEERING FOLLOWUP 6608288-003 5372 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	TSN:11 TSN:0 TSN:0			08-FEB-2013 4914.47 3412		
325025	LEFT NOSE WHEEL STEERING FOLLOWUP 6608288-003 5383 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	TSN:14 TSN:0 TSN:0			08-FEB-2013 4914.47 3412		
325628	AFT EMERGENCY GEAR CONTROL VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
326011	SQUAT SWITCH RELAY BOX PN SN-UNKNOWN REF: AMM 32-30-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
AA3211058 (s)	COMPLETELY DISASSEMBLE MAIN LANDING GEAR STRUTS AND ACTUATORS. REMOVE AXLES AND PISTONS FROM HUBS. CONDUCT VISUAL INSPECTION OF ALL COMPONENTS. DETERMINE EXTENT OF WEAR BY MAKING THE REQUIRED DIMENSIONAL CHECKS. CONDUCT FLUORESCENT PENETRANT OR MAGNETIC PARTICLE INSPECTION OF ALL COMPONENTS. PAY PARTICULAR ATTENTION TO THE MAIN GEAR UPPER TRUNNION AREAS AND LOWER GLAND NUT OF THE CYLINDER FORGING FOR CRACKS. PKG 26 REF: NDT 32-13-01	MOS HRS/MSC AFL	6000	+25/-25			PKG 10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C3211040 (s)	CLEAN AND EDDY CURRENT INSPECT UPPER CYLINDER. (SEE FIGURE 1.) (REFER TO NDI MANUAL [NDI-2], PART 3, 32-40-02.) PKG 26 REF: NDT 32-40-02	MOS HRS/MSC AFL	6000	+25/-25			10-MAY-2002 0 0		
C3211050 (s)	DEFLATE STRUTS AND STROKE FROM FULLY EXTENDED TO FULLY COMPRESSED POSITIONS. NOTE BINDING TENDENCIES DURING STROKING, PARTICULARLY NEAR THE FULLY COMPRESSED POSITION. PKG 26 REF: GENERIC NO REF	MOS HRS/MSC AFL	6000	+25/-25			10-MAY-2002 0 0		
C3231030 (s)	INSPECT INBOARD ATTACHMENT OF MAIN GEAR ACTUATOR FOR SECURITY, LOOSENESS, OVERLOAD INDICATIONS, AND FATIGUE CRACKS. THE PILLAR ATTACHMENTS TO SPARS 7 AND 8 ARE TO BE SPECIFICALLY INSPECTED FOR DISCREPANT CONDITIONS. PILLAR REMOVAL IS REQUIRED TO FACILITATE DEFINI PKG 26 REF: GENERIC NO REF	MOS HRS/MSC AFL	6000	+25/-25			10-MAY-2002 0 0		
C3233010 (s)	FUNCTIONAL TEST OF LANDING GEAR EMERGENCY BLOWDOWN EXTENSION SYSTEM. (REFER TO 32-33-00.) PKG 27 REF: AMM 32-33-00	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			02-SEP-2014 5979.4 4026		
C3233011 (s)	FUNCTIONAL TEST OF LANDING GEAR EMERGENCY FREEFALL SYSTEM. (REFER TO 32-33-00.) PKG 27 REF: AMM 32-33-00	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			02-SEP-2014 5979.4 4026		
D3211060 (s)	COMPLETELY DISASSEMBLE NOSE LANDING GEAR STRUT AND ACTUATOR. REMOVE AXLE AND PISTON FROM HUB. CONDUCT VISUAL INSPECTION OF ALL COMPONENTS. DETERMINE EXTENT OF WEAR BY MAKING THE REQUIRED DIMENSIONAL CHECKS. (REFER TO 32-21-00 AND 32-32-01.) CONDUCT FLUORE PKG 26 REF: See Workcard	MOS HRS/MSC AFL	6000	+25/-25			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
D3211061 (s)	VISUALLY INSPECT NOSE GEAR TRUNNION AXLE AND INSTALLATION AREA OF TRUNNION FOR CRACKS, CORROSION, AND DAMAGE. IF CORROSION IS FOUND, REMOVE AXLE FROM CYLINDER AND PERFORM FLUORESCENT PENETRANT INSPECTION OF LUG AREA AND MAGNETIC PARTICLE INSPECTION OF AXLE. IF CORROSION I						PKG		
	PKG 26	MOS					10-MAY-2002		
		HRS/MSC					0		
	REF: GENERIC NO REF	AFL	6000	+25/-25			0		
E3230020 (s)	INSPECT LANDING GEAR SQUAT SWITCHES FOR CONDITION.						PKG		
	PKG 5	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
E3242000 (s)	INSPECT NOSE AND MAIN TIRES FOR WEAR, CUTS, ABRASIONS, AND FLAT SPOTS. CHECK CHINE CONDITION ON CHINED TIRE. (REFER TO 32-40-00)						PKG		
	PKG 5	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: AMM 32-40-00	AFL					4467		
E3243010 (s)	INSPECT BRAKE ASSEMBLIES FO RWEAR, CRACKS, HYDRAULIC LEAKS, AND RELEASE.						PKG		
	PKG 5	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: AMM 32-41-01	AFL					4467		
E3244020 (s)	REMOVE AND CLEAN ANTI-SKID VALVE FILTERS. (REFER TO 32-42-01).						PKG		
	PKG 11	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: AMM 32-42-01	AFL					4467		
F3233020 (s)	FUNCTIONAL TEST OF EMERGENCY BRAKE SYSTEM. (REFER TO 34-43-00.)						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014		
		HRS/MSC					5979.4		
	REF: AMM 32-43-00	AFL	6000	+25/-25			4026		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
G3200000 (s)	PERFORM VISUAL INSPECTION OF LANDING GEAR SHOCK STRUTS FOR LEAKS AND GENERAL CONDITION. VISUALLY INSPECT LANDING GEAR SHOCK STRUTS AND LANDING GEAR ACTUATOR ATTACH POINTS FOR SECURITY AND GERNAL CONDITION. (REFER TO 5-10-00)						PKG		
	PKG 5	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
H3210000 (s)	VISUALLY INSPECT MAIN AND NOSE LANDING GEAR STRUT ASSEMBLIES, ACTUATORS, FASTENERS, AND SUPPORT STRUCTURE FOR FATIGUE CRACKS, CORROSION, SECURITY, AND GENERAL CONDITION. INSPECT NOSE GEAR ACTUATOR ATTACH BRACKET IN THE AREA AROUND THE GREASE FITTING. INSPECT FOR CRACKS EM						PKG		
	PKG 17	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
H3211010 (s)	INSPECT MAIN LANDING GEAR TORQUE LINKS FOR LOOSENESS.						PKG		
	PKG 17	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
H3211020 (s)	INSPECT INTERIOR AND EXTERIOR OF MAIN LANDING GEAR AXLE FOR WEAR AND CORROSION. (REFER TO 32-11-00.)						PKG		
	PKG 23	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: AMM 32-11-00	AFL					3315		
H3221000 (s)	INSPECT NOSE GEAR AND ACTUATOR FOR INSTALLATION SECURITY, FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION.						PKG		
	PKG 23	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: GENERIC NO REF	AFL					3315		
H3221010 (s)	INSPECT INTERIOR AND EXTERIOR OF NOSE LANDING GEAR AXLE FOR WEAR AND CORROSION. (REFER TO 32-21-00.)						PKG		
	PKG 23	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: AMM 32-21-00	AFL					3315		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H3230000 (s)	INSPECT LANDING GEAR ELECTRICAL WIRING FOR ROUTING AND GENERAL CONDITION. PKG 11 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
H3230010 (s)	PERFORM LANDING GEAR RETRACTION AND EXTENSION CHECK. CHECK AUTOMATIC BRAKE SNUBBING AND LANDING LIGHTS FOR RETRACT CUTOFF. (REFER TO 32-30-00.) PKG 17 REF: AMM 32-30-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
H3230021 (s)	INSPECT LANDING GEAR SQUAT SWITCHES FOR PROPER OPERATION AND CONDITION. (REFER TO 32-30-03.) PKG 17 REF: AMM 32-30-03	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
H3231014 (s)	INSPECT MAIN GEAR AND ACTUATOR FOR INSTALLATION SECURITY, FASTEMER CONDITION, AND PERMANENT DEFORMATION. PKG 23 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 16-OCT-2012 4757.3 3315		
H3232002 (s)	INSPECT NOSE GEAR ACTUATOR BOOT AND JYDRAULIC PLUMBING FOR SECURITY AND GENERAL CONDITION. PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
H3233000 (s)	VISUALLY INSPECT GEAR FREE FALL, GEAR BLOW DOWN, AND EMERGENCY BRAKE VALVES AND FITTINGS FOR SECURITY OF ATTACHMENT. (REFER TO 5-10-00.) PKG 14 REF: GENERIC NO REF	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H3233012 (s)	PERFORM EMERGENCY AIR EXTENSION SYSTEM AND EMERGENCY BRAKE SYSTEM PLUMBING LEAKAGE CHECK. (REFER TO 32-33-00 AND 32-43-00.)						PKG		
	PKG 17	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: See Workcard	AFL					4467		
H3243000 (s)	INSPECT BRAKE LINES FOR ROUTING AND LEAKS, MLG AND DOOR ACTUATOR ATTACH POINTS FOR SECURITY, AND STRUT HINGE POINTS FOR GENERAL CONDITION.						PKG		
	PKG 11	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
H3243023 (s)	INSPECT POWER BRAKE VALVES FOR SECURITY, OPERATION, AND LEAKS. ENSURE POWER BRAKE VALVE LEVER CONTACTS MECHANICAL STOP. (REFER TO 32-41-02.)						PKG		
	PKG 14	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: AMM 32-41-02	AFL					4467		
H3243030 (s)	FUNCTIONAL TEST OF HYDRAULIC BRAKE FUSES. (REFER TO 32-41-03.)						PKG		
	PKG 23	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: AMM 32-41-03	AFL					3315		
N3243024 (s)	POWER BRAKE VALVE - PERFORM INSPECTION OF ADJUSTMENT SCREWS FOR DAMAGE.						PKG		
	PKG 8	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
N3243050 (s)	POWER BRAKE VALVE - PERFORM INSPECTION OF ADJUSTMENT SCREWS FOR DAMAGE.						PKG		
	PKG 14	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Q3242001 (s)	OPERATIONAL CHECK ANTI-SKID VALVES (REFER TO 32-42-00) PKG 5	MOS	12	+14d/-14d			PKG 05-OCT-2018 6634.6		
	REF: AMM 32-42-00	HRS/MSC AFL	300	+25/-25			4467		
T3211030 (s)	REMOVE AND REPLACE RETAINER RING LOCKSCREW FROM NOSE LANDING GEAR STRUT (P/N AN500A6-10). PKG 11	MOS	24	+14d/-14d			PKG 05-OCT-2018 6634.6		
	REF: AMM 32-21-00	HRS/MSC AFL	600	+25/-25			4467		
T3231040 (s)	INSPECT MAIN LANDING GEAR DOOR ACTUATORS AND HINGES FOR SECURITY AND GENERAL CONDITION. PKG 11	MOS	24	+14d/-14d			PKG 05-OCT-2018 6634.6		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			4467		
W3232003 (s)	NOSE LANDING GEAR FREE FALL UPLATCH ACTUATOR - PERFORM DETAILED CHECK. (REFER TO 32-33-05.) PKG 17	MOS	48	+14d/-14d			PKG 05-OCT-2018 6634.6		
	REF: AMM 32-33-05	HRS/MSC AFL	1200	+25/-25			4467		
CHAPTER 33 LIGHTS									
331019-01	PS43 POWER, LIGHTING INVERTER SUPPLY 6608477-1	MOS			TSN:0		22-MAR-2004		
	2348	HRS/MSC	O/C		TSN:0		501		
	REF:	AFL			TSN:0		416		
331201	LEFT GLARESHIELD FLOODLIGHT POWER SUPPLY PN	MOS			TSN:0		10-MAY-2002		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 33-12-02	AFL			TSN:0		0		
331202	RIGHT GLARESHIELD FLOODLIGHT POWER SUPPLY PN	MOS			TSN:0		10-MAY-2002		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 33-12-02	AFL			TSN:0		0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331303	QUAD EL (ELECTROLUMINESCENT) POWER SUPPLY SDA 16 385 REF: AMM 33-13-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
331311	PILOT FORWARD CIRCUIT BREAKER PANEL OVERLAY PN SN-UNKNOWN REF: AMM 33-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
331312	COPILOT FORWARD CIRCUIT BREAKER PANEL OVERLAY PN SN-UNKNOWN REF: AMM 33-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
331313	PILOT AFT CIRCUIT BREAKER PANEL OVERLAY PN SN-UNKNOWN REF: AMM 33-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
331314	COPILOT AFT CIRCUIT BREAKER PANEL OVERLAY PN SN-UNKNOWN REF: AMM 33-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
331401	PILOT DIMMING CONTROL BOX LT-48G 1458 REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
331402	COPILOT DIMMING CONTROL BOX LT-48G 1459 REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331403	CENTER INSTRUMENT AND PEDESTAL DIMMING CONTROL BOX LT-48G 1455 REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
331404	PEDESTAL DIMMING CONTROL BOX LT-48E 2798 REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
331405	FUEL QUANTITY INDICATOR DIMMING CONTROL BOX LT-48E 2890 REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
331406	CDU LAMP DIMMING CONTROL BOX PN SN-UNKNOWN REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
331601	LEFT ACS DIMMER CONTROL BOX LT-48G 1481 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
331602	RIGHT ACS DIMMER CONTROL BOX LT-48G 1460 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
331701	LEFT AFT LIGHT DIMMING (E215) CONTROL BOX PN SN-UNKNOWN REF: AMM 33-17-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331801	LEFT FORWARD LIGHT DIMMING (AE9) CONTROL BOX PN SN-UNKNOWN REF: AMM 33-18-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
331802	RIGHT LIGHT DIMMING (2AE9) CONTROL BOX PN SN-UNKNOWN REF: AMM 33-18-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
332001	OVERHEAD INDIRECT LIGHTING (PS2) INVERTER 6900115-000 5895 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			25-AUG-2005 1203.65 997		
332002	OVERHEAD INDIRECT LIGHTING (2PS2) INVERTER 6608477-1 4997 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
332003	OVERHEAD INDIRECT LIGHTING (3PS2) INVERTER 6608477-1 5156 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
332004	OVERHEAD INDIRECT LIGHTING (4PS2) INVERTER 6608477-1 5183 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
332005	OVERHEAD INDIRECT LIGHTING (5PS2) INVERTER 6608477-1 5184 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
332006	OVERHEAD INDIRECT LIGHTING (6PS2) INVERTER 6608477-1 5157 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
332007	OVERHEAD INDIRECT LIGHTING (7PS2) INVERTER 6608477-1 5236 REF: AMM 33-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
332009	INDIRECT LIGHTING CONTROL PN SN-UNKNOWN REF: AMM 33-20-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
334101	LEFT LANDING AND TAXI LIGHT PN SN-UNKNOWN REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
334102	RIGHT LANDING AND TAXI LIGHT PN SN-UNKNOWN REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
334201	LEFT NAVIGATION LIGHT PN SN-UNKNOWN REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
334202	RIGHT NAVIGATION LIGHT PN SN-UNKNOWN REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334203	TAIL NAVIGATION LIGHT PN SN-UNKNOWN REF: AMM 33-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
334301	UPPER STROBE/BEACON LIGHT GE16386-9-2 AB0303 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
334302	LOWER STROBE/BEACON LIGHT GE16386-9-1 AB0390 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
334401	WING ICE INSPECTION LIGHT GLJ-140 12385 REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
334501	RECOGNITION LIGHT PN SN-UNKNOWN REF: AMM 33-45-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
334502	RECOGNITION LIGHT PULSE CONTROL UNIT 2401S AR00438 REF: AMM 33-45-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
335001	EMERGENCY EXIT LIGHTING PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P3310004 (s)	CHECK OPERATION OF INTERIOR LIGHTING SYSTEMS PKG 1	MOS	12	+14d/-14d			PKG 05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+25/-25			6634.6 4467		
P3340012 (s)	CHECK OPERATION OF EXTERIOR LIGHTING SYSTEMS PKG 1	MOS	12	+14d/-14d			PKG 05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+25/-25			6634.6 4467		
CHAPTER 34 NAVIGATION									
05-10-29-W3411025	C/W 24 MONTH AIR DATA SYSTEM FUNCTIONAL TEST IAW LEAR 60 M/M 34-17-00	MOS	24	+14d/-14d		-29	03-JUN-2019 6787.9 4531	05-MAY-2021	19-MAY-2021
	REF: AMM 34-17-00	HRS/MSC AFL							
05-10-30-RVSM-W3411015	C/W 12 MONTH PRIMARY ALTITUDE SYSTEM AIR DATA CERTIFICATION TESTING IAW LEAR 60 M/M 34-17-00 - RVSM	MOS	12	+14d/-14d			03-JUN-2019 6787.9 4531	03-JUN-2020	17-JUN-2020
	REF: AMM 34-17-00	HRS/MSC AFL							
34-00-FAR-91.411	C/W 24 MONTH PITOT-STATIC SYSTEM RE-CERTIFICATION IAW FAR 91.411	MOS	24				03-JUN-2019 6787.9 4531	03-JUN-2021	
	REF: FAR FAR 91.411	HRS/MSC AFL							
340001	PERFORM NAVIGATION DATABASE UPDATE	MOS					06-APR-2016 6394.4 4283		
CUSTOMER CODE	REF:	HRS/MSC AFL	O/C						
340002	EGPWS DATABASE UPDATE	MOS					13-AUG-2015 4196		
	REF:	HRS/MSC AFL	O/C						

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341020	C/W 15000HR LEFT PITOT/STATIC PROBE REPLACEMENT IAW LEAR 60 M/M 34-11-02								
	856KR7	MOS		TSN:0			10-MAY-2002		
	209107	HRS/MSC	15000	+25/-25			0	15000	15025
LIFE LIMIT	REF: AMM 34-11-02	AFL		TSN:0			0		
341020A	C/W 24 MONTH LEFT PITOT/STATIC PITCH AND YAW ALIGNMENT CHECK IAW LEAR 60 M/M 34-11-02								
	856KR7	MOS	24	+14d/-14d		-29	03-JUN-2019	05-MAY-2021	19-MAY-2021
	209107	HRS/MSC					6787.9		
	REF: AMM 34-11-02	AFL					4531		
341020B	C/W 24 MONTH LEFT PITOT/STATIC PROBE DETAILED VISUAL INSPECTION IAW LEAR 60 M/M 5-10-30-N3411064								
	856KR7	MOS	24	+14d/-14d		-29	03-JUN-2019	05-MAY-2021	19-MAY-2021
	209107	HRS/MSC					6787.9		
	REF: AMM 34-11-02	AFL					4531		
341025	C/W 15000HR RIGHT PITOT/STATIC PROBE REPLACEMENT IAW LEAR 60 M/M 34-11-02								
	856KR8	MOS		TSN:0			10-MAY-2002		
	209131	HRS/MSC	15000	+25/-25			0	15000	15025
LIFE LIMIT	REF: AMM 34-11-02	AFL		TSN:0			0		
341025A	C/W 24 MONTH RIGHT PITOT/STATIC PROBE PITCH AND YAW ALIGNMENT CHECK IAW LEAR 60 M/M 5-10-30-N3411016								
	856KR8	MOS	24	+14d/-14d		-29	03-JUN-2019	05-MAY-2021	19-MAY-2021
	209131	HRS/MSC					6787.9		
	REF: AMM 34-11-02	AFL					4531		
341025B	C/W 24 MONTH RIGHT PITOT/STATIC PROBE DETAILED VISUAL INSPECTION IAW LEAR 60 M/M 5-10-30-N3411064								
	856KR8	MOS	24	+14d/-14d		-29	03-JUN-2019	05-MAY-2021	19-MAY-2021
	209131	HRS/MSC					6787.9		
	REF: AMM 34-11-02	AFL					4531		
341026	PITOT/STATIC PROBE								
	856KR8 (STDBY)	MOS		TSN:0			10-MAY-2002		
	209133	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 34-11-02	AFL		TSN:0			0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341105	PILOT RIGHT STATIC SHUTOFF VALVE 6600473-2 1681 REF: AMM 34-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
341106	COPILOT RIGHT STATIC SHUTOFF VALVE 6600473-1 1994 REF: AMM 34-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
341107	PILOT LEFT STATIC SHUTOFF VALVE 6600473-1 2079 REF: AMM 34-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
341108	COPILOT LEFT STATIC SHUTOFF VALVE 6600473-2 1808 REF: AMM 34-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
341111	STANDBY ALTIMETER 8047-700-53MB 8324B REF: AMM 34-15-01	MOS HRS/MSC AFL	O/C				10-AUG-2011 3848.65 2794		
341111A	C/W 24 MONTH STANDBY ALTIMETER RE-CERTIFICATION IAW FAR 91.411 8047-700-53MB 8324B REF: See Workcard	MOS HRS/MSC AFL	24				03-JUN-2019	03-JUN-2021	
341133	NO. 1 LOWER (ADC) AIR DATA COMPUTER 822-0389-429 HPPB REF: AMM 34-17-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			05-MAY-2017 6491.7 4359		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341133A	C/W 24 MONTH #1 LOWER AIR DATA COMPUTER RE-CERTIFICATION IAW FAR 91.411 822-0389-429 HPPB REF: See Workcard	MOS HRS/MSC AFL	24				03-JUN-2019	03-JUN-2021	
341134	NO. 2 UPPER (ADC) AIR DATA COMPUTER 822-0389-429 4208 REF: AMM 34-17-01	MOS HRS/MSC AFL	O/C				10-AUG-2011 3848.65 2794		
341134A	C/W 24 MONTH #2 UPPER AIR DATA COMPUTER RE-CERTIFICATION IAW FAR 91.411 822-0389-429 4208 REF: See Workcard	MOS HRS/MSC AFL	24				03-JUN-2019	03-JUN-2021	
341401	RADIO ALTIMETER TRANSCEIVER 622-2855-011 101LN REF: AMM 34-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
341402	RADIO ALTIMETER CONVERTER 622-7209-002 J1CF REF: AMM 34-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
341403	AFT RADIO ALTIMETER ANTENNA 622-0954-002 FJHF REF: AMM 34-14-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
341404	FORWARD RADIO ALTIMETER ANTENNA 622-0954-002 16MV REF: AMM 34-14-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341703	FORWARD SIGNAL INTERFACE ADAPTER 622-9732-003 HVLK REF: AMM 34-17-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
341704	AFT SIGNAL INTERFACE ADAPTER 622-9732-003 GK4N REF: AMM 34-17-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
341705	PILOT AIR DATA REFERENCE PANEL 622-9500-002 HJ6K REF: AMM 34-17-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
341706	COPILOT AIR DATA REFERENCE PANEL 622-9500-002 HJ6J REF: AMM 34-17-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
341707	TAT SENSOR PROBE 102AU1AG 37369 REF: AMM 34-17-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
341709	PRIMARY ADC SWITCHING UNIT PN SN-UNKNOWN REF: AMM 34-17-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
341710	SECONDARY ADC SWITCHING UNIT PN SN-UNKNOWN REF: AMM 34-17-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341801	STANDBY MACH/AIRSPEED INDICATOR PN SN-UNKNOWN REF: AMM 34-18-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
342001	MAGNETIC COMPASS MAGNETOMETER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
342015	DISPLAY UNIT SENSOR 622-9735-002 2270Y REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			23-FEB-2009 2632.9 2057		
342055	NO. 1 FLUX DETECTOR UNIT 622-5812-001 26099 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
342056	NO. 2 FLUX DETECTOR UNIT 622-5812-001 26859 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
342057	NO. 1 INTERNAL COMPENSATOR (ICU-85) UNIT 622-6189-002 HJYY REF: AMM 34-26-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
342058	NO. 2 INTERNAL COMPENSATOR (ICU-85) UNIT 622-6189-002 HK08 REF: AMM 34-26-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342401	MAGNETIC COMPASS PN SN-UNKNOWN REF: AMM 34-24-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
342410	NO. 1 ATTITUDE/HEADING (AHC-85E) COMPUTER 622-9336-400 27JWT REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	TSR:1 TSR:0 TSR:0			05-FEB-2019 6735 4497		
342411	NO. 2 ATTITUDE/HEADING (AHC-85E) COMPUTER 622-9336-400 2311 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C				25-JAN-2019 6645.3 4493		
342501	STANDBY ATTITUDE DIRECTIONAL (ADI) INDICATOR PN SN-UNKNOWN REF: AMM 34-25-01	MOS HRS/MSC AFL	N/A	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
343007	MARKER BEACON (37X-2) ANTENNA 522-0854-069 52985 REF: AMM 34-51-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
344007	NO. 1 GPS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
344008	NO. 2 GPS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344111	LOWER TCAS DIRECTIONAL (TRE-920) ANTENNA 622-8973-001 838X REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
344112	UPPER TCAS DIRECTIONAL (TRE-920) ANTENNA 622-8973-001 837C REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:63 TSN:2343.78 TSN:1856			11-APR-2008 2360.78 1868		
344143	TCAS (TTR-4000) PROCESSOR 822-1294-032 154493 REF: AMM 34-43-01	MOS HRS/MSC AFL	O/C				23-JUL-2015 6288.98 4196		
344806	WEATHER RADAR INDICATOR 622-9302-004 FXKW REF: AMM 34-42-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
344807	PILOT EFIS RADAR CONTROL PANEL 1015-1-11 625 REF: AMM 34-61-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
344808	COPILOT EFIS RADAR CONTROL PANEL 1015-1-11 367 REF: AMM 34-61-07	MOS HRS/MSC AFL	O/C	TSR:6 TSR:0 TSR:0			29-SEP-2014 5979.4 4026		
345001	NO. 1 ADF (ADF-462) RECEIVER 622-7382-101 HXNY REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345002	NO. 2 ADF (ADF-462) RECEIVER 622-7382-101 10TJM REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
345005	ENHANCED GROUND PROXIMITY WARNING SYSTEM COMPUTER 965-0976-040-212-212 13584 REF: AMM 34-45-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
345011	NO. 1 DME TRANSCEIVER 622-7309-101 JBMK REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
345012	NO. 2 DME TRANSCEIVER 622-7309-101 JBMN REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
345013	ADF, DUAL (ANT-462B) ANTENNA 622-7384-001 HMYR REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
345021	NO. 1 VHF (VIR 432) RECEIVER 622-7194-201 GBBT REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
345022	NO. 2 VHF (VIR 432) RECEIVER 622-7194-201 YY9R REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345043	LEFT NAVIGATION (BLADE) ANTENNA DMN4-45 8835 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
345044	RIGHT NAVIGATION (BLADE) ANTENNA DMN4-45 8841 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
345079	#1 COLLINS TDR-940 TRANSPONDER 622-9210-501 4C0KGH REF: AMM 34-56-01	MOS HRS/MSC AFL	O/C				05-JUL-2018 6607.8 4443		
345079A	C/W 24 MONTH #1 COLLINS TDR-940 TRANSPONDER RE-CERTIFICATION IAW FAR 91.413 622-9210-501 4C0KGH REF: See Workcard	MOS HRS/MSC AFL	24				03-JUN-2019	03-JUN-2021	
345080	#2 COLLINS TDR-940 TRANSPONDER 622-9210-501 4323 REF: AMM 34-56-01	MOS HRS/MSC AFL	O/C				05-JUL-2018 6607.8 4443		
345080A	C/W 24 MONTH #2 COLLINS TDR-940 TRANSPONDER RE-CERTIFICATION IAW FAR 91.413 622-9210-501 4323 REF: See Workcard	MOS HRS/MSC AFL	24				03-JUN-2019	03-JUN-2021	
345091	NO. 1 TRANSPONDER ANTENNA C1100-2 40074 REF: AMM 34-56-02	MOS HRS/MSC AFL	O/C				29-SEP-2014 5978.6 4025		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346011	NO. 1 FLIGHT MANAGEMENT COMPUTER PN SN-UNKNOWN REF: AMM 34-60-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
346012	NO. 2 FLIGHT MANAGEMENT COMPUTER PN SN-UNKNOWN REF: AMM 34-60-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
346015	#1 UNIVERSAL UNS 1EW FMS 3017-41-221 2265 REF: See Workcard	MOS HRS/MSC AFL	O/C				05-JUL-2018 6607.8 4443		
346016	#2 UNIVERSAL UNS 1EW FMS 3017-41-221 2308 REF: See Workcard	MOS HRS/MSC AFL	O/C				05-JUL-2018 6607.8 4443		
346021	UNIVERSAL SSDTU DATALOADER. UNKNOWN SN-UNKNOWN REF: AMM 34-61-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-JUL-2018 6607.8		
346025	NO. 1 FMS CONFIGURATION MODULE 30171 2339 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				05-JUL-2018 6607.8 4443		
346026	NO. 2 FMS CONFIGURATION MODULE 30171 2389 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				05-JUL-2018 6607.8 4443		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346031	PILOT ALTITUDE AWARENESS PANEL 822-0328-004 HP5W REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:125 TSN:4757.3 TSN:3315			16-OCT-2012 4757.3 3315		
346032	COPILOT ALTITUDE AWARENESS PANEL 822-0328-004 HP5V REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:125 TSN:4757.3 TSN:3315			16-OCT-2012 4757.3 3315		
346041	COURSE HEADING PANEL 622-7397-006 GTVX REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
347510	#1 UNIVERSAL WAAS GPS ANTENNA 10708 10546 REF: AMM 34-54-02	MOS HRS/MSC AFL	O/C				05-JUL-2018 6607.8 4443		
347511	#2 UNIVERSAL WAAS GPS ANTENNA 10708 10360 REF: AMM 34-54-02	MOS HRS/MSC AFL	O/C				05-JUL-2018 6607.8 4443		
34CUS1	DIGITAL DISCRETE ADAPTER 08090021 656 REF:	MOS HRS/MSC AFL	O/C				05-JUL-2018 6607.8		
H3411010 (s)	INSPECT PITOT TUBES, STATIC AND PITOT LINES, DRAIN LINES, AND WIRING FOR CONDITION AND SECURITY. CHECK STATIC PORTS AND PITOT/STAIC PROBES FOR DISTORTION. CHECK OPERATION OF DRAIN VALVES. (REFER TO 34-11-02) PKG 8 REF: AMM 34-11-02	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			05-OCT-2018 6634.6 4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H3411012 (s)	INSPECT AIR TEMPERATURE SENSOR OR AIR DATA COMPUTER STATIC, PITOT, AND DRAIN LINES FOR CONDITION AND SECURITY. CHECK OPERATION OF DRAIN VALVES.						PKG		
	PKG 8	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
H3411031 (s)	PERFORM FUNCTIONAL TEST OF STATIC SHUTOFF (ISOLATION) VALVES. (REFER TO 34-11-00)						PKG		
	PKG 7	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: AMM 34-11-00	AFL					4467		
K3411061 (s)	PITOT-STATIC PROBE HEATING CURRENT SENSING RELAY - PERFORM FUNCTIONAL TEST. (REFER TO 30-30-01)						PKG		
	PKG 7	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: AMM 30-30-01	AFL					4467		
P3400004 (s)	INSPECT NOSE COMPARTMENT FROM THE FORWARD SIDE OF THE FORWARD PRESSURE BULKHEAD, FORWARD, FOR CLEANLINESS. ELECTRONIC AND ELECTRICAL EQUIPMENT AND ANTENNA INSTALLATIONS FOR SECURITY OF MOUNTING AND GENERAL CONDITION. WIRE BUNDLE AND PLUMBING ROUTING FOR SECURIT						PKG		
	PKG 8	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
T3453003 (s)	INSPECT ANTENNA INSTALLATIONS FOR SECURITY, CORROSION, AND PROPER TENSION OF HF ANTENNA WIRE. (REFER TO 23-12-03.)						PKG		
	PKG 18	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: AMM 23-12-03	AFL					4467		
U3411014 (s)	INSPECT PITOT STATIC PROBES - PERFORM PITOT-STATIC PROBE DRAIN HOLE CHECK. (REFER TO 34-11-02)						PKG		
	PKG 2	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: AMM 34-11-02	AFL					4467		

CHAPTER 35 OXYGEN

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350003	NOSE OXYGEN SYSTEM PRESSURE TRANSDUCER 124058-2000 42443 REF: AMM 35-00-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
350006	DORSAL OXYGEN SHUTOFF VALVE AND REGULATOR ASSEMBLY 172180-05 0646 REF: AMM 35-00-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
350008	DORSAL OXYGEN PRESSURE INDICATOR 6608401-20 273 REF: AMM 35-00-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
351001	PILOT OXYGEN MASK MC10-15-176 87844 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-MAR-2018 6570.7 4417		
351001A	C/W 72 MONTH PILOT OXYGEN MASK OVERHAUL IAW LEAR 60 M/M 05-10-29 MC10-15-176 87844 REF:	MOS HRS/MSC AFL	72	+14d/-14d	-13		07-MAR-2018 6570.7 4417	22-FEB-2024	07-MAR-2024
351002	COPILOT OXYGEN MASK MC10-15-107 26891 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			30-DEC-2016 6460.9 4334		
351002A	C/W 72 MONTH CO-PILOT OXYGEN MASK OVERHAUL IAW LEAR 60 M/M 05-10-29 MC10-15-107 26891 REF:	MOS HRS/MSC AFL	72	+14d/-14d			30-DEC-2016 6460.9 4334	30-DEC-2022	13-JAN-2023

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
352006	C/W 15YR NOSE OXYGEN CYLINDER REPLACEMENT IAW LEAR 60 M/M 35-00-01 - LIFE LIMIT 176270-77 ALT281-22617/492170 REF: AMM 35-00-01 Manufacture Date: 01-OCT-2008	MOS HRS/MSC AFL APH ACH	180	TSN:82 TSN:0 TSN:0			06-AUG-2015 6288.98 4196	01-OCT-2023	
352006A	C/W 5YR NOSE OXYGEN CYLINDER HYDROSTATIC TEST IAW LEAR 60 M/M 05-10-029 176270-77 ALT281-22617/492170 REF: GENERIC NO REF	MOS HRS/MSC AFL	60 +14d/-14d				28-JUL-2015	28-JUL-2020	11-AUG-2020
352027	PASSENGER OXYGEN CONTROL VALVE P21004-3 0150 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
352031	FORWARD SELECTOR, OXYGEN VALVE ZVC256 20103374 REF: AMM 35-00-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
352032	AFT SELECTOR, OXYGEN VALVE ZVC256 00125173 REF: AMM 35-00-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
352033	RIGHT AFT SELECTOR, OXYGEN VALVE ZVC179 1062134 REF: AMM 35-00-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
353002	R1 OXYGEN MASK DROP BOX 833-812-02 0284 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
353003	L2 OXYGEN MASK DROP BOX 833-812-01 0320 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
353004	R3 OXYGEN MASK DROP BOX 833-812-02 0427 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
353005	L3 OXYGEN MASK DROP BOX 833-812-01 0319 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
353006	R4 OXYGEN MASK DROP BOX 833-812-02 0433 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
353007	R2 OXYGEN MASK DROP BOX 833-812-01 0322 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
353013-701 (s)	OXYGEN, PORTABLE CYLINDER 5500-C1W-BF23A P11080058 REF:	MOS HRS/MSC AFL	O/C	TSN:7 TSN:0 TSN:0			23-AUG-2013 5370.27 3666		
353013-701A (s)	C/W 12 MONTH PORTABLE OXYGEN CYLINDER VISUAL INSPECTION IAW LEAR 60 M/M CH 35 5500-C1W-BF23A P11080058 REF:	MOS HRS/MSC AFL	12				05-MAY-2017 6491.7 4359		
353013-701B (s)	C/W 5YR PORTABLE OXYGEN CYLINDER HYDROSTATIC TEST 5500-C1W-BF23A P11080058 REF:	MOS HRS/MSC AFL	60				23-JAN-2013		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H3500020 (s)	INSPECT OXYGEN BOTTLE FOR SECURITY OF MOUNTING AND PLUMBING FOR ROUTING AND SECURITY. PKG 18	MOS	48	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25					
P3510020 (s)	ON AIRCRAFT EQUIPPED WITH E.R.O.S. AVIATION CREW MASKS, PERFORM FUNCTIONAL TEST OF OXYGEN MASK. (REFER TO 35-10-01.) PKG 13	MOS	48	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 35-10-01	HRS/MSC AFL	1200	+25/-25					
T3500000 (s)	FUNCTIONAL TEST OF OXYGEN SYSTEM. (REFER TO 35-00-00.) PKG 14	MOS	48	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: AMM 35-00-00	HRS/MSC AFL	1200	+25/-25					
T3500010 (s)	INSPECT OXYGEN BOTTLE FOR SECURITY OF MOUNTING AND PLUMBING FOR ROUTING AND SECURITY. PKG 14	MOS	48	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25					
T3500040 (s)	CHECK CREW MEMBER PROTECTIVE BREATHING EQUIPMENT (PBE) FOIL POUCH FOR VACUUM SEAL INTEGRITY. IF VACUUM SEAL IS BROKEN, REPLACE EQUIPMENT. PKG 7	MOS	24	+14d/-14d			PKG 05-OCT-2018 6634.6 4467		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25					
CHAPTER 36 PNEUMATIC									
05-11-00-L3610008	REPLACE L AND R ENGINE PYLON BLEED AIR SEALS.	MOS					19-MAR-2011 3580.3 2618		
	REF:	HRS/MSC AFL	O/C						
05-11-00-W3610011	REPLACE ENGINE BLEED AIR CHECK VALVES	MOS					11-APR-2008 2360.78 1868		
	REF: AMM 36-10-06	HRS/MSC AFL	O/C						

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
360001	REPLACE LEFT ENGINE PYLON BLEED AIR SEALS REF: AMM 36-10-01	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
360002	REPLACE RIGHT ENGINE PYLON BLEED AIR SEALS REF: AMM 36-10-01	MOS HRS/MSC AFL	O/C				10-MAY-2002 0 0		
360003	C/W 1200HR BLEED AIR SEALS REPLACEMENT IAW LEAR 60 M/M 36-10-01 - (LOCATED BETWEEN THE FORWARD BLEED AIR MANIFOLD AND AFT BLEED AIR MANIFOLD) REF: AMM 36-10-01	MOS HRS/MSC AFL	1200	+25/-25			29-SEP-2014 5979.4 4026	7179.4	7204.4
361001	NO. 1 BLEED AIR REGULATING/SHUTOFF VALVE 7608071-1 296 REF: AMM 36-10-04	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		10-MAY-2002 0 0		
361002	NO. 2 BLEED AIR REGULATING/SHUTOFF VALVE 7608071-1 325 REF: AMM 36-10-04	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		10-MAY-2002 0 0		
361007	LEFT MIXING VALVE CONTROL BOX PN SN-UNKNOWN REF: AMM 36-10-05	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		10-MAY-2002 0 0		
361008	RIGHT MIXING VALVE CONTROL BOX PN SN-UNKNOWN REF: AMM 36-10-05	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		10-MAY-2002 0 0		
361011	LEFT BLEED AIR MIXING VALVE 1H106-9 6AL28 REF: AMM 36-10-02	MOS HRS/MSC AFL	O/C		TSO:15 TSO:0 TSO:0		25-NOV-2011 4140.97 2967		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361012	RIGHT BLEED AIR MIXING VALVE 1H106-9 11AT79 REF: AMM 36-10-02	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			03-AUG-2005 1202.68 996		
361013	NO. 1 BLEED AIR CHECK VALVE 6608295-3 2097 REF: AMM 36-10-06	MOS HRS/MSC AFL	O/C				11-APR-2008 2360.78 1868		
361014	NO. 2 BLEED AIR CHECK VALVE 6608295-3 2370 REF: AMM 36-10-06	MOS HRS/MSC AFL	O/C				11-APR-2008 2360.78 1868		
361017	NO. 1 BLEED AIR (1 1/4) CHECK VALVE 6600210-10 7197 REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
361018	NO. 2 BLEED AIR (1 1/4) CHECK VALVE 6600210-10 7150 REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
361037	C/W 15YR #1 EMERGENCY AIR BOTTLE REPLACEMENT IAW LEAR 60 M/M 36-15-01 6600194-008 750 REF: AMM 36-15-01 SCRAP Manufacture Date: 04-OCT-2018	MOS HRS/MSC AFL APH ACH	180	TSN:0 TSN:0 TSN:0			03-JUN-2019 6787.9 4531	04-OCT-2033	
361037A	C/W 3YR #1 EMERGENCY AIR BOTTLE VISUAL INSPECTION AND HYDROSTATIC TEST IAW LEAR 60 M/M 36-15-01 6600194-008 750 REF: AMM 36-15-01	MOS HRS/MSC AFL	36	+14d/-14d			04-OCT-2018	04-OCT-2021	18-OCT-2021

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361037B	C/W 9YR #1 EMERGENCY AIR BOTTLE X-RAY INSPECTION IAW LEAR 60 M/M 36-15-01 6600194-008 750 REF: AMM 36-15-01	MOS HRS/MSC AFL	108	+14d/-14d			04-OCT-2018	04-OCT-2027	18-OCT-2027
361038	C/W 15YR #2 EMERGENCY AIR BOTTLE REPLACEMENT IAW LEAR 60 M/M 36-15-01 6600194-008 00540 REF: AMM 36-15-01 Manufacture Date: 01-SEP-2015	MOS HRS/MSC AFL	180	TSN:171.7 TSN:138			12-APR-2018 6580.9 4431	01-SEP-2030	
361038A	C/W 3YR #2 EMERGENCY AIR BOTTLE VISUAL INSPECTION AND HYDROSTATIC TEST IAW LEAR 60 M/M 36-15-01 6600194-008 00540 REF: AMM 36-15-01	MOS HRS/MSC AFL	36	+14d/-14d			06-APR-2018	06-APR-2021	20-APR-2021
361038B	C/W 9YR #2 EMERGENCY AIR BOTTLE X-RAY INSPECTION IAW LEAR 60 M/M 36-15-01 6600194-008 00540 REF: AMM 36-15-01	MOS HRS/MSC AFL	108	+14d/-14d			14-OCT-2015	14-OCT-2024	28-OCT-2024
361125	LEFT TAILCONE BLEED AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
361126	RIGHT TAILCONE BLEED AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
362001	LANDING GEAR/BRAKE AIR PRESSURE INDICATOR 6608401-12 446 REF: AMM 36-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
362003	PRIMARY EMERGENCY AIR SYSTEM PRESSURE TRANSDUCER 124058-5000 42151 REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
362004	SECONDARY EMERGENCY AIR SYSTEM PRESSURE TRANSDUCER 124058-5000 42158 REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
362011	NO. 1 ENGINE HI-LIMIT BLEED AIR THERMOSTAT PN SN-UNKNOWN REF: AMM 36-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
362012	NO. 2 ENGINE HI-LIMIT BLEED AIR THERMOSTAT PN SN-UNKNOWN REF: AMM 36-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
362019	NO. 1 INBOARD OVERHEAT SWITCH 6600213-5 175074 REF: AMM 36-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
362020	NO. 2 INBOARD OVERHEAT SWITCH 6600213-5 175068 REF: AMM 36-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
H3620001 (s)	FUNCTIONAL TEST OF PYLON OVERHEAT THERMOSTAT, DUCT TEMPERATURE SENSOR, AND ELECTRICAL SYSTEM. (REFER TO 36-20-03 AND 36-20-04.) PKG 21 REF: See Workcard	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			16-OCT-2012 4757.3 3315	PKG	
J3610037 (s)	VISUALLY INSPECT HIGH PRESSURE BLEED AIR CHECK VALVES PKG 21 REF: AMM 36-10-06	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			16-OCT-2012 4757.3 3315	PKG	
L3610039 (s)	PERFORM OPERATIONAL CHECK OF BILLED AIR CHECK VALVES. (REFER TO 36-10-03). PKG 9 REF: AMM 36-10-03	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			05-OCT-2018 6634.6 4467	PKG	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
U3610044 (s)	GENERAL VISUAL INSPECTION PKG 9 REF: GENERIC NO REF	BLEED AIR DUCTING (INCLUDING CLAMPS AND VALVES). (REFER TO 5-10-00) MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
CHAPTER 38 WATER/WASTE									
381008	LAVATORY SINK FAUCET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0 10-MAY-2002 0 0		
381009	FORWARD TOILET DRAIN, HEATED MAST 116393-101 3798 REF: AMM 38-32-01	MOS HRS/MSC AFL	O/C				TSN:9 TSN:0 TSN:0 29-SEP-2014 5979.4 4026		
381010	AFT TOILET DRAIN, HEATED MAST 116393-101C 1241 REF: AMM 38-32-01	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0 10-MAY-2002 0 0		
381020	TOILET WATER PUMP 5250-10H SN-UNKNOWN REF: AMM 12-10-13	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0 01-MAR-2017 6487.1 4353		
381030	TOILET TIMER PN SN-UNKNOWN REF: AMM 38-31-01	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0 10-MAY-2002 0 0		
381050	TOILET MACERATOR PN SN-UNKNOWN REF: AMM 12-10-13	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0 10-MAY-2002 0 0		
381060	LAVATORY ON-DEMAND WATER SYSTEM VOLTAGE REGULATOR PN SN-UNKNOWN REF: AMM 12-10-12	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0 10-MAY-2002 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
381070	LAVATORY SINK PUMP PN SN-UNKNOWN REF: AMM 12-10-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
382015	NO. 1 HOT WATER TANK PN SN-UNKNOWN REF: AMM 12-10-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
382016	NO. 2 HOT WATER TANK PN SN-UNKNOWN REF: AMM 12-10-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
383101	LAVATORY TOILET ASSEMBLY PN SN-UNKNOWN REF: AMM 38-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
CHAPTER 49 AIRBORNE AUXILIARY POWER									
490101	COCKPIT APU CONTROL PANEL PN SN-UNKNOWN REF: SMM 49-01-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
490102	APU RELAY BOX 201-6-028-9 4872-24 REF: SMM 49-01-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
490103	(ESU / DESU) ELECTRONIC SEQUENCE UNIT 160935-203B 7584-0060 REF: See Workcard	MOS HRS/MSC AFL	O/C			06/08/2043	08-JAN-2013 4889.02 3396		
490105	APU (GCU) GENERATOR CONTROL UNIT GCSG505-16G 1100C REF: SMM 49-01-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
490106	BITE ANNUNCIATOR BOX 161212-100 0720 REF: SMM 49-01-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
490109	UPPER CURRENT TRANSFORMER PN SN-UNKNOWN REF: SMM 49-01-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
490110	LOWER CURRENT TRANSFORMER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
490111	CURRENT SENSOR PN SN-UNKNOWN REF: SMM 49-01-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
493101	APU FUEL SHUTOFF VALVE EM91-41 2032852 REF: SMM 49-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
493102	APU FUEL BOOST PUMP 1500-00-22 0153 REF: SMM 49-31-02	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			27-JUL-2011 3823.32 2777		
496103	APU FIRE HORN 430-M1 20204 REF: SMM 49-61-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2003 17 12		
498010	EXHAUST (APU) DUCT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
49APU1	APU								
49.APU1	4503135 SP-E990310 REF: GENERIC NO REF	MOS HRS/MSC AFL	E/C	TSN:1439			25-NOV-2011 4140.97 2967		
APU Model : T-20G-10C3A (CIMMS) Serial # SP-E990310 Part # 4503135									
490020	APU - DESU , , PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
490030	APU - SEAL PLATE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
492001	APU - COMBUSTOR HOUSING ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
492002	APU - APU EXHAUST THERMOCOUPLE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
492010	APU - TURBINE NOZZLE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
492020	APU - IGNITER 160544-1 NSN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			23-JUN-2011 1439 3460		
492030	APU - OUTPUT GEAR PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
492040	APU - BITE BOX PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
492050	APU - SHAFT PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
492201	APU - ROTOR BEARING 161623-1 L098 REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			23-JUN-2011 1439 3460		
492202	APU - ROTOR BEARING 161623-1 L099 REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			23-JUN-2011 1439 3460		
492207	APU - HOUSING BEARING SUPPORT PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
492208	APU - BEARING HOUSING ADAPTER PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
492300	APU - PRESSURE (LOW OIL) SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
492320	APU - SPEED (MAGNETIC PICK-UP) SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
493001	APU - FUEL CONTROL 160962-5 2495131 REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
493003	APU - PUMP ASSEMBLY, FUEL CONTROL 4502863C 10-98-10 REF:	MOS HRS/MSC APUS	O/C				02-NOV-2007 1031 2594		
493005	APU - FUEL ATOMIZER INTERCONNECT HARNESS PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
493007	APU - ASSEMBLY, FUEL ATOMIZER 160938-200C 05-97-20 REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
493010	APU - HARNESS PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
493055	APU - ATOMIZER CUP MOTOR 4951372 M746 REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			23-JUN-2011 1439 3460		
493102	APU - FUEL PUMP 161627-2 VT0444 REF:	MOS HRS/MSC APUS	O/C				23-JUN-2011 1439 3460		
494001	APU - IGNITION EXCITER 4951302 99103642 REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
495001	APU - TURBINE WHEEL 164253-3 HB001	MOS HRS/MSC APUS	3500	TSN:0 TSN:0 TSN:0			23-JUN-2011 1439 3460		6960
LIFE LIMIT	REF:								
495005	APU - COMPRESSOR WHEEL 160915-4 V63-H550A	MOS HRS/MSC APUS	7000	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		7000
LIFE LIMIT	REF:								
495010	APU - AIR INLET HOUSING PN SN-UNKNOWN	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
LIFE LIMIT	REF:								
497010	APU - HOURMETER/EVENT COUNTER INDICATOR 4950959 A336	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			18-APR-2013		
LIFE LIMIT	REF:								
499010	APU - OIL PUMP GEAR PN SN-UNKNOWN	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
LIFE LIMIT	REF:								
CHAPTER 52 DOORS									
05-10-29-L5210025	C/W 24 MONTH EXTERIOR LWR DOOR STRUCTURE/HINGE VISUAL INSPECTION FOR CORROSION IAW LEAR 60 M/M 05-10-29								
		MOS	24	+14d/-14d			07-MAR-2018	07-MAR-2020	21-MAR-2020
	REF: GENERIC NO REF	HRS/MSC AFL					6570.7 4417		
521001	UPPER PASSENGER/CREW DOOR 5410501-117 W197	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
LIFE LIMIT	REF: AMM 52-10-00								
521002	LOWER PASSENGER/CREW DOOR 5410536-032 W305	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
LIFE LIMIT	REF: AMM 52-10-00								

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
521003	UPPER PASSENGER/CREW DOOR HANDLE 6600480-1 313 REF: AMM 52-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
521004	UPPER PASSENGER/CREW DOOR LOCK ASSEMBLY AS848 SG5931066 REF: AMM 52-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
+ 5210054	CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR HANDLE - REPLACE REF: GENERIC NO REF	MOS HRS/MSC AFL	36 1200	+14d/-14d +25/-25			(EBT) 5631	14-MAY-2021 5656	
521006	UPPER PASSENGER/CREW DOOR DAMPER PN SN-UNKNOWN REF: AMM 52-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
521008	LOWER PASSENGER/CREW DOOR HANDLE PN SN-UNKNOWN REF: AMM 52-10-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
521010	FORWARD PASSENGER/CREW LOWER DOOR CABLE 6015550-003 NSN REF: AMM 52-10-10	MOS HRS/MSC AFL	O/C	TSN:11 TSN:0 TSN:0			27-JAN-2014 5688.98 3844		
521011	AFT PASSENGER/CREW LOWER DOOR CABLE PN SN-UNKNOWN REF: AMM 52-10-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
521012	LOWER PASSENGER/CREW DOOR DAMPER 6600425-2 SN-UNKNOWN REF: AMM 52-10-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2018 6634.6 4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
522000	EMERGENCY EXIT / BAGGAGE DOOR PN SN-UNKNOWN REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
522002	EMERGENCY EXIT / BAGGAGE DOOR HANDLE PN SN-UNKNOWN REF: AMM 52-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
522005	PASSENGER DOOR FORWARD SNUBBER PN SN-UNKNOWN REF: AMM 52-10-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
522006	PASSENGER DOOR AFT SNUBBER PN SN-UNKNOWN REF: AMM 52-10-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
522007	EMERGENCY EXIT DOOR FORWARD SNUBBER PN SN-UNKNOWN REF: AMM 52-20-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
522008	EMERGENCY EXIT DOOR AFT SNUBBER PN SN-UNKNOWN REF: AMM 52-20-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
522025	EMERGENCY EXIT/BAGGAGE DAMPER PN SN-UNKNOWN REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
522032	EMERGENCY EXIT/BAGGAGE DOOR WINDOW ASSEMBLY PAS6600405A-8 10819 REF: AMM 52-20-06	MOS HRS/MSC AFL	O/C	TSN:60 TSN:0 TSN:0			29-SEP-2014 5979.4 4026		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
522032A	PRISM CHECK EMERGENCY EXIT/BAGGAGE DOOR WINDOW ASSEMBLY PAS6600405A-8 10819 REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C	05-10-29-M5600008			29-SEP-2014 5979.4 4026		
523101	TAILCONE BAGGAGE DOOR 6011552-17 164978 REF: AMM 52-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
523102	TAILCONE BAGGAGE HANDLE 6600480-2 283 REF: AMM 52-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
524001	C/W 24 MONTH AFT AVIONICS DOOR GAP AND MISMATCH RVSM INSPECTION IAW LEAR 60 M/M 52-40-01 REF: AMM 52-40-01	MOS HRS/MSC AFL	24	+14d/-14d	-29		03-JUN-2019 6787.9 4531	05-MAY-2021	19-MAY-2021
524003	LEFT FORWARD NOSE AVIONICS DOOR 6010430-003 0209 REF: AMM 52-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
524004	RIGHT FORWARD NOSE AVIONICS DOOR 6010430-004 0209 REF: AMM 52-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
524005	LEFT AFT NOSE AVIONICS DOOR 6010431-003 0209 REF: AMM 52-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
524006	RIGHT AFT NOSE AVIONICS DOOR 6010431-004 0209 REF: AMM 52-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
524007	TAILCONE AVIONICS DOOR 5412500-21 0164 REF: AMM 52-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
527005	CREW DOOR WARNING BOX ASSEMBLY PN SN-UNKNOWN REF: AMM 52-70-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
527006	EMERGENCY EXIT DOOR WARNING BOX ASSEMBLY PN SN-UNKNOWN REF: AMM 52-70-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
528001	LEFT INBOARD MAIN LANDING GEAR DOOR PN SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
528002	RIGHT INBOARD MAIN LANDING GEAR DOOR PN SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
528003	LEFT OUTBOARD MAIN LANDING GEAR DOOR PN SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
528004	RIGHT OUTBOARD MAIN LANDING GEAR DOOR 6022151-008 SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			03-NOV-2006 1806.22 1474		
528101	LEFT NOSE LANDING GEAR DOOR 5410450-19 60-0888 REF: AMM 52-81-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-DEC-2011 4140.97 2967		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
528102	RIGHT NOSE LANDING GEAR DOOR 5410450-20 60-255 REF: AMM 52-81-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
A5210030 (s)	REMOVE TENSION FITTINGS AND PLATES FROM PASSENGER/CREW DOORS (SIX [6] IN EACH DOOR). MAGNETIC PARTICLE INSPECT FOR EVIDENCE OF CRACKS. (REFER TO NDI MANUAL [NDI-2], PART 6, 52-10-01 AND 53-10-01.) PKG 25 REF: See Workcard	MOS HRS/MSC AFL	3000	+25/-25			25-NOV-2011 4140.97 2967		
AA5210056 (s)	CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATION PKG 18 REF: AMM 12-21-03	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			05-OCT-2018 6634.6 4467		
C5210052 (s)	UPPER AND LOWER DOOR HANDLE MECHANISM: GAIN ACCESS TO UPPER AND LOWER DOOR HANDLE MECHANISM. INSPECT FOR GENERAL CONDITION. PKG 27 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			02-SEP-2014 5979.4 4026		
C5220021 (s)	EMERGENCY EXIT/BAGGAGE DOOR HANDLE MECHANISM; GAIN ACCESS TO EMERGENCY EXIT/BAGGAGE DOOR HANDLE MECHANISM. INSPECT FOR GENERAL CONDITION. PKG 27 REF: See Workcard	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			02-SEP-2014 5979.4 4026		
E5220010 (s)	EMERGENCY EXIT/BAGGAGE DOOR HINGE INSTALLATION FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. OBSERVE FORWARD AND AFT HINGE INSTALLATIONS WHILE RACKING THE DOOR WITH ALTERNATING LOADS. PKG 18 REF: AMM 52-20-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			05-OCT-2018 6634.6 4467		
E5220020 (s)	EMERGENCY EXIT/BAGGAGE DOOR HANDLE AND CONTROL ASSEMBLY FREE PLAY CHECK. OPEN DOOR AND REMOVE UPHOLSETRY TO GAIN ACCESS TO ROD CONTROL ASSEMBLY. RESTRAIN THE DOOR PINS AND MOVE THE EMERGENCY EXIT/BAGGAGE DOOR HANDLE TOWARD THE CLOSED POSITION AND THEN TO PKG 18 REF: AMM 52-20-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			05-OCT-2018 6634.6 4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E5280002 (s)	VISUALLY INSPECT TAILCONE AVIONICS AND BAGGAGE DOOR ELECTRICAL BONDING JUMPERS, WHEN INSTALLED, FOR SECURITY AND GENERAL CONDITION						PKG		
	PKG 6	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
H5210020 (s)	UPPER AND LOWER DOOR HINGE INSTALLATIONS FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. OBSERVE FORWARD AND AFT EDGES OF HINGE INSTALLATION WHILE RACKING THE DOORS WITH ALTERNATING LOADS. IF HINGE INSTALLATION CONDITION REQUIRES A MORE THO						PKG		
	PKG 24	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: GENERIC NO REF	AFL					3315		
H5210040 (s)	CLEAN ARM GUIDES OF PASSENGER/CREW UPPER DOOR AND VISUALLY CHECK FOR CRACKS. (SEE FIGURE 1.)						PKG		
	PKG 18	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
H5210060 (s)	INSPECT ENTIRE LENGTH OF LOWER DOOR CABLES FOR EVIDENCE OF FRAYING OR OTHER DAMAGE. DOOR ACCESS PANELS MUST BE REMOVED. (REFER TO 52-10-10)						PKG		
	PKG 12	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: AMM 52-10-10	AFL					4467		
H5210065 (s)	CLEAN LATCH ARM OF PASSENGER/CREW LOWER DOOR AND VISUALLY INSPECT FOR CRACKS. (SEE FIGURE 1.)						PKG		
	PKG 18	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
H5210086 (s)	CHECK LOWER CABIN DOOR MECHANISM. OPEN UPPER AND LOWER CABIN DOORS. MOVE LOWER DOOR HANLE TOWARD THE DOOR PIN MOVEMENT. CHECK FOR SECURITY AND FREE PLAY IN MECHANISM. EXCESSIVE FREE PLAY MAY BE DUE TO MECHANISM FAILURE, EXCESSIVE WEAR, OR DEFORMATION. CHECK DOO						PKG		
	PKG 24	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: GENERIC NO REF	AFL					3315		
H5280001 (s)	VISUALLY INSPECT INBOARD AND OUTBOARD MAIN LANDING GEAR DOOR BONDING JUMPERS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00)						PKG		
	PKG 11	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
K5210070 (s)	EDDY CURRENT INSPECT AROUND LOWER CABIN DOOR LATCH ARM FASTENERS AND PERIPHERY OF ARM PIN EYES FOR CRACKS. (REFER TO NDI MANUAL [NDI-2], PART 3, 52-10-01.)						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014		
		HRS/MSC					5979.4		
	REF: NDT 52-10-01	AFL	6000	+25/-25			4026		
P5210042 (s)	INSPECT CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR SEALS FOR ADHESIONS, CUTS, AND ABRASION; LATCH FOR PROPER OPERATION, HINGES, LATCH PINS, AND RECEPTACLES FOR GENERAL CONDITION AND SECURITY.						PKG		
	PKG 12	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
T5230011 (s)	VISUALLY INSPECT AVIONICS DOORS, HINGES, AND FASTENERS FOR GENERAL CONDITION, PROPER FIT, SEALS, ELECTRICAL BONDING, AND GENERAL CONDITION.						PKG		
	PKG 14	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
T5240002 (s)	VISUAL INSPECTION SINGLE POINT REFUELING DOOR. (REFER TO 5-10-00)						PKG		
	PKG 8	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
T5280000 (s)	VISUALLY INSPECT EMERGENCY EXIT/BAGGAGE DOOR ELECTRICAL BONDING JUMPERS FOR SECURITY AND GENERAL CONDITION. (REFER TO 5-10-00).						PKG		
	PKG 12	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
T5280003 (s)	VISUALLY INSPECT NOSE AVIONICS DOOR AND NOSE LANDING GEAR DOOR ELECTRICAL BONDING JUMPERS FRO SECURITY AND GENERAL CONDITION.						PKG		
	PKG 14	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
CHAPTER 53	FUSELAGE								
05-10-29-Y5331017	C/W 12YR UPPER FUSELAGE SKIN UNDER THE AFT OXYGEN LINE FAIRING INSPECTION IAW LEAR 60 M/M 53-50-06								
		MOS	144	+14d/-14d			(EBT)	06-OCT-2028	20-OCT-2028
		HRS/MSC							
	REF: AMM 53-50-06	AFL							

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-30-RVSM-N5313000	C/W 24 MONTH PITOT-STATIC PROBE ZONE SKIN RVSM CONTOUR CHECK IAW LEAR 60 M/M 53-11-01	MOS	24	+14d/-14d			03-JUN-2019 6787.9 4531	05-MAY-2021	19-MAY-2021
	REF: AMM 53-11-01	HRS/MSC AFL							
05-11-00-T5322000	C/W 12YR/6000LANDING KEELBEAM ATTACHMENT BOLTS REPLACEMENT IAW LEAR 60 M/M 53-10-02	MOS	144	+14d/-14d			29-SEP-2014 5979.4 4026	29-SEP-2026	13-OCT-2026
	REF: AMM 53-10-02	HRS/MSC AFL	6000	+25/-25				10026	10051
535001	RADOME 5410420-2 171S	MOS					01-DEC-2011 4140.97 2967		
	REF: AMM 53-50-01	HRS/MSC AFL	O/C		TSN:0 TSN:0				
535002	RADOME EROSION BOOT 7600841-002 SN-UNKNOWN	MOS					06-APR-2016 6394.4 4283		
	REF:	HRS/MSC AFL	O/C						
A5321060 (s)	WING/FUSELAGE FITTINGS: CLEAN AND VISUALLY INSPECT ALL EIGHT WING/FUSELAGE FITTINGS (FOUR PER SIDE). USING 10X MAGNIFICATION AND ADEQUATE LIGHTING, VISUALLY INSPECT FITTINGS AND SUPPORT STRUCTURE FOR FATIGUE CRACKS, DEFORMATION, CORROSION, MARKS, SCRATCHE						PKG 10-MAY-2002 0 0		
	PKG 28	MOS							
	REF: GENERIC NO REF	HRS/MSC AFL	12000	+25/-25					
AA5323107 (s)	CIRCUMFERENTIAL SKIN SPLICES - CONDUCT AN X-RAY INSPECTION OF THE CIRCUMFERENTIAL SKIN SPLICES AT THE FRAMES LISTED BELOW: A. FRAMES 17, 20, 25, 26 AND 30. B. ON AIRCRAFT 60-002, FRAME 12. C. ON AIRCRAFT 60-003 AND SUBSEQUENT, FRAME 13. D. ON AIRCRAFT 60-002 THRU 60-093, FRAME 20B. CONDUCT SPECIFIC X-RAY INSPECTIONS OF THE CIRCUMFERENTIAL SKIN SPLICES IN THE PRESSURE CABIN ACROSS THE TOP OF THE FUSELAGE FROM STRINGER 8L TO 8R.						PKG 10-MAY-2002 0 0		
	PKG 28	MOS							
	REF: See Workcard	HRS/MSC AFL	12000	+25/-25					
B5331030 (s)	TAILCONE STRUCTURE (REFER TO 5-10-00.): CONDUCT A VISUAL INSPECTION OF THE TAILCONE STRUCTURE FOR EVIDENCE OF PERMANENT DEFORMATION, CORROSION, FATIGUE CRACKS, AND GENERAL CONDITION. FROM THE TAILCONE ACCESS DOOR OPENING, VISUALLY INSPECT ACCESSIBLE AREAS						PKG 10-MAY-2002 0 0		
	PKG 28	MOS							
	REF: GENERIC NO REF	HRS/MSC AFL	12000	+25/-25					

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C5314011 (s)	BELOW FLOORBOARD INSPECTION INSPECT FOR CORROSION, GENERAL CONDITION, AND FATIGUE CRACKS. PKG 27	MOS	144	+14d/-14d			PKG 02-SEP-2014 5979.4 4026		
	REF: GENERIC NO REF	HRS/MSC AFL	6000	+25/-25					
C5314040 (s)	EMERGENCY EXIT/BAGGAGE DOOR FUSELAGE FRAMING STRUCTURE: CONDUCT X-RAY INSPECTION OF FUSELAGE DOOR FRAMING STRUCTURE IN AREA OF BORDERING INNER SKIN. PAY PARTICULAR ATTENTION TO HINGES, HINGE ATTACHMENTS, CORNER DOUBLERS, AND THE LATCH PIN AND RECEPTACLE S PKG 27	MOS	144	+14d/-14d			PKG 02-SEP-2014 5979.4 4026		
	REF: NDT 52-60-01	HRS/MSC AFL	6000	+25/-25					
C5321000 (s)	FUSELAGE FRAMES AND STRINGERS: GAIN ACCESS TO ALL FUSELAGE FRAMES AND STRINGERS FROM FRAME 6 TO AFT PRESSURE BULKHEAD. CONDUCT AN INTERIOR VISUAL INSPECTION OF ALL FUSELAGE FRAMES AND STRINGERS. PARTICULAR ATTENTION SHOULD BE GIVEN TO ALL FRAME SPLICES. I PKG 27	MOS	144	+14d/-14d			PKG 02-SEP-2014 5979.4 4026		
	REF: GENERIC NO REF	HRS/MSC AFL	6000	+25/-25					
C5321040 (s)	WITH WING/FUSELAGE FAIRINGS REMOVED, USE FLASHLIGHT AND MIRROR TO VISUALLY INSPECT THE HONEYCOMB SUPPORT ANGLE SEGMENTS AT THE OUTBOARD ENDS OF THE FORWARD BAGGAGE FLOOR FOR FATIGUE CRACKS, CORROSION, FASTENER SECURITY, AND GENERAL CONDITION PKG 25	MOS					PKG 25-NOV-2011 4140.97 2967		
	REF: GENERIC NO REF	HRS/MSC AFL	3000	+25/-25					
C5321055 (s)	WING-TO-FUSELAGE ATTACHMENT FITTINGS: CLEAN AND VISUALLY INSPECT WITH THE AID OF 10X MAGNIFICATION, FLASHLIGHT, AND MIRROR, ALL EIGHT WING-TO-FUSELAGE ATTACHMENT FITTINGS. INSPECT FITTINGS AND SUPPORT STRUCTURE FOR CRACKS, CORROSION, MARKS, SCRATCHES, FAS PKG 27	MOS	144	+14d/-14d			PKG 02-SEP-2014 5979.4 4026		
	REF: GENERIC NO REF	HRS/MSC AFL	6000	+25/-25					
D5321020 (s)	REMOVE AFT BAGGAGE COMPARTMENT UPHOLSTERY AND FALSE FLOOR PANELS. TAP-TEST FLOOR PANEL, WHICH SUPPORTS THE ELECTRICAL EQUIPMENT, TO CHECK FOR UNBONDING OF UPPER SURFACE PLATE FROM THE HONEYCOMB CORE STRUCTURE. VISUALLY INSPECT FOR CORROSION, PARTICULARLY IN THE PKG 25	MOS					PKG 25-NOV-2011 4140.97 2967		
	REF: GENERIC NO REF	HRS/MSC AFL	3000	+25/-25					

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
D5350020 (s)	INSPECT UNDER WING KEELBEAM AND ATTACHMENTS FOR SECURITY, CORROSION, FASTENER CONDITION, FATIGUE CRACKS, AND PERMANENT DEFORMATION. ALSO INSPECT ATTACHING FITTINGS, FORWARD OF FRAME 24 AND AFT OF FRAME 31, FOR SIMILAR EFFECTS.						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014	5979.4	
	REF: GENERIC NO REF	AFL	6000	+25/-25			4026		
D5350051 (s)	UNDERWING KEEL BEAM: VISUALLY INSPECT REMOVED ASSEMBLY FOR CORROSION, FATIGUE CRACKS, AND GENERAL CONDITION. PAY PARTICULAR ATTENTION TO END FITTINGS COMMON TO BEAM ASSEMBLY AS WELL AS THOSE MATING FITTINGS FORWARD OF FRAME 24 AND AFT OF FRAME 31. (REFER						PKG		
	PKG 28	MOS					10-MAY-2002	0	
	REF: GENERIC NO REF	AFL	12000	+25/-25			0		
F5350010 (s)	VISUALLY INSPECT KEELBEAM, FORWARD AND AFT ATTACH FITTINGS ON KEELBEAM AND ON AIRCRAFT, FOR CRACKS AND GENERAL CONDITION. (REFER TO 5-10-00.)						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014	5979.4	
	REF: GENERIC NO REF	AFL	6000	+25/-25			4026		
G5321021 (s)	REMOVE AFT BAGGAGE COMPARTMENT UPHOLSTERY AND FALSE FLOOR PANELS. VISUALLY INSPECT FLOOR PANEL WHICH SUPPORTS THE ELECTRICAL EQUIPMENT AND FRAMES 25, 26, AND 26A FOR CORROSION AND ANY OTHER DAMAGE.						PKG		
	PKG 8	MOS	24	+14d/-14d			05-OCT-2018	6634.6	
	REF: GENERIC NO REF	AFL	600	+25/-25			4467		
G5321079 (s)	AFT PRESSURE BULKHEAD REMOVE FUEL BLADDER AND VISUALLY INSPECT BULKHEAD FOR EVIDENCE OF FATIGUE CRACKS, CORROSION, OR OTHER DAMAGE. VISUALLY INSPECT SUPPORTING STRUCTURE ALONG FLOOR, FRAME PERIPHERY, AND CENTERLINE BEAM FOR FATIGUE CRACKS, FASTENER SECURI						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014	5979.4	
	REF: GENERIC NO REF	AFL	6000	+25/-25			4026		
H5230020 (s)	INSPECT TAILCONE EQUIPMENT ACCESS AND TAILCONE BAGGAGE COMPARTMENT DOOR SEALS FOR CUTS, ADHESION, AND ABRASION; LOCKING MECHANISM FOR PROPER OPERATION, HINGES, LATCH PINS, AND RECEPTACLES FOR GENERAL CONDITION AND SECURITY.						PKG		
	PKG 12	MOS	24	+14d/-14d			05-OCT-2018	6634.6	
	REF: GENERIC NO REF	AFL	600	+25/-25			4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H5311000 (s)	INSPECT NOSE GEAR SUPPORT INSTALLATION FOR SECURITY, FASTENER CONDITION, PANEL FATIGUE CRACKS, PERMANENT DEFORMATION AT TRUNNION FITTINGS, ACTUATOR ATTACHMENT SUPPORT STRUCTURE AREAS, AND GENERAL CONDITION. PKG 23 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 16-OCT-2012 4757.3 3315		
H5314031 (s)	FRAMING MEMBERS OF PASSENGER/CREW AND EMERGENCY EXIT/BAGGAGE DOORS AND SURROUNDING FUSELAGE STRUCTURE FOR CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. PKG 24 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 16-OCT-2012 4757.3 3315		
H5321014 (s)	IF INSTALLED, INSPECT ACCESSIBLE AREAS AROUND THE GALLEY, POTTY, AND LAVATORY FOR EVIDENCE OF SPILLAGE. INVESTIGATE FURTHER IF EVIDENCE OF SPILLAGE IS FOUND. PKG 8 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
H5321039 (s)	VISUALLY INSPECT LOWER LONGERON IN REGION OF WING FOR FATIGUE CRACKS, PERMANENT DEFORMATION, AND GENERAL CONDITION. PKG 23 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 16-OCT-2012 4757.3 3315		
H5321042 (s)	BAGGAGE FLOOR/OVER WING AREA: A. INSPECT ENTIRE AREA FOR CORROSION, SECURITY, AND GENERAL CONDITION. INSPECT THE SEGMENTED HONEYCOMB FLOOR SUPPORT ANGLES AT THE OUTBOARD EDGES FOR FATIGUE CRACKS, FASTENER SECURITY, AND GENERAL CONDITION. B. INSPECT FRAME PKG 27 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 02-SEP-2014 5979.4 4026		
H5321048 (s)	BAGGAGE FLOOR/OVER WING AREA (REFER TO 5-10-00.) A. SUPPORT STRUCTURE FOR WING-TO-FUSELAGE FITTINGS. AT EACH LOCATION (SPAR/FRAME) 2/25, 5/27, 7/29, AND 8/30)8 LOCATIONS TOTAL) INSPECT FUSELAGE FRAME STRUCTURE FOR CRACKS, CORROSION, FASTENER CONDITION, P PKG 28 REF: GENERIC NO REF	MOS HRS/MSC AFL	12000	+25/-25			PKG 10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H5321049 (s)	VISUALLY INSPECT OVERWING CUTOUT RADIUS AT FS 346 AND FS 421 (FRAMES 24 AND 31 FUSELAGE SKIN PANELS). (REFER TO 5-10-00.)						PKG		
	PKG 20	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: GENERIC NO REF	AFL					3315		
H5321050 (s)	INSPECT ACCESSIBLE PORTIONS OF LOWER CAP OF THE FRAME 26A AREA, AND ADJACENT FLOOR STRUCTURE, FRAME 24-26A. VISUALLY INSPECT FOR EVIDENCE OF FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION. (REFER TO 5-10-00.)						PKG		
	PKG 17	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
H5323011 (s)	INSPECT CORNER OF DOORS FOR FASTENER SECURITY AND GENERAL CONDITION.						PKG		
	PKG 12	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
H5331010 (s)	INSPECT BULKHEADS, FRAMES, AND STIFFENERS IN THE TAILCONE FOR FASTENER SECURITY, CRACKS, AND GENERAL CONDITION.						PKG		
	PKG 21	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: GENERIC NO REF	AFL					3315		
H5331020 (s)	INSPECT CANTED BULKHEADS AND LOWER VERTICAL STABILIZER ATTACHMENTS IN THE AFT TAILCONE FOR FASTENER SECURITY AND PERMANENT DEFORMATION AT BULKHEADS AND SPAR ASSEMBLIES.						PKG		
	PKG 21	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: GENERIC NO REF	AFL					3315		
J5340001 (s)	EDDY CURRENT FORWARD BEAM SUPPORT FITTING. (REFER TO NDI MANUAL [NDI-2], PART 3, 53-40-01.)						PKG		
	PKG 28	MOS					10-MAY-2002		
		HRS/MSC	12000	+25/-25			0		
	REF: NDT 53-40-01	AFL					0		
J5340002 (s)	VISUAL INSPECTION FORWARD ENGINE BEAM ASSEMBLY. (REFER TO 5-10-00.)						PKG		
	PKG 28	MOS					10-MAY-2002		
		HRS/MSC	12000	+25/-25			0		
	REF: GENERIC NO REF	AFL					0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
J5340003 (s)	VISUAL INSPECTION FORWARD ENGINE BEAM STABILIZER STRUCTURE. (REFER TO 5-10-00.) PKG 28 REF: GENERIC NO REF	MOS HRS/MSC AFL	12000	+25/-25			PKG 10-MAY-2002 0 0		
J5340004 (s)	EDDY CURRENT AFT BEAM SUPPORT FITTING - PERFORM EDDY CURRENT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 3, 53-40-02.) PKG 28 REF: NDT 53-40-02	MOS HRS/MSC AFL	12000	+25/-25			PKG 10-MAY-2002 0 0		
J5340005 (s)	VISUAL INSPECTION AFT ENGINE BEAM - PERFORM VISUAL INSPECTION. (REFER TO 5-10-00.) PKG 28 REF: GENERIC NO REF	MOS HRS/MSC AFL	12000	+25/-25			PKG 10-MAY-2002 0 0		
J5340006 (s)	VISUAL INSPECTION AFT ENGINE BEAM AND FRAME STRUCTURE - PERFORM VISUAL INSPECTION. (REFER TO 5-10-00.) PKG 28 REF: GENERIC NO REF	MOS HRS/MSC AFL	12000	+25/-25			PKG 10-MAY-2002 0 0		
K5321081 (s)	VISUALLY INSPECT FORWARD PRESSURE BULKHEAD FOR CRACKS, LOCAL DEFORMATION, AND FASTENER CONDITION. INSPECT THE TOP CAP AT WINDSHIELD INTERSECTION FOR SECURITY, FATIGUE CRACKS, AND GENERAL CONDITION. PKG 27 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 02-SEP-2014 5979.4 4026		
L5321085 (s)	FORWARD PRESURE BULKHEAD: VISUALLY INSPECT FOR CRACKS, LOCAL DEFORMATION, AND FASTENER CONDITION. INSPECT THE TOP CAP AT WINDSHIELD INTERSECTION FOR SECURITY, FATIGUE CRACKS, AND GENERAL CONDITION. GAIN ACCESS TO THE FORWARD SIDE OF THE FORWARD PRESSURE B PKG 27 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 02-SEP-2014 5979.4 4026		
M5323065 (s)	CIRCUMFERENTIAL SKIN SPLICES: CONDUCT A GENERAL VISUAL INTERNAL AND EXTERNAL INSPECTION OF THE CIRCUMFERENTIAL SKIN SPLICES AT THE FRAMES LISTED BELOW: A. FRAMES 8, 17, 20, 25, AND 26. B. ON AIRCRAFT 60-002, FRAME 12. C. ON AIRCRAFT 60-003 AND SUBSEQUENT, PKG 27 REF: GENERIC NO REF	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 02-SEP-2014 5979.4 4026		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
M5323106 (s)	LONGITUDINAL SKIN SPLICES (PRESSURE CABIN) : A. CONDUCT AN INTERNAL AND EXTERNAL VISUAL INSPECTION OF THE LONGITUDINAL SKIN SPLICES ALONG THE MAIN "T" STRINGERS AT STRINGERS 4L, 6L, 7AL, 18L, 23L, 2R, 6R, 8R, AND 18R. (REFER TO 5-10-00.)						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014	5979.4	
	REF: GENERIC NO REF	AFL	6000	+25/-25			4026		
M5323108 (s)	LONGITUDINAL SKIN SPLICES (PRESSURE CABIN) - PERFORM AN X-RAY INSPECTION OF THE LONGITUDIAL SKIN SPLICES ALONG THE "T" STRINGERS AT STRINGERS 4L, 6L, 18L, 23L, 2R, 6R, AND 18R. (REFER TO NDI MANUAL [NDI-2], PART 2, CHAPTER 53-20-05, 53-20-06, 53-20-07, 53						PKG		
	PKG 28	MOS					10-MAY-2002	0	
	REF: See Workcard	AFL	12000	+25/-25			0		
N5323010 (s)	VISUAL INSPECTION EXTERIOR OF AIRCRAFT. (REFER TO 5-10-00)						PKG		
	PKG 2	MOS	12	+14d/-14d			05-OCT-2018	6634.6	
	REF: GENERIC NO REF	AFL	300	+25/-25			4467		
N5323012 (s)	VISUAL INSPECTION EXTERIOR OF AIRCRAFT. (REFER TO 5-10-00)						PKG		
	PKG 2	MOS	12	+14d/-14d			05-OCT-2018	6634.6	
	REF: GENERIC NO REF	AFL	300	+25/-25			4467		
O5331035 (s)	REMOVE TAIL CONE ACCESS PLATES AND USE A FLASHLIGHT AND MIRROR TO INSPECT INTERNAL TAIL CONE STRUCTURE IN AREA WHERE THE VERTICAL STABILIZER SPARS ATTACH TO THE CANTED FUSELAGE FRAMES. CHECK FOR ATTACHMENT SECURITY, FRAME CRIPPLING, CORROSION, AND FATIGUE CRACKS						PKG		
	PKG 28	MOS					10-MAY-2002	0	
	REF: GENERIC NO REF	AFL	12000	+25/-25			0		
P5311006 (s)	REMOVE NOSE GEAR TRUNNION FITTINGS AND VISUALLY INSPECT NOSE GEAR TRUNNION FITTING AREA IN FORWARD FUSELAGE FOR CRACKS, CORROSION, AND PERMANENT DEFORMATION. EDDY CURRENT INSPECT NOSE GEAR TRUNNION FITTING ATTACH HOLES AND TRUNNION AXLE BOSS. (REFER TO NDI MANUA						PKG		
	PKG 26	MOS					10-MAY-2002	0	
	REF: NDT 53-61-02	AFL	6000	+25/-25			0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5311007 (s)	EDDY CURRENT INSPECT UPPER ATTACHEMNET AREA OF NOSE GEAR ACTUATOR FOR CRACKS, CORROSION, PERMANENT DEFORMATION, AND ATTACHMENY FITTING SECURITY. (REFER TO NDI MANUAL [NDI-2], PART 3, 56-60-01.)						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014	5979.4	
	REF: NDT 53-60-01	AFL	6000	+25/-25			4026		
P5320008 (s)	INSPECT CENTER PEDESTAL AND EQUIPMENT FOR SECURITY AND GENERAL CONDITION. SPOILER, THROTTLE, AND FLAP CONTROLS FOR GENERAL CONDITION AND SERVICEABILITY.						PKG		
	PKG 1	MOS	12	+14d/-14d			05-OCT-2018	6634.6	
	REF: GENERIC NO REF	AFL	300	+25/-25			4467		
P5321087 (s)	AFT PRESSURE BULKHEAD A. GAIN ACCESS TO AND REMOVE AFT PRESSURE BULKHEAD. B. EDDY CURRENT INSPECT THE FORWARD FRAME FLANGE OF FRAM 26A AFT PRESSURE BULKHEAD. (REFER TO NDI MANUAL [NDI-2], PART 3, CHAPTER 53-20-01 AND 53-20-05.) C. EDDY CURRENT INSPECT SUP						PKG		
	PKG 28	MOS					10-MAY-2002	0	
	REF: See Workcard	AFL	12000	+25/-25			0		
P5323162 (s)	VISUALLY INSPECT EXTERNAL LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES FOR EVIDENCE OF FATIGUE CRACKS, WORKING RIVETS, CORROSION, AND GENERAL CONDITION. (REFER TO 5-10-00.)						PKG		
	PKG 25	MOS					25-NOV-2011	4140.97	
	REF: GENERIC NO REF	AFL	3000	+25/-25			2967		
S5230021 (s)	OPERATIONAL CHECK OF TAILCONE BAGGAGE AND TAILCONE ACCESS DOOR WARNING SYSTEMS. (REFER TO 52-70-00).						PKG		
	PKG 12	MOS	24	+14d/-14d			05-OCT-2018	6634.6	
	REF: AMM 52-70-00	AFL	600	+25/-25			4467		
S5314070 (s)	UPPER AND LOWER CABIN DOOR HINGES AND FUSELAGE FRAMING STRUCTURE: A. VISUALLY INSPECT ACCESSIBLESTRUCTURE FOR SECURITY, GENERAL CONDITION, EXCESSIVE WEAR OR LOOSENESS, AND FATIGUE CRACKS. (REFER TO 5-10-00.) B. CONDUCT X-RAY INSPECTION OF UPPER AND LOWER						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014	5979.4	
	REF: NDT 52-20-01	AFL	6000	+25/-25			4026		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
S5323158 (s)	INSPECT EXTERIOR OF THE SKIN, GIVING PARTICULAR ATTENTION TO LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES FOR FASTENER CONDITION, FATIGUE CRACKS, AND GENERAL SPLICE CONDITION.						PKG		
	PKG 20	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: GENERIC NO REF	AFL					3315		
T5321013 (s)	INSPECT ACCESSIBLE PORTION OF FRAME 26A AREA VISIBLE THROUGH WHEEL WELLS FOR FATIGUE CRACKS, PERMANENT DEFORMATION, SECURITY, AND GENERAL CONDITION.						PKG		
	PKG 11	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
T5321093 (s)	INSPECT TAILCONE BAGGAGE COMPARTMENT UPHOLSTERY FOR CUTS, TEARS , AND GENERAL CONDITION.						PKG		
	PKG 15	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
U5323146 (s)	SKIN CUTOUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT SKIN PENETRATIONS AND CUTOUTS FOR ANTENNAS AND ELECTRICAL COMPONENTS. (REFER TO 5-10-00.)						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014		
		HRS/MSC					5979.4		
	REF: GENERIC NO REF	AFL	6000	+25/-25			4026		
U5331012	* REMOVE ACCESS PANELS (TOP OF FUSELAGE) AND PERFORM VISUAL INSPECTION OF ELECTRICAL BOXES FOR SECURITY OF ATTACHMENT, CORROSION, AND GENERAL CONDITION. INSPECT DOUBLERS, FUSELAGE SKIN, INTERIOR FRAMES, AND INTERCOSTALS FOR FATIGUE CRACKS AND GENERAL CONDITION. (AWL*)								
		MOS	49				06-AUG-2015		06-SEP-2019
		HRS/MSC					6288.98		
AIRWORTHINESS	REF: AMM 53-30-02	AFL					4196		
U5360005 (s)	GENERAL VISUAL INSPECTION RADOME AND LIGHTNING DIVERTER STRIPS. (REFER TO 5-10-00)						PKG		
	PKG 2	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
CHAPTER 54	NACELLES/PYLONS								
H5450000 (s)	CHECK PYLON FIREWALLS FOR CRACKS, CONDITION OF FIREWALL SEALANT, SECURITY OF HYDRAULIC AND FUEL CONNECTIONS, ELECTRICAL AND MECHANICAL FEED-THROUGHS, AND CONDITION OF BLEED AIR FLANGE GASKETS.						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H5450002 (s)	VISUAL INSPECTION ENGINE SUPPORT STRUCTURE. (REFER TO 5-10-00.) PKG 28	MOS					PKG 10-MAY-2002		
	REF: GENERIC NO REF	HRS/MSC AFL	12000	+25/-25			0 0		
K5450010 (s)	INSPECT PYLON BEAMS FOR CRACKS, FASTENER CONDITION, ATTACHMENT TO FUSELAGE FRAMES, AND GENERAL CONDITION OF FITTINGS. REMOVE UPPER AND LOWER PYLON ACCESS COVERS FOR COMPLETE INSPECTION. PKG 15	MOS	48	+14d/-14d			PKG 05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25			6634.6 4467		
CHAPTER 55 STABILIZERS									
553001	VERTICAL STABILIZER 5431000-029	MOS					10-MAY-2002		
	453	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
	REF: GENERIC NO REF								
A5510061 (s)	HORIZONTAL STABILIZER (DETACHED FROM VERTICAL STABILIZER): A. CONDUCT A GENERAL VISUAL INSPECTION OF THE STABILIZER ASSEMBLY INCLUDING UPPER AND LOWER SKIN SPLICES AT BL 4.5 RIB, ACCESSIBLE PORTIONS OF FRONT AND REAR SPAR INSTALLATIONS, ELEVATOR HINGE SUP PKG 28	MOS					PKG 10-MAY-2002		
	REF: GENERIC NO REF	HRS/MSC AFL	12000	+25/-25			0 0		
A5510062 (s)	CLEAN AND VISUALLY INSPECT THE HINGE PIN FOR WEAR AND CORROSION (INCLUDING THE INTERNAL SURFACE OF THE PIN). APPLY A COAT OF EPOXY PRIMER TO THE INTERNAL SURFACE OF THE PIN PRIOR TO REINSTALLATION. (REFER TO 5-10-00.) MAGNETIC PARTICLE INSPECT PIN FOR CRACKS. PKG 28	MOS					PKG 10-MAY-2002		
	REF: GENERIC NO REF	HRS/MSC AFL	12000	+25/-25			0 0		
A5520020 (s)	ELEVATOR (REMOVED FROM HORIZONTAL STABILIZER) (REFER TO 5-10-00.): A. CLEAN HINGE LOCATIONS AND VISUALLY INSPECT LOCAL STRUCTURE USING PROPER LIGHTING AND 10X MAGNIFICATION. INSPECT HINGE SUPPORT STRUCTURE FOR DEFORMATION, CORROSION, LOOSE OR WORKING FAST PKG 28	MOS					PKG 10-MAY-2002		
	REF: NDT 55-20-01	HRS/MSC AFL	12000	+14/-14			0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
B5530010 (s)	VERTICAL STABILIZER (ATTACHE DTO FUSELAGE) (REFER TO 5-10-00.): A. CONDUCT A GENERAL VISUAL INSPECTION OF THE VERICAL STABILIZER ABOVE THE FUSELAGE FOR EVIDENCE OF PERMANENT DEFORMATION, CORROSION. LOOSE OR WORKING FASTENERS, FATIGUE CRACKS, AND GENERAL C						PKG		
	PKG 28	MOS					10-MAY-2002		
	REF: GENERIC NO REF	HRS/MSC AFL	12000	+25/-25			0		0
B5540020 (s)	RUDDER (REMOVED FROM VERTICAL STABILIZER) (REFER TO 5-10-00.) A. CLEAN HINGE LOCATIONS AND VISUALLY INSPECT LOCAL STRUCTURE USING PROPER LIGHTING AND 10X MAGNIFICATION. INSPECT HIMGE SUPPORT STRUCTURE FOR DEFORMATION, CORROSION, AND FATIGUE CRACKS. (INCLU						PKG		
	PKG 28	MOS					10-MAY-2002		
	REF: GENERIC NO REF	HRS/MSC AFL	12000	+25/-25			0		0
C5510050 (s)	HORIZONTAL STABILIZER (ATTACHED TO VERTICAL STABILIZER) (REFER TO 5-10-00.) A. WITH ALTERNATING UP AND DOWN LOADS (30 TO 50 LB.) BEING APPLIED TO THE STABILIZER TIP, OBSERVE HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS, HINGE PIN AND FIT						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014		
	REF: GENERIC NO REF	HRS/MSC AFL	6000	+25/-25			5979.4		4026
E5510040 (s)	WITH ALTERNATING UP AND DOWN LOADS (30 TO 50 LBS.) BEING APPLIED TO THE STABILIZER TIP, OBSERVE HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS, HINGE PIN AND FITTINGS, SUPPORT STRUCTURE ATTACHING BOLTS, AND BOLT RETAINERS FOR WEAR, LOOSENE						PKG		
	PKG 18	MOS	48	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25			6634.6		4467
E5520010 (s)	WITH CONTROL COLUMN FIXED, APPLY ALTERNATE UP AND DOWN LOADS TO THE ELEVATOR TRAILING EDGE. INSPECT EACH ELEVATOR HINGE LOCATION FOR LOOSENESS, FREE PLAY, FATIGUE CRACKS, AND GENERAL SECURITY.						PKG		
	PKG 18	MOS	48	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25			6634.6		4467
E5540010 (s)	WITH RUDDER PEDALS RESTRAINED, APPLY ALTERNATING LEFT AND RIGHT LOADS TO THE RUDDER TRAILING EDGE. OBSERVE RUDDER HINGE FITTING ATTACHMENTS FOR LOOSENESS, FREE PLAY, AND GENERAL SECURITY.						PKG		
	PKG 18	MOS	48	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25			6634.6		4467

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H5510031 (s)	REMOVE ACCESS PANELS AND INSPECT UPPER AND LOWER FLANGES OF HORIZONTAL STABILIZER RIBS AT RIGHT AND LEFT BUTT LINE 19.4 FOR CRACKS.						PKG		
	PKG 18	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
H5510035 (s)	INSPECT HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS (INCLUDING ATTACH BOLTS), SUPPORT STRUCTURE, AND ATTACH BOLT RETAINING CLIPS (IF INSTALLED) FOR CRACKS, FASTENER CONDITION, SECURITY, WEAR, AND GENERAL CONDITION.						PKG		
	PKG 18	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
H5520000 (s)	ELEVATOR: WITH PUSH-PULL TUBES DISCONNECTED FROM ELEVATOR BELLCRANKS, MOVE EACH ELEVATOR SURFACE THROUGH THE ENTIRE DEFLECTION RANGE. CHECK FOR SMOOTHNESS OF OPERATION, EXCESSIVE FRICTION, ROUGH BEARINGS, RUST OR CORROSION, TURNING ON BOLT RATHER THAN BEA						PKG		
	PKG 24	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: GENERIC NO REF	AFL					3315		
H5530001 (s)	VERTICAL STABILIZER FOR CRACKS, FASTENER CONDITION, AND SECURITY AT ATTACH POINTS, AND STRUCTURE IN AREA OF HORIZONTAL STABILIZER ATTACH FITTINGS.						PKG		
	PKG 18	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
H5540011 (s)	RUDDER: WITH CABLES DISCONNECTED AT AFT BELLCRANK LOCATION, MOVE RUDDER THROUGH THE ENTIRE DEFLECTION RANGE. CHECK FOR AMOOTHNESS OF OPERATION, EXCESSIVE FRICTION, ROUGH BEARINGS, TURNING ON BOLT RATHER THAN BEARING, RUST OR CORROSION, AND GENERAL CONDITI						PKG		
	PKG 24	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: GENERIC NO REF	AFL					3315		
H5560001 (s)	VISUALLY INSPECT THE DELTA FIN SURFACES. REMOVE TAILCONE ACCESS COVERS AND VISUALLY INSPECT SUPPORT STRUCTURE FOR LOOSE OR MISSING FASTENERS, FATIGUE CRACKS, PERMANENT DEFORMATION, AND CORROSION. INSPECT UPPER AND LOWER SURFACES, PAYING PARTICULAR ATTENTION TO THE TAILCON						PKG		
	PKG 21	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: GENERIC NO REF	AFL					3315		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
M5530003 (s)	VERTICAL STABILIZER (ATTACHED TO FUSELAGE) (REFER TO 5-10-00.) A. CONDUCT A VISUAL INSPECTION OF THE VERTICAL STABILIZER ABOVE THE FUSLEAGE FOR EVIDENCE OF PERMANENT DEFORMATION, CORROSION, LOSE OR WORKING FASTENERS, FATIGUE CRACKS, AND GENERAL CONDITION.						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014	5979.4	
	REF: GENERIC NO REF	AFL	6000	+25/-25			4026		
O5510060 (s)	HORIZONTAL STABILIZER (ATTACHED TO VERTICAL STABILIZER): WITH ALTERNATING UP AND DOWN LOADS (30 TO 50 LBS.) BEING APPLIED TO THE STABILIZER TIP, OBSERVE HORIZONTAL STABILIZER ACTUATOR UPPER AND LOWER ATTACH FITTINGS, HINGE PIN AND FITTINGS, SUPPORT STRUCT						PKG		
	PKG 28	MOS					10-MAY-2002	0	
	REF: GENERIC NO REF	AFL	12000	+25/-25			0		
P5510089 (s)	CONDUCT A THOROUGH EXTERNAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER FORWARD AND REAR SPAR CAPS (UPPER AND LOWER) FOR CORROSION, INTEGRITY OF PAINT, AND GENERAL CONDITION. (ELEVATOR REMOVAL NOT REQUIRED.) (REFER TO 5-10-00)						PKG		
	PKG 6	MOS	12	+14d/-14d			05-OCT-2018	6634.6	
	REF: GENERIC NO REF	AFL	300	+25/-25			4467		
T5500002 (s)	INSPECT RUDDER, RUDDER TAB, AND ELEVATOR HINGE POINTS FOR EVIDENCE OF WEAR, SECURITY, AND GENERAL CONDITION. WHEN INSTALLING VERTICAL STABILIZER AFT FAIRING, ENSURE THAT ELEVATOR TO FAIRING CLEARANCE IS 0.31 (+0.12) INCH [7.9 (+3) MM].						PKG		
	PKG 18	MOS	48	+14d/-14d			05-OCT-2018	6634.6	
	REF: GENERIC NO REF	AFL	1200	+25/-25			4467		
U5500000 (s)	GENERAL VISUAL INSPECTION FILLETS, FAIRINGS, AND SKINS. (REFER TO 5-10-00)						PKG		
	PKG 6	MOS	12	+14d/-14d			05-OCT-2018	6634.6	
	REF: GENERIC NO REF	AFL	300	+25/-25			4467		
U5560000 (s)	GENERAL VISUAL INSPECTION DELTA FINS. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018	6634.6	
	REF: GENERIC NO REF	AFL	600	+25/-25			4467		

CHAPTER 56		WINDOWS							
05-10-29-C5610022L	PRISM CHECK LEFT								
	6600394-003	MOS					11-JUN-2004		
	205	HRS/MSC	C/C				608		
	REF: NDT 56-10-01	AFL					500		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-29-C5610022R	PRISM CHECK RIGHT 6600394-004 498 REF: NDT 56-10-01	MOS HRS/MSC AFL	C/C				10-AUG-2011 3848.65 2794		
05-10-29-M5600008	INSPECT CABIN WINDOWS REF: NDT 56-50-01	MOS HRS/MSC AFL	C/C	TSI:0			11-JUN-2004 500		
561001	LEFT WINDSHIELD ASSY 6600394-003 205 REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
561002	RIGHT WINDSHIELD ASSY 6600394-004 498 REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			17-AUG-2010 3263.28 2431		
561009	LEFT COCKPIT CREW WINDOW 6600512-001 126 REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
561010	RIGHT COCKPIT CREW WINDOW 6600512-002 117 REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
562011	LEFT NO. 1 CABIN WINDOW PAS6600405-10 11303 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			25-NOV-2011 4140.97 2967		
562011A	PRISM CHECK LEFT NO. 1 CABIN WINDOW 05-10-29-M5600008 PAS6600405-10 11303 REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C				16-OCT-2012 4757.3 3315		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562013	LEFT NO. 2 CABIN WINDOW LA6600405-32 1012 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:2 TSN:0 TSN:0			16-OCT-2012 4757.3 3315		
562013A	PRISM CHECK LEFT NO. 2 CABIN WINDOW 05-10-29-M5600008 LA6600405-32 1012 REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C				16-OCT-2012 4757.3 3315		
562015	LEFT NO. 3 CABIN WINDOW LA6600405-20 1950 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-APR-2008 2360.78 1868		
562015A	PRISM CHECK LEFT NO. 3 CABIN WINDOW 05-10-29-M5600008 LA6600405-20 1950 REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C				02-FEB-2010 2929.12 2246		
562017	LEFT NO. 4 CABIN WINDOW LA6600405-32 1017 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:2 TSN:0 TSN:0			16-OCT-2012 4757.3 3315		
562017A	PRISM CHECK LEFT NO. 4 CABIN WINDOW 05-10-29-M5600008 LA6600405-32 1017 REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C				16-OCT-2012 4757.3 3315		
562019	LEFT NO. 5 CABIN WINDOW LA6600405-19 2278 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-APR-2008 2360.78 1868		
562019A	PRISM CHECK LEFT NO. 5 CABIN WINDOW 05-10-29-M5600008 LA6600405-19 2278 REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C				02-FEB-2010 2929.12 2246		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562022	RIGHT NO. 1 CABIN WINDOW PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
562022A	PRISM CHECK RIGHT NO. 1 CABIN WINDOW PN SN-UNKNOWN REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C				11-JUN-2004 608 500		
562024	RIGHT NO. 2 CABIN WINDOW LA6600405-20 1956 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-APR-2008 2360.78 1868		
562024A	PRISM CHECK RIGHT NO. 2 CABIN WINDOW LA6600405-20 1956 REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C				02-FEB-2010 2929.12 2246		
562026	RIGHT NO. 3 CABIN WINDOW LA6600405-32 1013 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:2 TSN:0 TSN:0			16-OCT-2012 4757.3 3315		
562026A	PRISM CHECK RIGHT NO. 3 CABIN WINDOW LA6600405-32 1013 REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C				16-OCT-2012 4757.3 3315		
562028	RIGHT NO. 4 CABIN WINDOW LA6600405-20 1979 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-APR-2008 2360.78 1868		
562028A	PRISM CHECK RIGHT NO. 4 CABIN WINDOW LA6600405-20 1979 REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C				02-FEB-2010 2929.12 2246		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562030	RIGHT NO. 5 CABIN WINDOW LA6600405-20 1971 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-APR-2008 2360.78 1868		
562030A	PRISM CHECK RIGHT NO. 5 CABIN WINDOW LA6600405-20 1971 REF: NDT 56-30-01	MOS HRS/MSC AFL	C/C	05-10-29-M5600008			02-FEB-2010 2929.12 2246		
H5610024 (s)	WINDSHIELDS AND FOUL WEATHER WINDOWS (INSTALLED IN FUSELAGE) A. CLEAN INTERIOR AND EXTERIOR SURFACE OF WINDSHIELDS. B. CONDUCT A GENERAL VISUAL INSPECTION OF THE ACCESSIBLE AREAS OF THE WINDSHIELDS AND BOTH FOUL WEATHER WINDOWS FOR DELAMINATION, CHIPPING, PKG 24 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 16-OCT-2012 4757.3 3315		
H5620000 (s)	PERFORM AN EXTERNAL VISUAL INSPECTION OF THE CABIN WINDOWS AND RETAINERS FOR GENERAL CONDITION, SECURITY, AND CLEANLINESS. INSPECT INTERNAL AND EXTERNAL SURFACES OF THE CABIN WINDOWS FOR SCRATCHES, PITS, OR OTHER DAMAGE. (REFER TO 56-20-01) PKG 8 REF: AMM 56-20-01	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
M5610010 (s)	WINDSHIELDS AND FOUL WEATHER WINDOWS (INSTALLED IN FUSELAGE): A. CLEAN INTERIOR AND EXTERIOR SURFACE OF WINDSHIELDS IN ACCORDANCE WITH CHAPTER 12. CONDUCT A GENERAL VISUAL INSPECTION OF THE ACCESSIBLE AREAS OF THE WINDSHIELDS AND BOTH FOUL WEATHER WINDOWS PKG 27 REF: See Workcard	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 02-SEP-2014 5979.4 4026		
M5620001 (s)	CABIN WINDOWS AND FRAMING MEMBERS: A. VISUALLY INSPECT ACCESSIBLE STRUCTURE FOR SECURITY, GENERAL CONDITION, AND FATIGUE CRACKS. (REFER TO 5-10-00.) B. CONDUCT X-RAY INSPECTION OF SUPPORT STRUCTURE. (REFER TO NDI MANUAL [NDI-2], PART 2, 56-50-01.) PKG 27 REF: NDT 56-50-01	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			PKG 02-SEP-2014 5979.4 4026		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T5610002 (s)	INSPECT INTERIOR AND EXTERIOR OF WINDSHIELD FOR CRAZING, INCLUDING VISIBLE PORTION UNDER RETAINERS FOR CRACKS, CLEANLINESS, SECURITY, AND GENERAL CONDITION. AREA UNDER ANTI-ICE DUCT SHALL BE INSPECTED BY VIEWING THE EPOXY-PRIMED OUTER SURFACE OF THE WINDSHIELD FR						PKG		
	PKG 14	MOS	48	+14d/-14d			05-OCT-2018		
	REF: See Workcard	HRS/MSC	1200	+25/-25			6634.6		
		AFL					4467		
T5620007 (s)	CABIN WINDOWS: USING PRISM TECHNIQUES, INSPECT WINDOWS FOR CRACKS, CHIPS, DELAMINATION, OR OTHER DAMAGE. THIS INSPECTION IS ALSO CAPABLE OF VISUALLY ASSESSING THE CONDITION OF THE ATTACHING FASTENERS. BROWN DISCOLORATIONS IN THE AREA OF THE FASTENERS MAY						PKG		
	PKG 24	MOS	96	+14d/-14d			16-OCT-2012		
	REF: NDT 56-30-01	HRS/MSC	2400	+25/-25			4757.3		
		AFL					3315		
CHAPTER 57 WINGS									
05-10-29-L5720012L	PERFORM LEFT FLAP SUPPORT FITTING-TITANIUM EDDY CURRENT INSPECTION								
		MOS					10-MAY-2002		
	REF: NDT 57-40-03	HRS/MSC					0		
		AFL	10000	+25/-25			0	10000	10025
05-10-29-L5720012R	PERFORM RIGHT FLAP SUPPORT FITTING-TITANIUM EDDY CURRENT INSPECTION								
		MOS					10-MAY-2002		
	REF: NDT 57-40-03	HRS/MSC					0		
		AFL	10000	+25/-25			0	10000	10025
570001	LEFT WING								
	PN	MOS		TSN:0			10-MAY-2002		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-00-01	AFL		TSN:0			0		
570002	RIGHT WING								
	PN	MOS		TSN:0			10-MAY-2002		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-00-01	AFL		TSN:0			0		
572001	LEFT WINGLET ASSEMBLY								
	2822650-43	MOS		TSN:0			10-MAY-2002		
	326	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 57-20-01	AFL		TSN:0			0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
572002	RIGHT WINGLET ASSEMBLY 2822650-44 335 REF: AMM 57-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
572003	LEFT WING LEADING EDGE PN SN-UNKNOWN REF: AMM 57-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
572004	RIGHT WING LEADING EDGE PN SN-UNKNOWN REF: AMM 57-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
572025	LEFT FRONT WINGLET SPAR FITTING 6022621-1 H0014 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
572026	RIGHT FRONT WINGLET SPAR FITTING 6022621-2 H0023 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
572027	LEFT AFT WINGLET SPAR FITTING 6022622-1 H0024 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
572028	RIGHT AFT WINGLET SPAR FITTING 6022622-2 R414 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
A5710045 (s)	REMOVE LOWER SURFACE ACCESS PLATES FROM WS 92 INBOARD TO BL 0.0 INCLUDING FUEL PUMPS AT WS 6.0 AND 11.0. VISUALLY INSPECT THE PERIPHERY OF THESE CUTOUTS FOR FATIGUE CRACKS, CORROSION, AND GENERAL CONDITION. (REFER TO 5-10-00.) CONDUCT EDDY CURRRENT INSPECTIONS A PKG 28 REF: NDT 57-10-01	MOS HRS/MSC AFL	12000	+25/-25			10-MAY-2002 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A5710070 (s)	CLEAN UPPER AND LOWER CENTERLINE SPLICE PLATE (SPAR 2 TO 5 AND 7 TO 8) ADJACENT TO BL 0.0 RIB CAP. VISUALLY INSPECT THESE AREAS FOR CORROSION, FATIGUE CRACKS, WORKING FASTENERS, AND GENERAL SECURITY. (REFER TO 5-10-00)						PKG		
	PKG 28	MOS					10-MAY-2002		
	REF: GENERIC NO REF	HRS/MSC AFL	12000	+25/-25			0		0
A5760010 (s)	AILERON (REMOVED FROM WING) (REFER TO 5-10-00.)						PKG		
	PKG 28	MOS					10-MAY-2002		
	REF: GENERIC NO REF	HRS/MSC AFL	12000	+25/-25			0		0
B5710050 (s)	CONDUCT AN X-RAY INSPECTION OF THE WING UPPER AND LOWER STRUCTURE IN THE CENTERLINE DOUBLER AREA. INSPECT FOR FATIGUE CRACKS, CORROSION, LOOSE OR MISSING FASTENERS, AND GENERAL SECURITY. (REFER TO NDI MANUAL [NDI-2], PART 2, 57-20-01 AND 57-21-01.)						PKG		
	PKG 28	MOS					10-MAY-2002		
	REF: See Workcard	HRS/MSC AFL	12000	+25/-25			0		0
C5710040 (s)	CLEAN AND CONDUCT A GENERAL EXTERNAL AND INTERNAL VISUAL INSPECTION OF THE WING CENTER SECTION, PAYING PARTICULAR ATTENTION TO THE LOWER SKIN AT THE FUEL PUMP LOCATIONS AND THE SPLICE DETAILS AT BL 0.0, AS ACCESSIBLE. INSPECT FOR EVIDENCE OF AFTIGUE CRACKS, COR						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014		
	REF: GENERIC NO REF	HRS/MSC AFL	6000	+25/-25			5979.4		4026
C5710055 (s)	CONDUCT AN X-RAY INSPECTION OF THE WING UPPER STRUCTURE INBOARD OF THE WING-TO-FUSELAGE FITTINGS AND FORWARD OF SPAR 5. INSPECT FOR CORROSION, FATIGUE CRACKS, LOOSE OR MISSING FASTENERS, AND GENERAL CONDITION. IF CORROSION IS FOUND, WING REMOVAL FROM FUSELAGE MAY						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014		
	REF: NDT 57-12-01	HRS/MSC AFL	6000	+25/-25			5979.4		4026
C5710060 (s)	CONDUCT AN EDDY CURRENT INSPECTION FOR THE FOLLOWING WING STRUCTURAL AREAS: SURFACE OF ACCESSIBLE AREAS OF LOWER DOUBLER FROM BL 0.0 TO OUTBOARD END OF DOUBLER ALONG SPARS 4, 5, AND 7, AND LOWER SKIN ADJACENT TO THE OUTBOARD 2 INCHES OF DOUBLER FINGERS. SKIN ADJA						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014		
	REF: NDT 57-12-01	HRS/MSC AFL	6000	+25/-25			5979.4		4026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C5710062 (s)	REMOVE THE ACCESS COVER AT WS 73.0 BETWEEN SPARS 4/5 AND 6/7. INSPECT ALL HOLES AT THIS LOCATION IN THE SPAR AND SKIN USING AN EDDY CURRENT HOLE PROBE. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-12-01.)						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014	5979.4	4026
	REF: GENERIC NO REF	AFL	6000	+25/-25					
C5710065 (s)	EDDY CURRENT AREA AROUND FASTENERS COMMON TO TRUNNION FITTINGS. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-12-01, AREAS E AND D.)						PKG		
	PKG 25	MOS					25-NOV-2011	4140.97	2967
	REF: NDT 57-12-01	AFL	3000	+25/-25					
C5720020 (s)	VISUALLY INSPECT INTERNAL AND EXTERNAL AREA OF WING WHEEL WELL STRUCTURE, PAYING PARTICULAR ATTENTION TO THE MAIN LANDING GEAR ACTUATOR UPPER ATTACHMENT AND LANDING GEAR RIB STRUCTURE AT WS 53.04. (REFER TO 5-10-00.)						PKG		
	PKG 27	MOS	144	+14d/-14d			29-SEP-2014	5979.4	4026
	REF: GENERIC NO REF	AFL	6000	+25/-25					
C5720025 (s)	X-RAY INSPECT THE OUTBOARD LOWER WING SKIN FROM WS 31 TO WS 61. (REFER TO NDI MANUAL [NDI-2], PART 2, 57-30-01.)						PKG		
	PKG 27	MOS	144	+14d/-14d			29-SEP-2014	5979.4	4026
	REF: NDT 57-30-01	AFL	6000	+25/-25					
C5720040 (s)	INSPECT THE JOINT AT WS 181 THAT SPLICES THE WING TO THE OUTER WING EXTENSION. VISUALLY INSPECT FOR LOOSE OR MISSING FASTENERS, FATIGUE CRACKS, CORROSION, AND GENERAL SECURITY. (REFER TO 5-10-00.)						PKG		
	PKG 27	MOS	144	+14d/-14d			29-SEP-2014	5979.4	4026
	REF: GENERIC NO REF	AFL	6000	+25/-25					
C5740001 (s)	WITH LEADING EDGE ASSEMBLIES REMOVED, INSPECT FORWARD SIDE OF SPAR 1 FOR EVIDENCE OF FATIGUE CRACKS, OVERHEAT (DISCOLORED PRIMER), GENERAL CORROSION, LOOSE OR MISSING FASTENERS, FIFLIFORM CORROSION, AND GENERAL CONDITION.						PKG		
	PKG 27	MOS	144	+14d/-14d			29-SEP-2014	5979.4	4026
	REF: GENERIC NO REF	AFL	6000	+25/-25					

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C5740002 (s)	WITH LEADING EDGE LOWER CUFF FAIRING ASSEMBLIES REMOVED, INSPECT LOWER WING SKIN COVERED BY CUFF FAIRING AND INNER SURFACE OF CUFF FOR EVIDENCE OF FATIGUE CRACKS, LOOSE OR MISSING FASTENERS, CORROSION, AND GENERAL CONDITION.						PKG		
	PKG 27	MOS	144	+14d/-14d			29-SEP-2014		
	REF: GENERIC NO REF	HRS/MSC					5979.4		
		AFL	6000	+25/-25			4026		
E5710066 (s)	CONDUCT A VISUAL AND EDDY CURRENT INSPECTION OF THE FOLLOWING LOWER WING STRUCTURAL AREAS						PKG		
	PKG 28	MOS					10-MAY-2002		
	REF: See Workcard	HRS/MSC	12000	+25/-25			0		
		AFL					0		
E5710071 (s)	CONDUCT AN EDDY CURRENT INSPECTION OF THE LOWER SPLICE PLATE ALONG THE CENTERLINE FASTENER ROWS. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-10-01)						PKG		
	PKG 28	MOS					10-MAY-2002		
	REF: GENERIC NO REF	HRS/MSC	12000	+25/-25			0		
		AFL					0		
E5720010 (s)	INSPECT FLAP SECTOR SUPPORT BRACKETS AND FLAP ACTUATOR SUPPORT FLAP BRACKET FOR CRACKS, DISTORTION, INTERFERENCE, AND FASTENER CONDITION. (REFER TO 57-40-03).						PKG		
	PKG 10	MOS	24	+14d/-14d			05-OCT-2018		
	REF: AMM 57-40-03	HRS/MSC	600	+25/-25			6634.6		
		AFL					4467		
E5750020 (s)	WITH FLAPS EXTENDED, APPLY ALTERNATE UP AND DOWN LOADS TO FLAP TRAILING EDGE. INSPECT INBOARD AND OUTBOARD FLAP TRACKS AND NOSE ROLLER SUPPORT STRUCTURE CRACKS, DISTORTION, FASTENER CONDITION, EVIDENCE OF CHAFING OR INTERFERENCE, AND GENERAL SECURITY.						PKG		
	PKG 16	MOS	48	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC	1200	+25/-25			6634.6		
		AFL					4467		
E5750030 (s)	INSPECT FLAP NOSE ROLLER BUSHINGS. REPLACE FLAP NOSE ROLLER IF WORN TO A DIAMETER LESS THAN 0.744 INCH. REPLACE FLAP NOSE ROLLER TRACK IF SLOT EXCEEDS 0.775 INCH AT ANY POINT WITH FLAPS FULLY EXTENDED. ENSURE THAT A POSITIVE CLEARANCE EXISTS BETWEEN NOSE ROLLERS						PKG		
	PKG 16	MOS	48	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC	1200	+25/-25			6634.6		
		AFL					4467		
E5750060 (s)	CLEAN AND VISUALLY INSPECT FLAP ATTACH FITTING (CASTINGS ATTACHED TO FLAP SPAR) FOR CRACKS. (REFER TO 5-10-00.) (SEE FIGURE 3.)						PKG		
	PKG 16	MOS	48	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC	1200	+25/-25			6634.6		
		AFL					4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E5770010 (s)	INSPECT SPOILER CENTER HINGE BRACKETS (ATTACHED TO WING SPAR 8) FOR CRACKS EMANATING FROM THE BOLT HOLE AND/OR BRACKET BEND RELIEF. INSPECT BOLT HOLE FOR ELONGATION OR DISTORTION.						PKG		
	PKG 10	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
G5720021 (s)	VISUALLY INSPECT INTERNAL AND EXTERNAL AREAS OF WING STRUCTURE ADJACENT TO LANDING GEAR RIB WS 53.04 (BETWEEN SPARS 4 AND 8). INSPECT TRUNNION FITTINGS FOR LOOSE OR MISSING FASTENERS, FATIGUE CRACKS, CORROSION, ELONGATION OF TRUNNION PIN HOLES, AND GENERAL SECURITY. CHECK						PKG		
	PKG 26	MOS					10-MAY-2002		
		HRS/MSC					0		
	REF: GENERIC NO REF	AFL	6000	+25/-25			0		
H5750000 (s)	INSPECT TRAILING EDGE REGION OF WING FOR LOCAL DEFORMATION AFFECTING NORMAL USAGE OF FLAP ANDAILERON.						PKG		
	PKG 22	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: GENERIC NO REF	AFL					3315		
H5750047 (s)	FLAP (REMOVED FROM WING) VISUALLY INSPECT THE FOLLOWING (REFER TO 5-10-00): A. FLAP SUPPRT FOR SECURITY, CORROSION, FATIGUE CRACKS, WEAR, EVIDENCE OF INTERFERENCE, AND GENERAL CONDITION. INSPECT THE FLAP SECTOR AND SUPPORTIN BRACKERTY FOR EVIDENCE OF OVER						PKG		
	PKG 25	MOS					25-NOV-2011		
		HRS/MSC					4140.97		
	REF: GENERIC NO REF	AFL	3000	+25/-25			2967		
J5720011 (s)	FLAP SUPPORT FITTING (ALUMINUM, P/N 6022521-1 THRU 6022521-8) - OERFORM EDDY CURRENT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 3, 57-40-02.)						PKG		
	PKG 16	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: NDT 57-40-02	AFL					4467		
K5730012 (s)	DETAILED INSPECTIONAILERON BRUSH SEALS. (REFER TO 57-30-07)						PKG		
	PKG 4	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: AMM 57-30-07	AFL					4467		
N5700004 (s)	VISUAL INSPECTION WING SURFACE, WING TO FUSELAGE FAIRING AND WINGLET EXTERIOR. (REFER TO 5-10-00)						PKG		
	PKG 4	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5710140 (s)	REMOVE UPPER WING-TO-FUSELAGE FAIRINGS AND INSPECT WING SKINS, WING TO FUSELAGE ATTACH FITTINGS, AND ADJACENT STRUCTURE FOR CORROSION, FASTENER SECURITY, CRACKS, PERMANENT DEFORMATION, PROTECTIVE COATING, AND GENERAL CONDITION. EXAMINE EXPOSED EDGE OF HONEYCOMB						PKG		
	PKG 22	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: GENERIC NO REF	AFL					3315		
P5710141 (s)	INSPECT WING-TO-FUSELAGE ATTACH POINTS FOR SECURITY (THAT PORTION VISIBLE THROUGH WHEEL WELLS).						PKG		
	PKG 23	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: GENERIC NO REF	AFL					3315		
P5710142 (s)	WITH WING-TO-FUSELAGE FAIRING REMOVED, CLEAN AND VISUALLY INSPECT ALL EIGHT WING-TO-FUSELAGE FITTINGS (FOUR PER SIDE). USING A 10X MAGNIFYING GLASS, ADEQUATE LIGHTING, AND MIRROR, INSPECT FITTINGS AND SUPPORT STRUCTURES FOR FATIGUE CRACKS, DEFORMATION, CO						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014		
		HRS/MSC					5979.4		
	REF: GENERIC NO REF	AFL	6000	+25/-25			4026		
P5710143 (s)	CLEAN CLEAN AND VISUALLY INSPECT, USING 10X MAGNIFICATION AND ADEQUATE LIGHTING, ALL EIGHT WING/FUSELAGE FITTINGS (FOUR PER SIDE) AND SUPPORT STRUCTURE FOR FATIGUE CRACKS, DEFORMATION, CORROSION, MARKS, SCRATCHES, FASTENER WORKING, AND GENERAL SECURITY. (REFER TO 5-10-00.)						PKG		
	PKG 28	MOS					10-MAY-2002		
		HRS/MSC	12000	+25/-25			0		
	REF: NDT 57-13-01	AFL					0		
P5710144 (s)	INSPECT WHEEL WELL AND CENTER SECTION OF WING FOR GENERAL CONDITION OF SKIN, SPARS, ATTACH FITTINGS AND SUPPORTING STRUCTURE, LANDING GEAR RIB, AND TRUNNION FITTINGS. CHECK FOR DEFORMATION, FATIGUE CRACKS, PROTECTIVE FINISH CONDITION, AND GENERAL SECURITY.						PKG		
	PKG 23	MOS	96	+14d/-14d			16-OCT-2012		
		HRS/MSC	2400	+25/-25			4757.3		
	REF: GENERIC NO REF	AFL					3315		
P5710146 (s)	INSPECT UPPER PORTION OF BL 0.0 RIB CAP, JUST FORWARD OF SPAR 7. INSPECT FOR ANY EVIDENCE OF CORROSION, PRIMER BLISTERING, AND CONDITION OF PRIMER SURFACE. (SEE FIGURE 2.)						PKG		
	PKG 16	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P5750050 (s)	INSPECT FLAP UPPER AND LOWER SURFACES FOR SKIN CRACKS, LOOSE RIVETS, AND OTHER DAMAGE. CHECK NOSE ROLLERS FOR FREEDOM OF ROTATION. PAY PARTICULAR ATTENTION TO NOSE ROLLER SUPPORT STRUCTURE FOR CRACKS.						PKG		
	PKG 4	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
U5720071 (s)	GENERAL VISUAL INSPECTION STALL FENCES, STALL STRIPS, WING STALL TRIANGLES, AND BOUNDARY LAYER ENERGIZERS. (REFER TO 5-10-00.)						PKG		
	PKG 4	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
CHAPTER 71 POWER PLANT									
05-11-00-E7120049L	REPLACE * NO. 1 ENGINE AFT MOUNT ATTACH BOLTS (AWL*)								
		MOS					10-MAY-2002		
		HRS/MSC	20000				0		20000
LIFE LIMIT	REF: AMM 71-20-10	AFL					0		
05-11-00-E7120049R	REPLACE * NO. 2 ENGINE AFT MOUNT ATTACH BOLTS (AWL*)								
		MOS					10-MAY-2002		
		HRS/MSC	20000				0		20000
LIFE LIMIT	REF: AMM 71-20-10	AFL					0		
05-11-00-G7110021L	REPLACE LEFT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA								
		MOS					29-MAY-2007		
		HRS/MSC	O/C				2056.55		
TEFLON	REF: AMM 28-00-00	AFL					1653		
05-11-00-G7110021R	REPLACE RIGHT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA								
		MOS					29-MAY-2007		
		HRS/MSC	O/C				2056.55		
TEFLON	REF: AMM 28-00-00	AFL					1653		
05-11-00-G7110022L	REPLACE LEFT HYDRAULIC HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIRE-WALL)								
		MOS					29-MAY-2007		
		HRS/MSC	O/C				2056.55		
TEFLON	REF:	AFL					1653		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-11-00-G7110022R	REPLACE RIGHT HYDRAULIC HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIRE-WALL)	MOS					29-MAY-2007		
TEFLON	REF:	HRS/MSC AFL	O/C				2056.55 1653		
05-11-00-M7120048L	REPLACE NO. 1 ENGINE * FORWARD ENGINE MOUNT ATTACH BOLTS (70315-12-986, 83648-8-18, 77458-8-69, RA22021-8-69, AIC457-8-69, AND PBF1340-8-69) (AWL*)	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 71-20-05	HRS/MSC AFL	20000				0 0	20000	
05-11-00-M7120048R	REPLACE NO. 2 ENGINE * FORWARD ENGINE MOUNT ATTACH BOLTS (70315-12-986, 83648-8-18, 77458-8-69, RA22021-8-69, AIC457-8-69, AND PBF1340-8-69) (AWL*)	MOS					10-MAY-2002		
LIFE LIMIT	REF: AMM 71-20-05	HRS/MSC AFL	20000				0 0	20000	
711005	LEFT ENGINE INLET COWL	MOS					08-JUL-2016		
	282-0211-505	HRS/MSC	O/C	TSN:170			6419		
	0638	AFL		TSN:6419			4301		
	REF: AMM 71-10-05			TSN:4301					
711006	RIGHT ENGINE INLET COWL	MOS					19-MAR-2011		
	282-0211-507	HRS/MSC	O/C	TSN:106			3580.3		
	0639	AFL		TSN:3580.3			2618		
	REF: AMM 71-10-05			TSN:2618					
711015	LEFT ENGINE PYLON APRON ASSEMBLY	MOS					10-MAY-2002		
	266-0213-511	HRS/MSC	O/C	TSN:0			0		
	638	AFL		TSN:0			0		
	REF: AMM 71-10-15			TSN:0					
711016	RIGHT ENGINE PYLON APRON ASSEMBLY	MOS					10-MAY-2002		
	266-0213-512	HRS/MSC	O/C	TSN:0			0		
	639	AFL		TSN:0			0		
	REF: AMM 71-10-15			TSN:0					

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
711021	LEFT ENGINE OUTER FAN DUCT 266-0075-517 CFND0190 REF: AMM 71-10-20	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
711022	RIGHT ENGINE OUTER FAN DUCT 266-0075-519 CFNR0190 REF: AMM 71-10-20	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
712005	LEFT ENGINE FORWARD UPPER VIBRATION ISOLATOR 266D0820-501 LK0913 REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
712006	RIGHT ENGINE FORWARD UPPER VIBRATION ISOLATOR 266D0820-505 LK0981 REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
712007	LEFT ENGINE FORWARD LOWER VIBRATION ISOLATOR 266D0820-505 LK0988 REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
712008	RIGHT ENGINE FORWARD LOWER VIBRATION ISOLATOR 266D0820-501 LK0862 REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
712011	LEFT ENGINE AFT VIBRATION ISOLATOR 266D0820-503 LK0820 REF: AMM 71-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
712012	RIGHT ENGINE AFT VIBRATION ISOLATOR 266D0820-503 LK0875 REF: AMM 71-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71EN1	NO. 1 ENGINE 31B4067-02 PCE-305018 REF: See Workcard	MOS HRS/MSC AFL	E/C	TSN:9032.8			22-MAR-2016 6382.8 4275		
71EN2	NO. 2 ENGINE 31B4067-02 PCE-305110 REF: See Workcard	MOS HRS/MSC AFL	E/C	TSN:9654.5			22-MAR-2016 6382.8 4275		
E7100004 (s)	VISUAL INSPECTION OF ALL BLEED AIR DUCTS, LINES, HOSES, AND ELECTRICAL WIRING IN THE ENGINE NACELLE. INSPECT FOR SECURITY, CLAMPING, ROUTING, CLEARANCE, EVIDENCE OF LEAKS, AND GENERAL CONDITION. (REFER TO 5-10-00)	PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25		05-OCT-2018 6634.6 4467		
E7100016 (s)	INSPECT HOLD OPEN RODS FOR SECURITY OF INSTALLATION AND EVIDENCE OF DAMAGE.	PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25		05-OCT-2018 6634.6 4467		
E7100020 (s)	REMOVE IGNITER ACCESS PANEL AND INSPECT CORE COWL FOR FAILED FASTENERS, SECURITY, AND EVIDENCE OF DAMAGE.	PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25		05-OCT-2018 6634.6 4467		
E7100022 (s)	INSPECT IGNITER ACCESS PANEL FOR FAILED FASTENERS, SECURITY, AND EVIDENCE OF DAMAGE.	PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25		05-OCT-2018 6634.6 4467		
E7100030 (s)	INSPECT FUEL, HYDRAULIC, FIRE EXTINGUISHER, AND DRAIN LINES, CONTROLS CONNECTIONS, COUPLINGS, AND ACCESSORIES FOR LOOSE OR FAILED FASTENERS, CHAFING WEAR, ROUTING, PROPER SAFETY, SECURITY OF MOUNTING, AND EVIDENCE OF DAMAGE. INSPECT SHIELDED FADEC ELECTRICAL HAR	PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25		05-OCT-2018 6634.6 4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
J7120051 (s)	FORWARD ENGINE BEAM INTERMEDIATE FITTING - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-01.)						PKG		
	PKG 28	MOS						10-MAY-2002	
	REF: NDT 71-20-01	HRS/MSC AFL	12000	+25/-25				0	0
J7120052 (s)	FORWARD ENGINE MOUNT YOKE - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-02.)						PKG		
	PKG 28	MOS						10-MAY-2002	
	REF: NDT 71-20-02	HRS/MSC AFL	12000	+25/-25				0	0
J7120053 (s)	BOLT/FORWARD INTERMEDIATE FITTING TO FORWARD BEAM SUPPORT FITTING - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-03.)						PKG		
	PKG 28	MOS						10-MAY-2002	
	REF: NDT 71-20-03	HRS/MSC AFL	12000	+25/-25				0	0
J7120054 (s)	BOLT/FORWARD YOKE TO INTERMEDIATE FITTING - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-04.)						PKG		
	PKG 28	MOS						10-MAY-2002	
	REF: NDT 71-20-04	HRS/MSC AFL	12000	+25/-25				0	0
J7120055 (s)	BOLT/FORWARD YOKE TO ISOLATOR - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-05.)						PKG		
	PKG 28	MOS						10-MAY-2002	
	REF: NDT 71-20-05	HRS/MSC AFL	12000	+25/-25				0	0
J7120056 (s)	BOLT/FORWARD ENGINE ISOLATOR TO ENGINE CASE - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-06.)						PKG		
	PKG 28	MOS						10-MAY-2002	
	REF: NDT 71-20-06	HRS/MSC AFL	12000	+25/-25				0	0
J7120057 (s)	FORWARD TO ENGINE ISOLATOR - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-07.)						PKG		
	PKG 28	MOS						10-MAY-2002	
	REF: NDT 71-20-07	HRS/MSC AFL	12000	+25/-25				0	0

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
J7120058 (s)	AFT ENGINE ISOLATOR - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-08.) PKG 28 REF: NDT 71-20-08	MOS HRS/MSC AFL	12000	+25/-25			PKG 10-MAY-2002 0 0		
J7120059 (s)	AFT MOUNT LINKS - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-09.) PKG 28 REF: NDT 71-20-09	MOS HRS/MSC AFL	12000	+25/-25			PKG 10-MAY-2002 0 0		
J7120060 (s)	BOLT/AFT ISOLATOR TO SUPPORT FITTING - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-10.) PKG 28 REF: NDT 71-20-10	MOS HRS/MSC AFL	12000	+25/-25			PKG 10-MAY-2002 0 0		
J7120061 (s)	BOLT/AFT ISOLATOR TO MOUNT LINKS - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-11.) PKG 28 REF: NDT 71-20-11	MOS HRS/MSC AFL	12000	+25/-25			PKG 10-MAY-2002 0 0		
J7120062 (s)	BOLT/MOUNT LINKS TO ENGINE CASE - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL [NDI-2], PART 5, 71-20-12.) PKG 28 REF: NDT 71-20-12	MOS HRS/MSC AFL	12000	+25/-25			PKG 10-MAY-2002 0 0		
M7120068A	INSPECT NO. 1 ENGINE FORWARD AND AFT MOUNT ISOLATORS AND ASSOCIATED PARTS REF: See Workcard	MOS HRS/MSC AFL	3600	+25/-25			19-MAR-2011 3580.3 2618	10862.4 M 10887.4	
M7120068B	INSPECT NO. 2 ENGINE FORWARD AND AFT MOUNT ISOLATORS AND ASSOCIATED PARTS REF: See Workcard	MOS HRS/MSC AFL	3600	+25/-25			19-MAR-2011 3580.3 2618	13245.3 M 13270.3	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T7100010 (s)	INSPECT UPPER COWL DOOR AND APRON FOR FAILED FASTENERS, SECURITY, AND EVIDENCOS OF DAMAGE. INSPECT BONDING JUMPERS ACROSS COWLING HINGES FOR CONDITION. INSPECT OUTER SURFACE OF DOOR AND APRON FOR EVIDENCE OF BLISTERED PAINT OR SUBSURFACE DELAMINATION, PARTICULARLY						PKG		
	PKG 15	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
T7100012 (s)	INSPECT LOWER COWL DOOR INNER AND OUTER SKINS AND SEALS FOR EVIDENCE OF DAMAGE. INSPECT LATCH ASSEMBLIES FOR CONDITION. INSPECT OUTER SURFACE OF DOOR FOR EVIDENCE OF BLISTERED PAINT OR SUBSURFACE DELAMINATION, PARTICULARLY AROUND THE HEADS OF FASTENERS AND ALONG						PKG		
	PKG 15	MOS	48	+14d/-14d			05-OCT-2018		
		HRS/MSC	1200	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
T7100018 (s)	GENERAL VISUAL INSPECTION FAN DUCT OUTER SKIN AND ATTACHMENT. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
U7100014 (s)	GENERAL VISUAL INSPECTION OIL FILLER DOOR. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
U7110032 (s)	GENERAL VISUAL INSPECTION GENERATOR INLET DUCT SEAL. (REFER TO 5-10-00)						PKG		
	PKG 3	MOS	12	+14d/-14d			05-OCT-2018		
		HRS/MSC	300	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
U7110041 (s)	GENERAL VISUAL INSPECTION NACELLE OUTER SKIN ATTACHMENT. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
U7110042 (s)	GENERAL VISUAL INSPECTION NACELLE LIP ASSEMBLY AND INNER BARREL. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		

ENGINE NO. 1 Model : PW305A Serial # PCE-305018 Part # 31B4067-02

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-P&W-710001	NO. 1 ENGINE - PERFORM OVERHAUL ENGINE	MOS					10-FEB-2009		
OVERHAUL	REF: GENERIC NO REF	HRS/MSC ENC	7200	+50			7262.4 4986	(14462.4) 11812.4	14512.4
05-P&W-710006	NO. 1 ENGINE - PERFORM HOT SECTION INSPECTION	MOS					10-FEB-2009		
INSPECT	REF: GENERIC NO REF	HRS/MSC ENC	3600	+50			7262.4 4986	(10862.4) 8212.4	10912.4
05-P&W-710015	NO. 1 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS	MOS					22-MAR-2016		
	REF: GENERIC NO REF	HRS/MSC ENC	1200	+25/-25			9032.8 6211	(10232.8) 7582.8	10257.8
05-P&W-710017	NO. 1 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR	MOS					24-MAR-2016		
	REF: GENERIC NO REF	HRS/MSC ENC	600	+25/-25			9032.8 6211	(9632.8) 6982.8	9657.8
05-P&W-710019	NO. 1 ENGINE - REPLACE BLEED OFF VALVE SOLENOID 31B4197-05 ARK0332T REF: EMM 75-30-02	MOS					30-DEC-2013		
		HRS/MSC ENC	1500	+300/-300	-25.6		8788 6043	(10262.4) 7612.4	10562.4
05-P&W-710020	NO. 1 ENGINE - DO A VISUAL INSPECTION CHECK FOR CONDITION OF ACCESSIBLE WIRING HARNESES AND SECURITY OF CONNECTORS - N1 SPEED SENSOR	MOS					10-FEB-2009		
	REF: GENERIC NO REF	HRS/MSC ENC	3600	+50			7262.4 4986	(10862.4) 8212.4	10912.4
710000	NO. 1 ENGINE - COMPRESSOR WASH	MOS					07-DEC-2013		
	REF: EMM 71-00-00	HRS/MSC ENC	A/R				8744.6 6024		
710050	NO. 1 ENGINE - RUN ENGINES	MOS							
	REF: EMM 72-00-00	HRS/MSC ENC	A/R						

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
715020	NO. 1 ENGINE - ENGINE WIRE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			25-OCT-1993 0 0		
715025	NO. 1 ENGINE - PERMANENT MAGNET (PMA) ALTERNATOR 89061-1 083 REF: EMM 72-60-01	MOS HRS/MSC ENC	O/C				22-DEC-2004		
ENGINE NO. 2 Model : PW305A Serial # PCE-305110 Part # 31B4067-02									
+ 05-P&W-710001	NO. 2 ENGINE - PERFORM OVERHAUL ENGINE	MOS HRS/MSC ENC	7200	+50			26-AUG-2003 6096.9 4139	(13296.9) 10025.2	13346.9
OVERHAUL	REF: GENERIC NO REF								
+ 05-P&W-710006	NO. 2 ENGINE - PERFORM HOT SECTION INSPECTION	MOS HRS/MSC ENC	3600	+50			10-OCT-2014 9645.3 6543	(13245.3) 9973.6	13295.3
INSPECT	REF: GENERIC NO REF								
05-P&W-710015	NO. 2 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS	MOS HRS/MSC ENC	1200	+25/-25			22-MAR-2016 9654.5 6554	(10854.5) 7582.8	10879.5
REF: GENERIC NO REF									
05-P&W-710017	NO. 2 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR	MOS HRS/MSC ENC	600	+25/-25			24-MAR-2016 9654.5 6554	(10254.5) 6982.8	10279.5
REF: GENERIC NO REF									
05-P&W-710019	NO. 2 ENGINE - REPLACE BLEED OFF VALVE SOLENOID 31B4197-05 ARK0700T REF: EMM 75-30-02	MOS HRS/MSC ENC	1500	+300/-300			10-OCT-2014 9645.3 6543	(11145.3) 7873.6	11445.3
05-P&W-710020	NO. 2 ENGINE - DO A VISUAL INSPECTION CHECK FOR CONDITION OF ACCESSIBLE WIRING HARNESES AND SECURITY OF CONNECTORS - N1 SPEED SENSOR	MOS HRS/MSC ENC	3600	+50			10-OCT-2014 9645.3 6543	(13245.3) 9973.6	13295.3
REF: GENERIC NO REF									

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710000	NO. 2 ENGINE - COMPRESSOR WASH REF: EMM 71-00-00	MOS HRS/MSC ENC	A/R				07-DEC-2013 9366.3 6367		
710050	NO. 2 ENGINE - RUN ENGINES REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R						
715020	NO. 2 ENGINE - ENGINE WIRE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-OCT-1992 0 0		
715025	NO. 2 ENGINE - PERMANENT MAGNET (PMA) ALTERNATOR PN SN-UNKNOWN REF: EMM 72-60-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-OCT-1992 0 0		
CHAPTER 72 ENGINE									
APU Model : T-20G-10C3A (CIMMS) Serial # SP-E990310 Part # 4503135									
496010	APU - H.O.T. SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1999 0 0		
ENGINE NO. 1 Model : PW305A Serial # PCE-305018 Part # 31B4067-02									
720000	NO. 1 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION REF: EMM 72-00-00	MOS HRS/MSC ENC	180	+12m			15-APR-2008 7100.7 4885	15-APR-2023	15-APR-2024
+ 720010 (s)	NO. 1 ENGINE - EEC, CHECK SECURITY OF POST-SB24379 SILICONE SEALANT IN VENT HOLES PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24	600			PKG 12-APR-2018 9230.9 6367		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720020 (s)	NO. 1 ENGINE - EDU, CHECK ADVISORY DATA IN COCKPIT (REF. AMM) FOR THE EDU BATTERY EXPIRY DATE PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9230.9 6367		
+ 720030 (s)	NO. 1 ENGINE - TUBING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS, EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION AND EVIDENCE OF FUEL OR OIL LEAKS PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9230.9 6367		
+ 720040 (s)	NO. 1 ENGINE - WIRING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS AND FOR EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9230.9 6367		
+ 720050 (s)	NO. 1 ENGINE - WIRING HARNESS CONNECTORS, CHECK FOR SECURITY PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9230.9 6367		
+ 720060 (s)	NO. 1 ENGINE - ENGINE MOUNTS, SECURITY AND CONDITION PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9230.9 6367		
+ 720070 (s)	NO. 1 ENGINE - FAN CASE AND COMPRESSOR INLET, CHECK FOR CLEANLINESS AND DAMAGE. CHECK LP COMPRESSOR BLADES FOR FOD, DEPOSITS, CORROSION AND EROSION PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9230.9 6367		
+ 720080 (s)	NO. 1 ENGINE - BYPASS DUCTS, CHECK INNER AND OUTER BYPASS DUCTS FOR DAMAGE PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9230.9 6367		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720090 (s)	NO. 1 ENGINE - FAN BLADES, CHECK FOR EROSION OF LE THICKNESS USING GAGE (PWC60640) PKG 0	MOS	24				PKG 12-APR-2018 9230.9 6367		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720100 (s)	NO. 1 ENGINE - FAN EXIT STATOR VANES, CHECK FOR FOD, DEPOSITS, CORROSION AND EROSION PKG 0	MOS	24				PKG 12-APR-2018 9230.9 6367		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720110 (s)	NO. 1 ENGINE - EXHAUST DUCT, CRACKS OR DISTORTION PKG 0	MOS	24				PKG 12-APR-2018 9230.9 6367		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720120 (s)	NO. 1 ENGINE - ACCESSORIES, SECURITY OF INSTALLATION. CHECK FOR FUEL AND OIL LEAKS EXTERNALLY AND AT DRAINS PKG 0	MOS	24				PKG 12-APR-2018 9230.9 6367		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720130 (s)	NO. 1 ENGINE - INTERMEDIATE CASE AND AGB, CHECK FOR SECURITY AND CORROSION PKG 0	MOS	24				PKG 12-APR-2018 9230.9 6367		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720140 (s)	NO. 1 ENGINE - OIL QUANTITY, CHECK OIL LEVEL AND REPLENISH IF REQUIRED. CHECK CONDITION AND SECURITY OF OIL FILLER CAP PKG 0	MOS	24				PKG 12-APR-2018 9230.9 6367		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720150 (s)	NO. 1 ENGINE - IMPENDING BYPASS INDICATOR, CHECK FOR PROTRUDING INDICATOR (RED BUTTON). REPLACE OIL FILTER IF INDICATOR HAS POPPED OUT PKG 0	MOS	24				PKG 12-APR-2018 9230.9 6367		
	REF: EMM 05-20-00	HRS/MSC ENC	600						

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720160 (s)	NO. 1 ENGINE - CHIP DETECTOR, REMOVE AND CHECK FOR METALLIC PICKUP. USING A SUITABLE OHMMETER, CHECK FOR CONTINUITY OF ELECTRICAL CIRCUIT WHEN THE TWO POLES ARE SHORTED TOGETHER. REJECT DETECTOR IF NO CONTINUITY. LOOSE PINS ARE ALSO CAUSE FOR REJECTION						PKG		
	PKG 0	MOS	24				12-APR-2018		
		HRS/MSC	600				9230.9		
	REF: EMM 05-20-00	ENC					6367		
+ 720170 (s)	NO. 1 ENGINE - OIL FILTER ELEMENT, REMOVE, INSPECT AND CHECK FOR FOREIGN MATTER AND DAMAGE						PKG		
	PKG 0	MOS	24				12-APR-2018		
		HRS/MSC	600				9230.9		
	REF: EMM 79-20-01	ENC					6367		
+ 720180 (s)	NO. 1 ENGINE - AGB PAD SEALS, CHECK PAD SEAL FOR OIL LEAKS. LEAK RATE OF 1 DROP PER 5 MINUTES FROM ANY PAD SEAL IS ACCEPTABLE						PKG		
	PKG 0	MOS	24				12-APR-2018		
		HRS/MSC	600				9230.9		
	REF: EMM 05-20-00	ENC					6367		
+ 720190 (s)	NO. 1 ENGINE - AGB REAR COVER, CHECK FOR FOREIGN DEPOSITS. WIPE CLEAN IF FOUND						PKG		
	PKG 0	MOS	24				12-APR-2018		
		HRS/MSC	600				9230.9		
	REF: EMM 05-20-00	ENC					6367		
+ 720200 (s)	NO. 1 ENGINE - FUEL PUMP, SECURITY AND LEAKAGE						PKG		
	PKG 0	MOS	24				12-APR-2018		
		HRS/MSC	600				9230.9		
	REF: EMM 05-20-00	ENC					6367		
+ 720210 (s)	NO. 1 ENGINE - HMU, SECURITY, LEAKAGE, AND FUEL LEAKS AT TUBE CONNECTIONS						PKG		
	PKG 0	MOS	24				12-APR-2018		
		HRS/MSC	600				9230.9		
	REF: EMM 05-20-00	ENC					6367		
+ 720220 (s)	NO. 1 ENGINE - HMU, CHECK FOR CARBON DEPOSITS. WIPE CLEAN IF FOUND.						PKG		
	PKG 0	MOS	24				12-APR-2018		
		HRS/MSC	600				9230.9		
	REF: EMM 05-20-00	ENC					6367		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720230 (s)	NO. 1 ENGINE - FUEL FILTER, REMOVE AND CHECK FOR FOREIGN MATTER AND DAMAGE PKG 0	MOS	24				PKG 12-APR-2018 9230.9 6367		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720240 (s)	NO. 1 ENGINE - DUMP VALVE, SECURITY AND LEAKAGE PKG 0	MOS	24				PKG 12-APR-2018 9230.9 6367		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720250 (s)	NO. 1 ENGINE - FUEL/OIL HEAT EXCHANGER, SECURITY AND LEAKAGE. PKG 0	MOS	24				PKG 12-APR-2018 9230.9 6367		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720260 (s)	NO. 1 ENGINE - FUEL WASTE EJECTOR, SECURITY AND LEAKAGE PKG 0	MOS	24				PKG 12-APR-2018 9230.9 6367		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720270 (s)	NO. 1 ENGINE - P1 AND P3 AIR TUBES, DRAIN CONDENSATION TRAPS. CHECK FOR WEAR, CHAFING, CRACKS AND CORROSION PKG 0	MOS	24				PKG 12-APR-2018 9230.9 6367		
	REF: See Workcard	HRS/MSC ENC	600						
+ 720280 (s)	NO. 1 ENGINE - IGNITION EXCITERS, SECURITY AND CORROSION PKG 0	MOS	24				PKG 12-APR-2018 9230.9 6367		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720290 (s)	NO. 1 ENGINE - IGNITION CABLES, CHAFING, WEAR AND SECURITY. PKG 0	MOS	24				PKG 12-APR-2018 9230.9 6367		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720300 (s)	NO. 1 ENGINE - SPARK IGNITERS, CLEANLINESS AND EROSION PKG 0	MOS	24				PKG 12-APR-2018 9230.9 6367		
	REF: EMM 05-20-00	HRS/MSC ENC	600						

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720310 (s)	NO. 1 ENGINE - SPARK IGNITERS, OPERATIONAL TEST PKG 0	MOS	24				PKG 12-APR-2018 9230.9 6367		
	REF: EMM 05-20-00	HRS/MS ENC	600						
723001	NO. 1 ENGINE - FAN HUB 30B1778 31A949	MOS		TSN:0			25-OCT-1993 0		
LIFE LIMIT	REF: EMM 72-30-01	HRS/MS ENC	12000	TSN:0			0	(12000) 10064	
723002	NO. 1 ENGINE - FAN CASE ASSEMBLY PN SN-UNKNOWN	MOS		TSN:0			25-OCT-1993 0		
	REF: EMM 72-30-01	HRS/MS ENC	O/C	TSN:0			0		
723003	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 30B4565-01 A002DT5K	MOS		TSN:0			10-FEB-2009 7262.4		
LIFE LIMIT	REF: EMM 72-30-01	HRS/MS ENC	7000	TSN:0			4986	(11986) 10050	
723004	NO. 1 ENGINE - PRESSURE CHECK IMPELLER SHROUD	MOS					25-OCT-1993 0		
	REF: GENERIC NO REF	HRS/MS ENC	N/A				0		
723005	NO. 1 ENGINE - STAGE 1 COMPRESSOR ROTOR 30B6531-01 TXA1B7790	MOS		TSN:0			10-FEB-2009 7262.4		
LIFE LIMIT	REF: EMM 72-30-01	HRS/MS ENC	12000	TSN:0			4986	(16986) 15050	
723005A	NO. 1 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR (IBR) 30B6531-01 TXA1B7790	MOS	300	+25			05-FEB-2019 9323.4 6433	(9623.4) 6973.4	9648.4
	REF: EMM 72-00-00	HRS/MS ENC							
723008	NO. 1 ENGINE - HPC (2ND-,3RD- AND 4TH STAGE) ROTOR 30B2797-01 32B070	MOS		TSN:0			12-SEP-1998 2867.5		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MS ENC	8500	TSN:0			2015	(10515) 8579	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723008A	NO. 1 ENGINE - BORESCOPE 30B2797-01 32B070 REF: GENERIC NO REF	HPC (2ND-,3RD- AND 4TH STAGE) ROTOR MOS HRS/MSC ENC	O/C	DRUM			12-SEP-1998 2867.5 2015		
724010	NO. 1 ENGINE - BORESCOPE REF: GENERIC NO REF	WORKSCOPE ENGINE CONDITION TREND MONITORING (ECTM) MOS HRS/MSC ENC	N/A				25-OCT-1993 0 0		
725001	NO. 1 ENGINE - STAGE 2 TURBINE ASSEMBLY 30B2059 7C170 REF: EMM 72-50-01	VANE-RING MOS HRS/MSC ENC	O/C				25-OCT-1993 0 0		
725003	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY 30A1426 5D635 REF: EMM 72-50-03		O/C				25-OCT-1993 0 0		
725101	NO. 1 ENGINE - STAGE 1 TURBINE DISC 30B2981-01 A002F42L LIFE LIMIT REF: EMM 72-50-01	MOS HRS/MSC ENC	3100				10-FEB-2009 7262.4 4986		(8086) 6150
725102	NO. 1 ENGINE - STAGE 2 TURBINE DISC 30B2912-01 A002ETK4 LIFE LIMIT REF: EMM 72-50-01	MOS HRS/MSC ENC	3300				10-FEB-2009 7262.4 4986		(8286) 6350
725103	NO. 1 ENGINE - STAGE 3 TURBINE DISC 30A1853 MAA13215 LIFE LIMIT REF: EMM 72-50-01	MOS HRS/MSC ENC	10000				10-FEB-2009 7262.4 4986		(14986) 13050
725104	NO. 1 ENGINE - STAGE 4 TURBINE DISC 30A1834 68B844 LIFE LIMIT REF: EMM 72-50-01	MOS HRS/MSC ENC	10000				06-MAR-2003 5263.7 3679		(13679) 11743

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725105	NO. 1 ENGINE - STAGE 5 TURBINE DISC 30B1855 MAA40800 REF: EMM 72-50-01	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			10-FEB-2009 7262.4 4986	(14986) 13050	
LIFE LIMIT									
725107	NO. 1 ENGINE - FRONT HIGH PRESSURE TURBINE COVER 30B2748-01 A001AAAF REF: EMM 72-50-01	MOS HRS/MSC ENC	4800	TSN:0 TSN:0 TSN:0			06-MAR-2003 5263.7 3679	(8479) 6543	
LIFE LIMIT									
725109	NO. 1 ENGINE - REAR HIGH PRESSURE TURBINE COVER 30B2747-01 A001A2W1 REF: EMM 72-50-01	MOS HRS/MSC ENC	4400	TSN:0 TSN:0 TSN:0			06-MAR-2003 5263.7 3679	(8079) 6143	
LIFE LIMIT									
725111	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR AIR SEAL 30B2793-01 WG001556 REF: EMM 72-50-01	MOS HRS/MSC ENC	4000	TSN:0 TSN:0 TSN:0			06-MAR-2003 5263.7 3679	(7679) 5743	
LIFE LIMIT									
726001	NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING 30B1054 SN-UNKNOWN REF: EMM 72-60-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			25-OCT-1993 0 0		
+ 726011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE AC GENERATOR (PMA) REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
727001	NO. 1 ENGINE - COMBUSTION CHAMBER LINER 31B4008-01 A00199XW REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			06-MAR-2003 5263.7 3679		
727001A	NO. 1 ENGINE - INSPECT FOR DAMAGE - COMBUSTION CHAMBER LINER REF: EMM 72-40-01	MOS HRS/MSC ENC	3600	+50			10-FEB-2009 7262.4 4986	(10862.4) 8212.4 10912.4	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727002	NO. 1 ENGINE - INNER COMBUSTION LINER ASSEMBLY PN SN-UNKNOWN REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			25-OCT-1993 0 0		
727003	NO. 1 ENGINE - OUTER COMBUSTION LINER ASSEMBLY PN SN-UNKNOWN REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			25-OCT-1993 0 0		
ENGINE NO. 2 Model : PW305A Serial # PCE-305110 Part # 31B4067-02									
720000	NO. 2 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION REF: EMM 72-00-00	MOS HRS/MSC ENC	180	+12m			10-OCT-2014 9645.3 6543	10-OCT-2029	10-OCT-2030
+ 720010 (s)	NO. 2 ENGINE - EEC, CHECK SECURITY OF POST-SB24379 SILICONE SEALANT IN VENT HOLES PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9852.6 6710		
+ 720020 (s)	NO. 2 ENGINE - EDU, CHECK ADVISORY DATA IN COCKPIT (REF. AMM) FOR THE EDU BATTERY EXPIRY DATE PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9852.6 6710		
+ 720030 (s)	NO. 2 ENGINE - TUBING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS, EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION AND EVIDENCE OF FUEL OR OIL LEAKS PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9852.6 6710		
+ 720040 (s)	NO. 2 ENGINE - WIRING, CHECK FOR SECURITY OF ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS AND FOR EVIDENCE OF WEAR, CHAFING, CRACKS AND CORROSION PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9852.6 6710		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720050 (s)	NO. 2 ENGINE - WIRING HARNESS CONNECTORS, CHECK FOR SECURITY PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720060 (s)	NO. 2 ENGINE - ENGINE MOUNTS, SECURITY AND CONDITION PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720070 (s)	NO. 2 ENGINE - FAN CASE AND COMPRESSOR INLET, CHECK FOR CLEANLINESS AND DAMAGE. CHECK LP COMPRESSOR BLADES FOR FOD, DEPOSITS, CORROSION AND EROSION PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720080 (s)	NO. 2 ENGINE - BYPASS DUCTS, CHECK INNER AND OUTER BYPASS DUCTS FOR DAMAGE PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720090 (s)	NO. 2 ENGINE - FAN BLADES, CHECK FOR EROSION OF LE THICKNESS USING GAGE (PWC60640) PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720100 (s)	NO. 2 ENGINE - FAN EXIT STATOR VANES, CHECK FOR FOD, DEPOSITS, CORROSION AND EROSION PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720110 (s)	NO. 2 ENGINE - EXHAUST DUCT, CRACKS OR DISTORTION PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720120 (s)	NO. 2 ENGINE - ACCESSORIES, SECURITY OF INSTALLATION. CHECK FOR FUEL AND OIL LEAKS EXTERNALLY AND AT DRAINS PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720130 (s)	NO. 2 ENGINE - INTERMEDIATE CASE AND AGB, CHECK FOR SECURITY AND CORROSION PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9852.6 6710		
+ 720140 (s)	NO. 2 ENGINE - OIL QUANTITY, CHECK OIL LEVEL AND REPLENISH IF REQUIRED. CHECK CONDITION AND SECURITY OF OIL FILLER CAP PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9852.6 6710		
+ 720150 (s)	NO. 2 ENGINE - IMPENDING BYPASS INDICATOR, CHECK FOR PROTRUDING INDICATOR (RED BUTTON). REPLACE OIL FILTER IF INDICATOR HAS POPPED OUT PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9852.6 6710		
+ 720160 (s)	NO. 2 ENGINE - CHIP DETECTOR, REMOVE AND CHECK FOR METALLIC PICKUP. USING A SUITABLE OHMMETER, CHECK FOR CONTINUITY OF ELECTRICAL CIRCUIT WHEN THE TWO POLES ARE SHORTED TOGETHER. REJECT DETECTOR IF NO CONTINUITY. LOOSE PINS ARE ALSO CAUSE FOR REJECTION PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9852.6 6710		
+ 720170 (s)	NO. 2 ENGINE - OIL FILTER ELEMENT, REMOVE, INSPECT AND CHECK FOR FOREIGN MATTER AND DAMAGE PKG 0 REF: EMM 79-20-01	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9852.6 6710		
+ 720180 (s)	NO. 2 ENGINE - AGB PAD SEALS, CHECK PAD SEAL FOR OIL LEAKS. LEAK RATE OF 1 DROP PER 5 MINUTES FROM ANY PAD SEAL IS ACCEPTABLE PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9852.6 6710		
+ 720190 (s)	NO. 2 ENGINE - AGB REAR COVER, CHECK FOR FOREIGN DEPOSITS. WIPE CLEAN IF FOUND PKG 0 REF: EMM 05-20-00	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9852.6 6710		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720200 (s)	NO. 2 ENGINE - FUEL PUMP, SECURITY AND LEAKAGE PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720210 (s)	NO. 2 ENGINE - HMU, SECURITY, LEAKAGE, AND FUEL LEAKS AT TUBE CONNECTIONS PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720220 (s)	NO. 2 ENGINE - HMU, CHECK FOR CARBON DEPOSITS. WIPE CLEAN IF FOUND. PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720230 (s)	NO. 2 ENGINE - FUEL FILTER, REMOVE AND CHECK FOR FOREIGN MATTER AND DAMAGE PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720240 (s)	NO. 2 ENGINE - DUMP VALVE, SECURITY AND LEAKAGE PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720250 (s)	NO. 2 ENGINE - FUEL/OIL HEAT EXCHANGER, SECURITY AND LEAKAGE. PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720260 (s)	NO. 2 ENGINE - FUEL WASTE EJECTOR, SECURITY AND LEAKAGE PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720270 (s)	NO. 2 ENGINE - P1 AND P3 AIR TUBES, DRAIN CONDENSATION TRAPS. CHECK FOR WEAR, CHAFING, CRACKS AND CORROSION PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: See Workcard	HRS/MSC ENC	600						

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720280 (s)	NO. 2 ENGINE - IGNITION EXCITERS, SECURITY AND CORROSION PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720290 (s)	NO. 2 ENGINE - IGNITION CABLES, CHAFING, WEAR AND SECURITY. PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720300 (s)	NO. 2 ENGINE - SPARK IGNITERS, CLEANLINESS AND EROSION PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
+ 720310 (s)	NO. 2 ENGINE - SPARK IGNITERS, OPERATIONAL TEST PKG 0	MOS	24				PKG 12-APR-2018 9852.6 6710		
	REF: EMM 05-20-00	HRS/MSC ENC	600						
723001	NO. 2 ENGINE - FAN HUB 30B1778 52A437	MOS		TSN:0			21-OCT-1992 0		
LIFE LIMIT	REF: EMM 72-30-01	HRS/MSC ENC	12000	TSN:0			0	(12000) 9721	
723002	NO. 2 ENGINE - FAN CASE ASSEMBLY 31B5237-01 1F914	MOS		TSN:0			21-OCT-1992 0		
	REF: EMM 72-30-01	HRS/MSC ENC	O/C	TSN:0			0		
723003	NO. 2 ENGINE - CENTRIFUGAL IMPELLER 30B4565-01 A000LMT5	MOS		TSN:0			16-MAR-2001 4958.3		
LIFE LIMIT	REF: EMM 72-30-01	HRS/MSC ENC	7000	TSN:0			3384	(10384) 8105	
723004	NO. 2 ENGINE - PRESSURE CHECK IMPELLER SHROUD MOS						21-OCT-1992 0		
	REF: GENERIC NO REF	HRS/MSC ENC	N/A				0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723005	NO. 2 ENGINE - STAGE 1 COMPRESSOR ROTOR 30B6551-01 TXA1D2077	MOS HRS/MSC		TSN:0 TSN:0			10-OCT-2014 9645.3		
LIFE LIMIT	REF: EMM 72-30-01	ENC	12000	TSN:0			6543	(18543) 16264	
723005A	NO. 2 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR (IBR) 30B6551-01 TXA1D2077	MOS HRS/MSC	N/A				10-OCT-2014 9645.3		
NOT APPLICABLE	REF: EMM 72-00-00	ENC					6543		
723008	NO. 2 ENGINE - HPC (2ND-,3RD- AND 4TH STAGE) ROTOR 30B4745-01 A00FPLB	MOS HRS/MSC		TSN:0 TSN:0			10-OCT-2014 9645.3		
LIFE LIMIT	REF: GENERIC NO REF	ENC	8500	TSN:0			6543	(15043) 12764	
723008A	NO. 2 ENGINE - BORESCOPE HPC (2ND-,3RD- AND 4TH STAGE) ROTOR DRUM 30B4745-01 A00FPLB	MOS HRS/MSC	O/C				10-OCT-2014 9645.3		
	REF: GENERIC NO REF	ENC					6543		
724010	NO. 2 ENGINE - BORESCOPE WORKSCOPE ENGINE CONDITION TREND MONITORING (ECTM)	MOS HRS/MSC	N/A				21-OCT-1992 0		
	REF: GENERIC NO REF	ENC					0		
725001	NO. 2 ENGINE - STAGE 2 TURBINE ASSEMBLY VANE-RING 30B3012 SN-UNKNOWN	MOS HRS/MSC	O/C	TSN:0 TSN:0			21-OCT-1992 0		
	REF: EMM 72-50-01	ENC		TSN:0			0		
725003	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY 30A1426 7E641	MOS HRS/MSC	O/C	TSN:0 TSN:0			21-OCT-1992 0		
	REF: EMM 72-50-03	ENC		TSN:0			0		
725101	NO. 2 ENGINE - STAGE 1 TURBINE DISC 30B2981-01 A0006C3R	MOS HRS/MSC		TSN:829.3			10-OCT-2014 9645.3		
LIFE LIMIT	REF: EMM 72-50-01	ENC	3100	TSN:569			6543	(9074) 6795	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725102	NO. 2 ENGINE - STAGE 2 TURBINE DISC 30B2912-01 A00061KM REF: EMM 72-50-01	MOS HRS/MSC ENC	3300	TSN:829.3 TSN:569			10-OCT-2014 9645.3 6543	(9274) 6995	
725103	NO. 2 ENGINE - STAGE 3 TURBINE DISC 30A1102 6Y769 REF: EMM 72-50-01	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			21-OCT-1992 0 0	(10000) 7721	
725104	NO. 2 ENGINE - STAGE 4 TURBINE DISC 30A1834 35B532 REF: EMM 72-50-01	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			14-JAN-2001 4949.9 3378	(13378) 11099	
725105	NO. 2 ENGINE - STAGE 5 TURBINE DISC 30A1104 6Y873 REF: EMM 72-50-01	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			21-OCT-1992 0 0	(10000) 7721	
725107	NO. 2 ENGINE - FRONT HIGH PRESSURE TURBINE COVER 30B2748-01 A003FPL4 REF: EMM 72-50-01	MOS HRS/MSC ENC	4800	TSN:0 TSN:0 TSN:0			10-OCT-2014 9645.3 6543	(11343) 9064	
725109	NO. 2 ENGINE - REAR HIGH PRESSURE TURBINE COVER 30B6726-01 A003EC0Y REF: EMM 72-50-01	MOS HRS/MSC ENC	4400	TSN:0 TSN:0 TSN:0			10-OCT-2014 9645.3 6543	(10943) 8664	
725111	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR AIR SEAL 30B2500 PKAAA502674 REF: EMM 72-50-01	MOS HRS/MSC ENC	4000	TSN:0 TSN:0 TSN:0			10-OCT-2014 9645.3 6543	(10543) 8264	
726001	NO. 2 ENGINE - ACCESSORY GEARBOX HOUSING PN SN-UNKNOWN REF: EMM 72-60-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-DEC-1994 1377.2 874		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 726011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE AC GENERATOR (PMA)	MOS					21-OCT-1992		
	REF: GENERIC NO REF	HRS/MSC ENC	7200	+50			0 0	(13296.9)	10025.2 M 13396.9
727001	NO. 2 ENGINE - COMBUSTION CHAMBER LINER	MOS					26-AUG-2003		
	30B4008-01 SN-UNKNOWN REF: EMM 72-40-01	HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0				
727001A	NO. 2 ENGINE - INSPECT FOR DAMAGE - COMBUSTION CHAMBER LINER	MOS					10-OCT-2014		
	REF: EMM 72-40-01	HRS/MSC ENC	3600	+50			9645.3 5643	(13245.3)	9973.6 13295.3
727002	NO. 2 ENGINE - INNER COMBUSTION LINER ASSEMBLY	MOS					21-OCT-1992		
	PN SN-UNKNOWN REF: EMM 72-40-01	HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		0 0		
727003	NO. 2 ENGINE - OUTER COMBUSTION LINER ASSEMBLY	MOS					21-OCT-1992		
	PN SN-UNKNOWN REF: EMM 72-40-01	HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		0 0		
CHAPTER 73 ENGINE FUEL AND CONTROL									
733101	LEFT ENGINE FUEL FLOW TRANSMITTER	MOS					22-AUG-2017		
	7600021-1 516332 REF: AMM 73-31-01	HRS/MSC AFL	O/C						
733102	RIGHT ENGINE FUEL FLOW TRANSMITTER	MOS					22-AUG-2017		
	7600021-1 516327 REF: AMM 73-31-01	HRS/MSC AFL	O/C						
733103	LEFT ENGINE FUEL FLOW INDICATOR	MOS					04-NOV-2006		
	6608488-001 4567 REF: AMM 73-31-02	HRS/MSC AFL	O/C		TSO:0 TSO:0 TSO:0		1814.1 1484		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
733104	RIGHT ENGINE FUEL FLOW INDICATOR 6608488-001 5702 REF: AMM 73-31-02	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			07-SEP-2006 1736 1426		
ENGINE NO. 1 Model : PW305A Serial # PCE-305018 Part # 31B4067-02									
05-P&W-730001	NO. 1 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT	MOS HRS/MSC ENC	12 1200	+25/-25			03-JUN-2019 9437.9 6467	03-JUN-2020 (10637.9) 7987.9	10662.9
+ 05-P&W-730005	NO. 1 ENGINE - CLEAN THE PRIMARY FUEL NOZZLE	MOS HRS/MSC ENC	1800	+600/-600			06-JUL-2016 9069 6237	(10869) 8219	11469
731001	NO. 1 ENGINE - FUEL PUMP PF4-038-11C MX-514634 REF: EMM 73-10-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			25-OCT-1993 0 0		
731002	NO. 1 ENGINE - MOTIVE FLOW VALVE 30B2062 B44017 REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C				26-JAN-1994		
731003	NO. 1 ENGINE - FUEL FILTER BYPASS INDICATOR SWITCH 30B1669 0873 REF: EMM 73-10-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			10-FEB-2009 7262.4 4986		
731004	NO. 1 ENGINE - UPPER PRIMARY FUEL NOZZLE 31B5832-04 1ANT1952 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			06-JUL-2016 9069 6237		
731005	NO. 1 ENGINE - LOWER PRIMARY FUEL NOZZLE 31B5832-04 1PL06403 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			06-JUL-2016 9069 6237		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731010	NO. 1 ENGINE - FUEL SHUTOFF VALVE ASSEMBLY 31B3681-01 PWC08A189 REF: EMM 73-10-05	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			10-FEB-2009 7262.4 4986		
+ 731011 (s)	NO. 1 ENGINE - CHECK EMERGENCY FUEL SHUT-OFF TRIPPER DIMENSION T AND ADJUST IF NECESSARY PKG 0 REF: EMM 73-10-05	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9230.9 6367		
+ 731012	NO. 1 ENGINE - OVERHAUL - (PRE-SB24589) FUEL PUMP PF4-038-11C MX-514634 REF: EMM 73-10-02	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
OVERHAUL									
+ 731013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL FILTER BYPASS SWITCH 30B1669 0873 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
+ 731014	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - PRIMARY REF: EMM 73-10-04	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
OVERHAUL									
+ 731022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (PRE-SB24589) MOTIVE FLOW VALVE (PW305 ONLY) 30B2062 B44017 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
+ 731023	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL WASTE EJECTOR TANK 30B1781 187 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
+ 731024	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - SECONDARY REF: EMM 73-10-04	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
OVERHAUL									

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731025	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DUMP/START VALVE 26240-07 0624 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M	14512.4
731026	NO. 1 ENGINE - FUEL WASTE EJECTOR 30B1781 187 REF: EMM 73-10-03	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			10-FEB-2009 7262.4 4986		
+ 731044	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - INLET REF: EMM 73-10-04	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M	14512.4
+ 731045	NO. 1 ENGINE - DISCARD - FUEL SHUT-OFF CABLE REF: EMM 73-10-05	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M	14512.4
731051	NO. 1 ENGINE - FUEL START & DUMP VALVE 26240-07 0624 REF: EMM 73-10-05	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			14-FEB-2017 9132.4 6287		
+ 731055	NO. 1 ENGINE - OVERHAUL - VALVE FUEL SHUT-OFF REF: EMM 73-10-05	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M	14512.4
732001	NO. 1 ENGINE - HYDRO MECHANICAL FUEL CONTROL 1891-7 1891145 REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C				14-DEC-1994		
+ 732002	NO. 1 ENGINE - REPLACE TRIM PLUG PKG 0 REF: EMM 73-20-02	MOS HRS/MSC ENC	120 2500	+25/-25			25-OCT-1993 0 0	12-APR-2020 M (9830.9) 7180.9 M	9855.9

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732003	NO. 1 ENGINE - ELECTRICAL FRONT HARNESS 31B3101-01 SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C				26-JAN-1994		
732004	NO. 1 ENGINE - ELECTRICAL REAR HARNESS 31B4159-01 SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C				26-JAN-1994		
732005	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL EEC PN SN-UNKNOWN REF: EMM 73-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			(EBT)		
+ 732011	NO. 1 ENGINE - VISUALLY INSPECT OF THE (PRE-SB24589) HMU 1891-7 1891145 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
+ 732012	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EEC PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
+ 732013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESSES (OUTER, INNER, FRONT AND REAR) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
+ 732021	NO. 1 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU 1891-7 1891145 REF: EMM 73-20-01	MOS HRS/MSC ENC	N/A				25-OCT-1993 0 0		
732101	NO. 1 ENGINE - ENGINE FADEC 1240KDC03-005 YM473 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C				03-NOV-2006 6466.9 4485		

ENGINE NO. 2 Model : PW305A Serial # PCE-305110 Part # 31B4067-02

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-P&W-730001	NO. 2 ENGINE - REPLACE REF: EMM 73-10-03	ENGINE FUEL FILTER ELEMENT MOS HRS/MSC ENC	12 1200	+25/-25			03-JUN-2019 10059.6 6810	03-JUN-2020 (11259.6) 7987.9	11284.6
+ 05-P&W-730005	NO. 2 ENGINE - CLEAN THE PRIMARY FUEL NOZZLE REF: EMM 73-10-04	MOS HRS/MSC ENC	1800	+600/-600			10-OCT-2014 9645.3 6543	(11445.3) 8173.6	12045.3
731001	NO. 2 ENGINE - FUEL PUMP PF4-038-11C MX-569012A REF: EMM 73-10-02	MOS HRS/MSC ENC	O/C		TSO:0 TSO:0 TSO:0		26-AUG-2003 6096.9 4139		
731002	NO. 2 ENGINE - MOTIVE FLOW VALVE 3244870-1 B44018 REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		26-AUG-2003 6096.9 4139		
731003	NO. 2 ENGINE - FUEL FILTER BYPASS INDICATOR SWITCH 30B1669 0219 REF: EMM 73-10-03	MOS HRS/MSC ENC	O/C		TSO:0 TSO:0 TSO:0		26-AUG-2003		
731004	NO. 2 ENGINE - UPPER PRIMARY FUEL NOZZLE 31B5832-04 1UN03446 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C				10-OCT-2014 9645.3 6543		
731005	NO. 2 ENGINE - LOWER PRIMARY FUEL NOZZLE 31B5832-04 1UN03458 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C				10-OCT-2014 9645.3 6543		
731010	NO. 2 ENGINE - FUEL SHUTOFF VALVE ASSEMBLY PN SN-UNKNOWN REF: EMM 73-10-05	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		21-OCT-1992 0 0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731011 (s)	NO. 2 ENGINE - CHECK EMERGENCY FUEL SHUT-OFF TRIPPER DIMENSION T AND ADJUST IF NECESSARY PKG 0 REF: EMM 73-10-05	MOS HRS/MSC ENC	24 600				PKG 12-APR-2018 9852.6 6710		
+ 731012	NO. 2 ENGINE - OVERHAUL - (PRE-SB24589) FUEL PUMP PF4-038-11C MX-569012A REF: EMM 73-10-02	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M 13396.9	
OVERHAUL									
+ 731013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL FILTER BYPASS SWITCH 30B1669 0219 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M 13396.9	
+ 731014	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - PRIMARY REF: EMM 73-10-04	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M 13396.9	
OVERHAUL									
+ 731022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (PRE-SB24589) MOTIVE FLOW VALVE (PW305 ONLY) 3244870-1 B44018 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M 13396.9	
+ 731023	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL WASTE EJECTOR TANK 26100-6 165 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M 13396.9	
+ 731024	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - SECONDARY REF: EMM 73-10-04	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M 13396.9	
OVERHAUL									
+ 731025	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DUMP/START VALVE 26240-5 0237 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M 13396.9	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731026	NO. 2 ENGINE - FUEL WASTE EJECTOR 26100-6 165 REF: EMM 73-10-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-OCT-1992 0 0		
+ 731044	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - INLET REF: EMM 73-10-04	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
+ 731045	NO. 2 ENGINE - DISCARD - FUEL SHUT-OFF CABLE REF: EMM 73-10-05	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
731051	NO. 2 ENGINE - FUEL START & DUMP VALVE 26240-5 0237 REF: EMM 73-10-05	MOS HRS/MSC ENC	O/C				18-DEC-1992		
+ 731055	NO. 2 ENGINE - OVERHAUL - VALVE FUEL SHUT-OFF REF: EMM 73-10-05	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
732001	NO. 2 ENGINE - HYDRO MECHANICAL FUEL CONTROL 1891-11 1891314 REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			05-OCT-2003 5270.2 3881		
+ 732002	NO. 2 ENGINE - REPLACE TRIM PLUG PKG 0 REF: EMM 73-20-02	MOS HRS/MSC ENC	120 2500	+25/-25			21-OCT-1992 0 0	12-APR-2020 M (10452.6) 7180.9 M	10477.6
732003	NO. 2 ENGINE - ELECTRICAL FRONT HARNESS 31B3767-01 7Y970 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-OCT-1992 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732004	NO. 2 ENGINE - ELECTRICAL REAR HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-OCT-1992 0 0		
732005	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL EEC PN SN-UNKNOWN REF: EMM 73-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			(EBT)		
+ 732011	NO. 2 ENGINE - VISUALLY INSPECT OF THE (PRE-SB24589) HMU 1891-11 1891314 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
+ 732012	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE EEC PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
+ 732013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESSSES (OUTER, INNER, FRONT AND REAR) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
+ 732021	NO. 2 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU 1891-11 1891314 REF: EMM 73-20-01	MOS HRS/MSC ENC	N/A				21-OCT-1992 0 0		
732101	NO. 2 ENGINE - ENGINE FADEC 1203KDC-03-005 YM506 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C				31-JUL-2007 6249.7 4236		
CHAPTER 74 IGNITION									
743003	ENGINE WARNING LIGHT BOX 6018314-005 MRP334568 REF: AMM 74-30-03	MOS HRS/MSC AFL	O/C	TSR:33 TSR:0 TSR:0			07-APR-2012 4363.63 3098		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1 Model : PW305A Serial # PCE-305018 Part # 31B4067-02									
741001	NO. 1 ENGINE - NO. 1 IGNITION EXCITER 904798021 NN02092630 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			23-JUN-2004		
741002	NO. 1 ENGINE - NO. 2 IGNITION EXCITER 9047980-1 90110068 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C				14-DEC-1994		
741003	NO. 1 ENGINE - NO. 1 IGNITION CABLE PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			(EBT)		
741004	NO. 1 ENGINE - NO. 2 IGNITION CABLE PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			(EBT)		
+ 741011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITION EXCITER BOX 904798021 NN02092630 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
+ 741012	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITION EXCITER BOX 9047980-1 90110068 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
+ 741021	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITER CABLES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
+ 741022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITER CABLES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 741031	NO. 1 ENGINE - REPLACE - NO. 1 IGNITER PLUGS 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M	14512.4
REPLACE									
+ 741032	NO. 1 ENGINE - REPLACE - NO. 2 IGNITER PLUGS 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M	14512.4
REPLACE									
742025	NO. 1 ENGINE - NO. 1 IGNITER PLUG 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		10-FEB-2009 7262.4 4986		
742026	NO. 1 ENGINE - NO. 2 IGNITER PLUG 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		10-FEB-2009 7262.4 4986		
ENGINE NO. 2 Model : PW305A Serial # PCE-305110 Part # 31B4067-02									
741001	NO. 2 ENGINE - NO. 1 IGNITION EXCITER 9047980-1 NN92050281 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		21-OCT-1992 0 0		
741002	NO. 2 ENGINE - NO. 2 IGNITION EXCITER 9047980-1 NN92050282 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		21-OCT-1992 0 0		
741003	NO. 2 ENGINE - NO. 1 IGNITION CABLE PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		(EBT)		
741004	NO. 2 ENGINE - NO. 2 IGNITION CABLE PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		(EBT)		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 741011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITION EXCITER BOX 9047980-1 NN92050281 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
+ 741012	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITION EXCITER BOX 9047980-1 NN92050282 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
+ 741021	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITER CABLES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
+ 741022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITER CABLES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
+ 741031	NO. 2 ENGINE - REPLACE - NO. 1 IGNITER PLUGS 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
+ 741032	NO. 2 ENGINE - REPLACE - NO. 2 IGNITER PLUGS 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
742025	NO. 2 ENGINE - NO. 1 IGNITER PLUG 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C				26-AUG-2003 TSN:0 TSN:0 TSN:0		
742026	NO. 2 ENGINE - NO. 2 IGNITER PLUG 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C				26-AUG-2003 TSN:0 TSN:0 TSN:0		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1	Model : PW305A Serial # PCE-305018 Part # 31B4067-02								
751001	NO. 1 ENGINE - ANTI-ICING SOLENOID VALVE 31B5108-04 AL194 REF: EMM 75-10-01	MOS HRS/MSC O/C ENC		TSO:0 TSO:0 TSO:0			10-FEB-2009 7262.4 4986		
+ 751011	NO. 1 ENGINE - OVERHAUL - ANTI-ICING VALVE 31B5108-04 AL194 REF: EMM 75-10-01	MOS HRS/MSC 7200 ENC	+50				25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
OVERHAUL									
+ 753001	NO. 1 ENGINE - OVERHAUL - COMPRESSOR BLEED VALVES REF: EMM 75-30-01	MOS HRS/MSC 7200 ENC	+50				25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
OVERHAUL									
+ 753002	NO. 1 ENGINE - DISCARD - (PRE-SB24645) COMPRESSOR BOV SOLENOID REF: GENERIC NO REF	MOS HRS/MSC 7200 ENC	+50				25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
DISCARD									
+ 753003	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24434) P3 TRANSDUCER REF: GENERIC NO REF	MOS HRS/MSC 7200 ENC	+50				25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
753004	NO. 1 ENGINE - LINEAR STATOR VANE (POST SB24369) ACTUATOR 30B1960 0262 REF: EMM 75-30-04	MOS HRS/MSC O/C ENC		TSN:0 TSN:0 TSN:0			25-OCT-1993 0 0		
753005	NO. 1 ENGINE - ROTARY STATOR VANE (PRE SB24369) ACTUATOR PN SN-UNKNOWN REF: EMM 75-30-04	MOS HRS/MSC O/C ENC		TSN:0 TSN:0 TSN:0			25-OCT-1993 0 0		
+ 753012	NO. 1 ENGINE - OVERHAUL - (POST-SB24645) COMPRESSOR BOV SOLENOID REF: EMM 75-30-02	MOS HRS/MSC N/A ENC					25-OCT-1993 0 0		
DISCARD									

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 753014	NO. 1 ENGINE - DISCARD - (PRE-SB24369) ROTARY STATOR VAN ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	N/A				25-OCT-1993 0 0		
DISCARD									
+ 753024	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24369) LINER STATOR VANE ACTUATOR 30B1960 0262 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4	M 14512.4
753081	NO. 1 ENGINE - (BOV) COMPRESSOR BLEED VALVE SOLENOID 31B4197-05 ARK0332T REF: EMM 75-30-02	MOS HRS/MSC ENC	O/C		TSO:0 TSO:0 TSO:0		30-DEC-2013 8788 6043		
753082	NO. 1 ENGINE - BOV SOLENOID STRAINER ELEMENT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		(EBT)		
753083	NO. 1 ENGINE - BOV SOLENOID STRAINER ELEMENT - REPLACE PN SN-UNKNOWN REF: EMM 75-30-02	MOS HRS/MSC ENC	N/A				(EBT)		
753101	NO. 1 ENGINE - INBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 AHX013644 REF: EMM 75-30-01	MOS HRS/MSC ENC	3600	+50	TSN:0 TSN:0 TSN:0		10-FEB-2009 7262.4 4986	(10862.4) 8212.4	10912.4
REPLACE									
753102	NO. 1 ENGINE - OUTBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 AHX013599 REF: EMM 75-30-01	MOS HRS/MSC ENC	3600	+50	TSN:0 TSN:0 TSN:0		10-FEB-2009 7262.4 4986	(10862.4) 8212.4	10912.4
REPLACE									
753105	NO. 1 ENGINE - COMPRESSOR BLEED - P2.8 VALVE 31B5756-01 AHX013644 REF: EMM 75-30-01	MOS HRS/MSC ENC	3600	+50	TSN:0 TSN:0 TSN:0		10-FEB-2009 7262.4 4986	(10862.4) 8212.4	10912.4
REPLACE									

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 753111	NO. 1 ENGINE - INSPECT AND CLEAN INBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 PKG 0 AHX013644 REF: See Workcard	MOS HRS/MSC ENC	1500	+300/-300			10-FEB-2009 7262.4 4986	12-APR-2020 M (9830.9) 7180.9 M	10130.9
+ 753112	NO. 1 ENGINE - INSPECT AND CLEAN OUTBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 PKG 0 AHX013599 REF: See Workcard	MOS HRS/MSC ENC	1500	+300/-300			10-FEB-2009 7262.4 4986	12-APR-2020 M (9830.9) 7180.9 M	10130.9
+ 753115	NO. 1 ENGINE - INSPECT AND CLEAN COMPRESSOR BLEED - P2.8 VALVE 31B5756-01 PKG 0 AHX013644 REF: See Workcard	MOS HRS/MSC ENC	1500	+300/-300			10-FEB-2009 7262.4 4986	12-APR-2020 M (9830.9) 7180.9 M	10130.9
754001	NO. 1 ENGINE - PRESSURE P3 TRANSDUCER PN SN-UNKNOWN REF: EMM 75-30-03	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		25-OCT-1993 0 0		
ENGINE NO. 2 Model : PW305A Serial # PCE-305110 Part # 31B4067-02									
751001	NO. 2 ENGINE - ANTI-ICING SOLENOID VALVE 31B5108-03 AL561 REF: EMM 75-10-01	MOS HRS/MSC ENC	O/C		TSO:0 TSO:0 TSO:0		17-MAR-2001		
+ 751011	NO. 2 ENGINE - OVERHAUL - ANTI-ICING VALVE 31B5108-03 AL561 REF: EMM 75-10-01	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
OVERHAUL									
+ 753001	NO. 2 ENGINE - OVERHAUL - COMPRESSOR BLEED VALVES REF: EMM 75-30-01	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
OVERHAUL									
+ 753002	NO. 2 ENGINE - DISCARD - (PRE-SB24645) COMPRESSOR BOV SOLENOID REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
DISCARD									

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 753003	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24434) P3 TRANSDUCER	MOS					21-OCT-1992		
	REF: GENERIC NO REF	HRS/MSC ENC	7200	+50			0 0	(13296.9) 10025.2 M	13396.9
753004	NO. 2 ENGINE - LINEAR STATOR VANE (POST SB24369) ACTUATOR	MOS					21-OCT-1992		
	PN SN-UNKNOWN REF: EMM 75-30-04	HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
753005	NO. 2 ENGINE - ROTARY STATOR VANE (PRE SB24369) ACTUATOR	MOS					30-MAR-2000		
	30B1960A 0230 REF: EMM 75-30-04	HRS/MSC ENC	O/C				4321.4 2903		
+ 753012	NO. 2 ENGINE - OVERHAUL - (POST-SB24645) COMPRESSOR BOV SOLENOID	MOS					21-OCT-1992		
DISCARD	REF: EMM 75-30-02	HRS/MSC ENC	N/A				0 0		
+ 753014	NO. 2 ENGINE - DISCARD - (PRE-SB24369) ROTARY STATOR VAN ACTUATOR	MOS					21-OCT-1992		
DISCARD	30B1960A 0230 REF: GENERIC NO REF	HRS/MSC ENC	7200	+50			0 0	(13296.9) 10025.2 M	13396.9
+ 753024	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24369) LINER STATOR VANE ACTUATOR	MOS					21-OCT-1992		
	PN SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC ENC	N/A				0 0		
753081	NO. 2 ENGINE - (BOV) COMPRESSOR BLEED VALVE SOLENOID	MOS					10-OCT-2014		
	31B4197-05 ARK0700T REF: EMM 75-30-02	HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0					
753082	NO. 2 ENGINE - BOV SOLENOID STRAINER ELEMENT	MOS					(EBT)		
	PN SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0					

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
753083	NO. 2 ENGINE - BOV SOLENOID STRAINER ELEMENT - REPLACE PN SN-UNKNOWN REF: EMM 75-30-02	MOS HRS/MSC ENC	N/A				(EBT)		
753101	NO. 2 ENGINE - INBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 GF00L628 REF: EMM 75-30-01	MOS HRS/MSC ENC	3600	+50			10-OCT-2014 9645.3 6543	(13245.3) 9973.6	13295.3
REPLACE									
753102	NO. 2 ENGINE - OUTBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 GF001581 REF: EMM 75-30-01	MOS HRS/MSC ENC	3600	+50			10-OCT-2014 9645.3 6543	(13245.3) 9973.6	13295.3
REPLACE									
753105	NO. 2 ENGINE - COMPRESSOR BLEED - P2.8 VALVE 31B5756-01 19A290 REF: EMM 75-30-01	MOS HRS/MSC ENC	3600	+50			10-OCT-2014 9645.3 6543	(13245.3) 9973.6	13295.3
REPLACE									
+ 753111	NO. 2 ENGINE - INSPECT AND CLEAN INBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 GF00L628 REF: See Workcard	MOS HRS/MSC ENC	1500	+300/-300			10-OCT-2014 9645.3 6543	(11145.3) 7873.6	11445.3
+ 753112	NO. 2 ENGINE - INSPECT AND CLEAN OUTBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 GF001581 REF: See Workcard	MOS HRS/MSC ENC	1500	+300/-300			10-OCT-2014 9645.3 6543	(11145.3) 7873.6	11445.3
+ 753115	NO. 2 ENGINE - INSPECT AND CLEAN COMPRESSOR BLEED - P2.8 VALVE 31B5756-01 19A290 REF: See Workcard	MOS HRS/MSC ENC	1500	+300/-300			10-OCT-2014 9645.3 6543	(11145.3) 7873.6	11445.3
754001	NO. 2 ENGINE - PRESSURE P3 TRANSDUCER PN SN-UNKNOWN REF: EMM 75-30-03	MOS HRS/MSC ENC	O/C				21-OCT-1992 0 0		

CHAPTER 76

ENGINE CONTROLS

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E7614000 (s)	FUNCTIONAL TEST OF APR (AUTOMATIC PERFORMANCE RESERVE) SYSTEM. (REFER TO 76-14-00) PKG 3 REF: AMM 76-14-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
H7611007 (s)	VISUALLY INSPECT ALL WIRE HARNESS SHIELD OVERBRAIDS AND SHIELD TERMINATIONS FOR SECURITY AND GENERAL CONDITION. REMOVAL OF UPPER COWLING IS REQUIRED FOR THIS INSPECTION. (REFER TO 5-10-00) PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		
J7611006 (s)	VISUALLY INSPECT ALL WIRE HARNESS SHIELD OVERBRAIDS FOR SECURITY AND GENERAL CONDITION, INCLUDING THE SHIELDED HARNESSES ROUTED TO THE FADEC MAINTENANCE PANEL. PAY PARTICULAR ATTENTION TO SIGNS OF CHAFING AGAINST STRUCTURE ADJACENT TO ELECTRICAL BONDING CLAMP LOCATIONS. (PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 05-OCT-2018 6634.6 4467		

ENGINE NO. 1 Model : PW305A Serial # PCE-305018 Part # 31B4067-02

761101	NO. 1 ENGINE - FADEC, ENGINE TAILCONE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			25-OCT-1993 0 0		
761103	NO. 1 ENGINE - FADEC, ENGINE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			25-OCT-1993 0 0		
761105	NO. 1 ENGINE - CHANNEL A FADEC, ENGINE NACELLE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			25-OCT-1993 0 0		
761107	NO. 1 ENGINE - CHANNEL B FADEC, ENGINE NACELLE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			25-OCT-1993 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
76CUS1	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL(EEC) 822821-6-003 02077367 REF:	MOS HRS/MSC ENC	O/C				30-MAR-2016		
ENGINE NO. 2 Model : PW305A Serial # PCE-305110 Part # 31B4067-02									
761101	NO. 2 ENGINE - FADEC, ENGINE TAILCONE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-OCT-1992 0 0		
761103	NO. 2 ENGINE - FADEC, ENGINE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-OCT-1992 0 0		
761105	NO. 2 ENGINE - CHANNEL A FADEC, ENGINE NACELLE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-OCT-1992 0 0		
761107	NO. 2 ENGINE - CHANNEL B FADEC, ENGINE NACELLE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-OCT-1992 0 0		
76CUS1	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL(EEC) 822821-5-003 99112187 REF:	MOS HRS/MSC ENC	O/C				30-MAR-2016		
CHAPTER 77 ENGINE INDICATING									
771001	LEFT ENGINE N1 INDICATOR 6608496-001 3162L REF: AMM 77-10-01	MOS HRS/MSC AFL	O/C				18-FEB-2014 5751.22 3882		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
771002	RIGHT ENGINE N1 INDICATOR 6608496-001 5232 REF: AMM 77-10-01	MOS HRS/MSC AFL	O/C				18-FEB-2014 5751.22 3882		
771003	LEFT ENGINE N2 INDICATOR 6608508-001 5469 REF: AMM 77-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
771004	RIGHT ENGINE N2 INDICATOR 6608508-001 4856 REF: AMM 77-10-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			11-OCT-2006 1797.35 1468		
772001	LEFT ENGINE ITT INDICATOR 6608505-001 4826 REF: AMM 77-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
772002	RIGHT ENGINE ITT INDICATOR 6608505-001 5353 REF: AMM 77-20-01	MOS HRS/MSC AFL	O/C				19-MAR-2011 3580.3 2618		
773000 (s)	DOWNLOAD ENGINE DIAGNOSTIC SYSTEM FLASHCARD REF:	DAYS HRS/MSC AFL	30				12-OCT-2018 6635.2 4468		
774001	ENGINE DIAGNOSTIC UNIT 9-361-06 F288 REF: AMM 77-40-01	MOS HRS/MSC AFL	O/C				07-MAR-2018 6570.7 4417		
774001A	REPLACE ENGINE DIAGNOSTIC UNIT INTERNAL BATTERY 9-361-06 F288 REF:	MOS HRS/MSC AFL	36				26-FEB-2018 6570.7 4417	26-FEB-2021	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
774002	CONTROL AND DISPLAY (CDU) UNIT 9-362-03 C132 REF: AMM 77-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
774003	LEFT ENGINE ISOLATION INTERFACE UNIT 9-343-04 C204 REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
774004	RIGHT ENGINE ISOLATION INTERFACE UNIT 9-343-04 C224 REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
774101	SIGNAL CONDITIONING BOX 6600504-5 0346 REF: AMM 77-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
774103	LEFT ENGINE VIBRATION ACCELEROMETER 6600504-2 O346 REF: AMM 77-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
774104	RIGHT ENGINE VIBRATION ACCELEROMETER 6600504-2 0969 REF: AMM 77-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		

ENGINE NO. 1 Model : PW305A Serial # PCE-305018 Part # 31B4067-02

+ 771001	NO. 1 ENGINE - DISCARD - (PRE-SB24545 & PRE-SB24546) N1 SPEED SENSORS	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
DISCARD	REF: GENERIC NO REF								
+ 771011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24545, POST-SB24546 & PRE-SB24579) N1 SPEED SENSORS	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
	REF: EMM 77-10-01								

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 771021	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL A N2 SPEED SENSOR 30B1449 131 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M	14512.4
+ 771022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL B N2 SPEED SENSOR 30B1449 132 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M	14512.4
771027	NO. 1 ENGINE - CHANNEL A N1 SPEED SENSOR 30B6150-05 CH2618 REF: EMM 77-10-01	MOS HRS/MSC ENC	A/R		TSN:0 TSN:0 TSN:0		10-FEB-2009 7262.4 4986		
771028	NO. 1 ENGINE - CHANNEL B N1 SPEED SENSOR 30B6152-05 CH2618 REF: EMM 77-10-01	MOS HRS/MSC ENC	A/R		TSN:0 TSN:0 TSN:0		10-FEB-2009 7262.4 4986		
771040	NO. 1 ENGINE - CHANNEL A N2, TURBINE SPEED SENSOR 30B1449 131 REF: EMM 77-10-01	MOS HRS/MSC ENC	O/C				14-DEC-1994		
771041	NO. 1 ENGINE - CHANNEL B N2, TURBINE SPEED SENSOR 30B1449 132 REF: EMM 77-10-01	MOS HRS/MSC ENC	O/C				14-DEC-1994		
772010	NO. 1 ENGINE - T4.5 THERMOCOUPLE HARNESS PN SN-UNKNOWN REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		25-OCT-1993 0 0		
+ 772013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 P1/T1 SENSORS 31B5412-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M	14512.4

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
772014	NO. 1 ENGINE - PRESSURE AND TEMPERATURE SENSOR 31B5412-01 SN-UNKNOWN REF: EMM 77-20-02	MOS HRS/MSC ENC	O/C	TSO:324 TSO:230			13-JUN-1995 1111.2 810		
772015	NO. 1 ENGINE - PRESSURE AND TEMPERATURE SENSOR 31B5412-01 SN-UNKNOWN REF: EMM 77-20-02	MOS HRS/MSC ENC	O/C	TSO:324 TSO:230			13-JUN-1995 1111.2 810		
+ 772021	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL CHECK OF THE T4.5 HARNESSES AND T4.5 TERMINAL BOX PN SN-UNKNOWN REF: EMM 77-20-01	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
+ 772022	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 P1/T1 SENSORS 31B5412-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M 14512.4	
ENGINE NO. 2 Model : PW305A Serial # PCE-305110 Part # 31B4067-02									
+ 771001	NO. 2 ENGINE - DISCARD - (PRE-SB24545 & PRE-SB24546) N1 SPEED SENSORS REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M 13396.9	
	DISCARD								
+ 771011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24545, POST-SB24546 & PRE-SB24579) N1 SPEED SENSORS REF: EMM 77-10-01	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M 13396.9	
+ 771021	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL A N2 SPEED SENSOR 30B1449F CH528 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M 13396.9	
+ 771022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL B N2 SPEED SENSOR 30B1449F CH531 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M 13396.9	

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
771027	NO. 2 ENGINE - CHANNEL A N1 SPEED SENSOR 30B6150-06 CH3571 REF: EMM 77-10-01	MOS HRS/MSC ENC	3600	+50			10-OCT-2014	(13245.3) 9973.6 M	13295.3
771028	NO. 2 ENGINE - CHANNEL B N1 SPEED SENSOR 30B6150-06 CH3233 REF: EMM 77-10-01	MOS HRS/MSC ENC	3600	+50			10-OCT-2014	(13245.3) 9973.6 M	13295.3
771040	NO. 2 ENGINE - CHANNEL A N2, TURBINE SPEED SENSOR 30B1449F CH528 REF: EMM 77-10-01	MOS HRS/MSC ENC	O/C				21-OCT-1992 0 0		
771041	NO. 2 ENGINE - CHANNEL B N2, TURBINE SPEED SENSOR 30B1449F CH531 REF: EMM 77-10-01	MOS HRS/MSC ENC	O/C				21-OCT-1992 0 0		
772010	NO. 2 ENGINE - T4.5 THERMOCOUPLE HARNESS 30B2749-02 SN-UNKNOWN REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C				26-AUG-2003		
+ 772013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 P1/T1 SENSORS 31B3876-01 WE00078 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
772014	NO. 2 ENGINE - PRESSURE AND TEMPERATURE SENSOR 31B3876-01 WE00079 REF: EMM 77-20-02	MOS HRS/MSC ENC	O/C				18-DEC-1992		
772015	NO. 2 ENGINE - PRESSURE AND TEMPERATURE SENSOR 31B3876-01 WE00078 REF: EMM 77-20-02	MOS HRS/MSC ENC	O/C				18-DEC-1992		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 772021	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL CHECK OF THE T4.5 HARNESSSES AND T4.5 TERMINAL BOX 30B2749-02 SN-UNKNOWN REF: EMM 77-20-01	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
+ 772022	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 P1/T1 SENSORS 31B3876-01 WE00079 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
CHAPTER 78 EXHAUST									
78-CUS-01	R/H OUTBOARD STOW SWITCH THRUST REVERSER 602HE8-11 1423 REF:	MOS HRS/MSC AFL	O/C		TSN:35 TSN:0 TSN:0		27-JAN-2014 5688.98 3844		
780001	LEFT THRUST REVERSER 282-0052-519 638 REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		10-MAY-2002 0 0		
780002	RIGHT THRUST REVERSER 282-0052-517 639 REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		10-MAY-2002 0 0		
783005	LEFT THRUST REVERSER HYDRAULIC CONTROL UNIT 282D0007-507 0530 REF: AMM 78-30-03	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0		26-FEB-2004 463 389		
783006	RIGHT THRUST REVERSER HYDRAULIC CONTROL UNIT 282D0007-505 0591 REF: AMM 78-30-03	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		10-MAY-2002 0 0		
783009	THRUST REVERSER INTERFACE BOX 6018003-001 BAS002432-01A REF: AMM 78-30-07	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		01-AUG-2005 1203.65 997		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783025	LEFT ENGINE THRUST REVERSER SWITCH CABLE 38HE13-CA 1425 REF: AMM 78-30-25	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-JAN-2014 5688.98 3844		
783106	LEFT INBOARD THRUST REVERSER ACTUATOR 282D0006-501 1137R REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
783107	RIGHT INBOARD THRUST REVERSER ACTUATOR 282D0006-501 1138R. REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
783108	RIGHT OUTBOARD THRUST REVERSER ACTUATOR 282D0006-501 1133R REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
783116	RIGHT UPPER SECONDARY LOCK ACTUATOR 266D0486-507 1353 REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
783117	LEFT LOWER SECONDARY LOCK ACTUATOR 266D0486-507 1357 REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
783118	RIGHT LOWER SECONDARY LOCK ACTUATOR 266D0486-507 1348 REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
E7830038 (s)	DETAILED INSPECTION THRUST REVERSERS FORWARD AND AFT GUIDE ROD MOUNTING POINTS ON AFT SUPPORT ASSEMBLY. (REFER TO 78-30-00.) PKG 15 REF: AMM 78-30-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			05-OCT-2018 6634.6 4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
M7830084 (s)	INSPECT THRUST REVERSER SECONDARY LATCH - LUBRICATE LATCH SWITCH PLUNGERS, ROLLER ASSEMBLY, AND ACTUATOR PINS. (REFER TO 12-21-04)						PKG		
	PKG 3	MOS	12	+14d/-14d			05-OCT-2018		
	REF: AMM 12-21-04	HRS/MSC	300	+25/-25			6634.6		
		AFL					4467		
P7830022 (s)	FUNCTIONAL TEST OF THRUST REVERSER HYDRAULIC CONTROL VALVE ASSEMBLY CHECK VALVES. (REFER TO 78-30-03.)						PKG		
	PKG 27	MOS	144	+14d/-14d			02-SEP-2014		
	REF: AMM 78-30-03	HRS/MSC	6000	+25/-25			5979.4		
		AFL					4026		
T7830014 (s)	VISUAL INSPECTION OF THRUST REVERSER ACTUATING MECHANISM LINK BEARINGS AND DOOR BUSHINGS, CARRIAGE GUIDE RODS, CARRIAGE ASSEMBLY, AND LINKAGE PIVOT POINTS FOR FREEDOM OF ROTATION. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC	600	+25/-25			6634.6		
		AFL					4467		
T7830016 (s)	VISUAL INSPECTION OF THRUST REVERSER ACTUATOR FOR HYDRAULIC LEAKS, DAMAGED PUSHROD, DAMAGED FLEXIBLE HOSES, AND SECURITY OF INSTALLATION. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC	600	+25/-25			6634.6		
		AFL					4467		
T7830018 (s)	VISUAL INSPECTION OF HYDRAULIC CONTROL UNITS, PRESSURE SWITCH, CHECK VALVES, AND HYDRAULIC LINES FOR LEAKAGE, CLEANLINESS, SECURITY OF INSTALLATION, AND CONDITION OF ECLECTRICAL COMPONENTS. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC	600	+25/-25			6634.6		
		AFL					4467		
T7830020 (s)	VISUAL INSPECTION OF STOW AND DEPLOY SWITCHES FOR SECURITY OF INSTALLATION AND CONDITION OF ELECTRICAL COMPONENTS. VISUALLY INSPECT SHIELDED ELECTRICAL THRUST REVERSER HARNESS FOR CONDITION. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC	600	+25/-25			6634.6		
		AFL					4467		

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019
Owner/Operator: RJ AIRCRAFT LEASING
Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T7830026 (s)	VISUAL INSPECTION OF THRUST REVERSER DRIVER LINKS(EIGHT PER AIRCRAFT) AND DRIVER LINK ATTACH POINTS (24 PER AIRCRAFT.) INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
T7830028 (s)	VISUAL INSPECTION OF THRUST REVERSER OVERCENTER LINK (EIGHT PER AIRCRAFT) AND OVERCENTER LINK ATTACH POINTS (16 PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATIONS. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
T7830030 (s)	VISUAL INSPECTION OF THRUST REVERSER CARRIAGE ASSEMBLY (FOUR PER AIRCRAFT) AND CARRIAGE LINK ATTACH POINTS (TWO LOCATIONS PER CARRIAGE, 16 LUGS PER AIRCRAFT). INSPECT FOR CRACKS AND EXCESSIVE PLAY AT ATTACH POINT FASTENER LOCATI						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
T7830032 (s)	VISUAL INSPECTION OF THRUST REVERSER DOOR ATTACH LUGS (EIGHT LOCATIONS PER DOOR, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF DOORS. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
T7830034 (s)	VISUAL INSPECTION OF THRUST REVERSER SUPPORT BEAM ATTACH LUGS (FOUR LOCATIONS PER CASTING, 32 LUGS PER AIRCRAFT). INSPECT FOR CRACKS IN LUGS AND EXCESSIVE PLAY OF IDLER LINKS AND DRIVER LINKS. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		
T7830039 (s)	VISUAL INSPECTION OF FORWARD AND AFT GUIDE ROD MOUNTING POINTS ON AFT SUPPORT ASSEMBLY. (REFER TO 5-10-00)						PKG		
	PKG 9	MOS	24	+14d/-14d			05-OCT-2018		
		HRS/MSC	600	+25/-25			6634.6		
	REF: GENERIC NO REF	AFL					4467		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T7830085 (s)	FUNCTIONAL TEST ** OF THE THRUST REVERSER WITH WHEEL SPEED DETECT INTERFACE. (REFER TO 78-30-00.) (AWL**)						PKG		
	PKG 15	MOS	48	+14d/-14d			05-OCT-2018		
	REF: AMM 78-30-00	HRS/MSC AFL	1200	+25/-25			6634.6 4467		
U7830010A (s)	INSPECT NO. 1 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION						PKG		
	PKG 29	MOS					22-MAR-2016		
	REF:	HRS/MSC AFL	3600	+50			6382.8 4275		
U7830010B (s)	INSPECT NO. 2 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION						PKG		
	PKG 30	MOS					22-MAR-2016		
	REF:	HRS/MSC AFL	3600	+50			6382.8 4275		
U7830012A (s)	INSPECT NO. 1 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE						PKG		
	PKG 29	MOS					22-MAR-2016		
	REF:	HRS/MSC AFL	3600	+50			6382.8 4275		
U7830012B (s)	INSPECT NO. 2 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE						PKG		
	PKG 30	MOS					22-MAR-2016		
	REF: GENERIC NO REF	HRS/MSC AFL	3600	+50			6382.8 4275		

CHAPTER 79 OIL

793001	LEFT ENGINE OIL PRESSURE/TEMPERATURE INDICATOR								
	6608499-001	MOS			TSN:0		10-MAY-2002		
	5425	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 79-30-01	AFL			TSN:0		0		
793002	RIGHT ENGINE OIL PRESSURE/TEMPERATURE INDICATOR								
	6608499-001	MOS			TSN:0		10-MAY-2002		
	5418	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 79-30-01	AFL			TSN:0		0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793003	LEFT ENGINE OIL PRESSURE TRANSDUCER 7600019-1 6479-10A-148 REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
793004	RIGHT ENGINE OIL PRESSURE TRANSDUCER 7600019-1 6479-10A-126 REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
793010	LEFT ENGINE OIL TEMPERATURE BULB MS28034-3 E6260 REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
793011	RIGHT ENGINE OIL TEMPERATURE BULB MS28034-3 F6996 REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-MAY-2002 0 0		
ENGINE NO. 1 Model : PW305A Serial # PCE-305018 Part # 31B4067-02									
05-P&W-790001	NO. 1 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT	MOS HRS/MSC ENC	12 1200	+25/-25			03-JUN-2019 9437.9 6467	03-JUN-2020 (10637.9) 7987.9	10662.9
05-P&W-790002	NO. 1 ENGINE - PERFORM ENGINE OIL CHANGE	MOS HRS/MSC ENC	12 600	+50/-50			03-JUN-2019 9437.9 6467	03-JUN-2020 (10037.9) 7387.9	10087.9
792001	NO. 1 ENGINE - OIL PUMP 31B3608-01 4Y859 REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C				05-AUG-1996 2587.4 1741		
792002	NO. 1 ENGINE - FUEL/OIL HEAT EXCHANGER 31B5790-02 1091 REF: EMM 79-20-02	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			10-FEB-2009 7262.4 4986		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792005	NO. 1 ENGINE - OIL PRESSURE DIFFERENTIAL SWITCH 30B1948 0050 REF: EMM 79-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			25-OCT-1993 0 0		
792010	NO. 1 ENGINE - ENGINE OIL PRESSURE LIGHT SWITCH 30B1506 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				21-APR-2009 7472.3 5130		
+ 792011	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL FILTER BYPASS SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M	14512.4
+ 792012	NO. 1 ENGINE - VISUALLY INSPECT THE FUEL/OIL HEAT EXCHANGER 31B5790-02 1091 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M	14512.4
792020	NO. 1 ENGINE - OIL PUMP HOUSING PN SN-UNKNOWN REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			25-OCT-1993 0 0		
792035	NO. 1 ENGINE - OIL FILTER BYPASS SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			(EBT)		
+ 793001	NO. 1 ENGINE - DISCARD - CHIP DETECTOR REF: EMM 79-30-01	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M	14512.4
+ 793002	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LOW OIL PRESSURE SWITCH REF: EMM 79-30-02	MOS HRS/MSC ENC	7200	+50			25-OCT-1993 0 0	(14462.4) 11812.4 M	14512.4

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 793003	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL TANK FILLER CAP	MOS					25-OCT-1993		
	REF: EMM 79-30-03	HRS/MSC ENC	7200	+50			0 0	(14462.4)	11812.4 M 14512.4
793005	NO. 1 ENGINE - CHIP DETECTOR	MOS					14-NOV-1998		
REPLACE	PN SN-UNKNOWN REF: EMM 79-30-01	HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		3015.1 2120		
+ 793013	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL PRESSURE DIFFERENTIAL INDICATOR (POP-UP)	MOS					25-OCT-1993		
	PN SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC ENC	7200	+50			0 0	(14462.4)	11812.4 M 14512.4
793030	NO. 1 ENGINE - OIL PRESSURE DIFFERENTIAL INDICATOR	MOS					(EBT)		
	PN SN-UNKNOWN REF: EMM 79-30-03	HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0				
ENGINE NO. 2 Model : PW305A Serial # PCE-305110 Part # 31B4067-02									
05-P&W-790001	NO. 2 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT	MOS	12				03-JUN-2019	03-JUN-2020	
	REF: See Workcard	HRS/MSC ENC	1200	+25/-25			10059.6 6810	(11259.6)	7987.9 11284.6
05-P&W-790002	NO. 2 ENGINE - PERFORM ENGINE OIL CHANGE	MOS	12				03-JUN-2019	03-JUN-2020	
	REF: EMM 72-00-00	HRS/MSC ENC	600	+50/-50			10059.6 6810	(10659.6)	7387.9 10709.6
792001	NO. 2 ENGINE - OIL PUMP	MOS					26-AUG-2003		
	30B2767-01 PWV030243P3 REF: EMM 79-20-05	HRS/MSC ENC	O/C		TSO:0 TSO:0 TSO:0		6096.9 4139		
792002	NO. 2 ENGINE - FUEL/OIL HEAT EXCHANGER	MOS					10-OCT-2014		
	31B5790-02 1526 REF: EMM 79-20-02	HRS/MSC ENC	O/C				9645.3 6543		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792005	NO. 2 ENGINE - OIL PRESSURE DIFFERENTIAL SWITCH TD331UL057 0147 REF: EMM 79-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-OCT-1992 0 0		
792010	NO. 2 ENGINE - ENGINE OIL PRESSURE LIGHT SWITCH 30B1506 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				21-APR-2009 8002.5 5411		
+ 792011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL FILTER BYPASS SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
+ 792012	NO. 2 ENGINE - VISUALLY INSPECT THE FUEL/OIL HEAT EXCHANGER 31B5790-02 1526 REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
792020	NO. 2 ENGINE - OIL PUMP HOUSING 30B2750-01 SN-UNKNOWN REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			21-OCT-1992 0 0		
792035	NO. 2 ENGINE - OIL FILTER BYPASS SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			(EBT)		
+ 793001	NO. 2 ENGINE - DISCARD - CHIP DETECTOR REF: EMM 79-30-01	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9
+ 793002	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LOW OIL PRESSURE SWITCH REF: EMM 79-30-02	MOS HRS/MSC ENC	7200	+50			21-OCT-1992 0 0	(13296.9) 10025.2 M	13396.9

Status Report

LEARJET 60 S/N 60 255 (N160RJ): 6787.9 HRS, 4531 AFL as of 03-Jun-2019

Owner/Operator: RJ AIRCRAFT LEASING

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 793003	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL TANK FILLER CAP	MOS					21-OCT-1992		
	REF: EMM 79-30-03	HRS/MSC ENC	7200	+50			0	(13296.9)	10025.2 M 13396.9
793005	NO. 2 ENGINE - CHIP DETECTOR	MOS					26-AUG-2003		
	30B3756-02	HRS/MSC	O/C	TSN:0					
REPLACE	SN-UNKNOWN	ENC		TSN:0					
	REF: EMM 79-30-01			TSN:0					
+ 793013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL PRESSURE DIFFERENTIAL INDICATOR (POP-UP)	MOS					21-OCT-1992		
	PN	HRS/MSC	7200	+50			0	(13296.9)	10025.2 M 13396.9
	SN-UNKNOWN	ENC					0		
	REF: GENERIC NO REF								
793030	NO. 2 ENGINE - OIL PRESSURE DIFFERENTIAL INDICATOR	MOS					(EBT)		
	PN	HRS/MSC	O/C	TSN:0					
	SN-UNKNOWN	ENC		TSN:0					
	REF: EMM 79-30-03			TSN:0					